inverter frequency (800Hz at 1.2V)

PWM frequency (needs to be determined)

