# CLARKSVILLE ELEMENTARY SCHOOL EXTERIOR DOOR REPLACEMENT

12041 MARYLAND ROUTE 108 CLARKSVILLE, MD 21029

# ARCHITECT

SCHAMU MACHOWSKI + PATTERSON ARCHITECTS, INC.


1100 CATHEDRAL STREET

BALTIMORE, MD 21201


TEL 410-685-3582

FAX 410-625-4790

### VICINITY MAP




## LOCATION MAP



### DRAWING LIST

A0.1 GENERAL INFORMATION
A1.1 PART FLOOR PLAN - NEW WORK
A2.1 DOOR SCHEDULE & TYPES, DETAILS



F. 1982		
SCHAMU MACHOWSKI + PATTERSON ARCHITECTS,		ECTS, INC
SM+P	1100 CATHEDRAL STREET, BALTIMORE, 1	MD 21201
ARCHITECTS	TEL 410-685-3582 WWW.SMP-ARCHITE	CTS.COM
SULTANTS		

approved by me, and that I am a duly licensed architect under the laws of the State of Maryland. License No. 3715R, expiration date: 05.02.2018."

ROJECT

CLARKSVILLE ELEMENTARY SCHOOL
EXTERIOR DOOR REPLACEMENT

RAWING TITLE

COVER SHEET

DRAWN
PROJECT # 11001.02

CHECKED
CHECKED
DRAWING #
ZSS/REM
REVIEWED
REM
DATE

Professional Certification: "I certify that these documents were prepared or

LE ES EXTERIOR DOOR REPLACEMENT - 100% CD SUBMISSION

