RN0189

MIV_RV32IMA_L1_AHB v2.3 Release Notes





a MICROCHIP company

Microsemi Headquarters One Enterprise, Aliso Viejo,

CA 92656 USA Within the USA: +1 (800) 713-4113 Outside the USA: +1 (949) 380-6100 Sales: +1 (949) 380-6136 Fax: +1 (949) 215-4996

Email: sales.support@microsemi.com www.microsemi.com

©2018 Microsemi, a wholly owned subsidiary of Microchip Technology Inc. All rights reserved. Microsemi and the Microsemi logo are registered trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

About Microsemi

Microsemi, a wholly owned subsidiary of Microchip Technology Inc. (Nasdaq: MCHP), offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions, security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Learn more at www.microsemi.com.



1 Revision History

The revision history describes the changes that were implemented in the document. The changes are listed by revision, starting with the most current publication.

1.1 **Revision 3.0**

Update for MIV_RV32IMA_L1_AHB v2.3. Sections added to document for Resolved Issues and Discontinued Features. This release includes an asynchronous reset fix and changes to ECC configuration.

1.2 Revision 2.0

Updated for MIV_RV32IMA_L1_AHB v2.1. Added cache with ECC, Debug reset, and external debug halt features.

1.3 **Revision 1.0**

Revision 1.0 was the first publication of this document. Created for MIV_RV32IMA_L1_AHB v2.0.



Contents

1	Revisi 1.1 1.2 1.3	ion History Revision 3.0 Revision 2.0 Revision 1.0	. 3
2	MIV_RV32IMA_L1_AHB v2.3 Release Notes		. 5
	2.1	Overview	. 5
	2.2	Features	. 5
	2.3	Delivery Types	. 5
	2.4	Supported Families	
	2.5	Supported Tool Flows	. 5
	2.6	Installation Instructions	. 5
	2.7	Documentation	. 6
	2.8	Supported Test Environments	. 6
	2.9	Resolved Issues in v2.3 Release	. 6
	2.10	Discontinued Features and Devices	. 6
	2.11	Known Limitations and Workarounds	. 6



3 MIV_RV32IMA_L1_AHB v2.3 Release Notes

3.1 Overview

These release notes accompany the production release of MIV_RV32IMA_L1_AHB v2.3. This document provides details about the features, enhancements, system requirements, supported families, implementations, known issues, and workarounds.

3.2 Features

- Designed for FPGA soft-core implementation.
- Integrated 8Kbytes instructions cache and 8Kbytes data cache.
- A Platform-Level Interrupt Controller (PLIC) can support up to 31 programmable interrupts with a single priority level.
- Supports the RISC-V standard RV32IMA ISA.
- On-Chip debug unit with a JTAG interface.
- Two external AHB interfaces for IO and memory.
- External HALT signal can halt processor execution during a debug session.
- Support for Error-Correcting Code (ECC) memories on RTG4 and PolarFire.

3.3 Delivery Types

MIV RV-32IMA L1 AHB does not require license. Complete RTL source code is provided for the core.

3.4 Supported Families

- PolarFire[®]
- RTG4TM
- IGLOO[®]2
- SmartFusion[®]2

3.5 Supported Tool Flows

MIV_RV-32IMA_L1_AHB requires Libero[®] System-on-Chip (SoC) software v11.8 or later. For RTG4 designs with ECC Libero System-on-Chip (SoC) software v11.8 SP4 or later is recommended.

3.6 Installation Instructions

The MIV_RV-32IMA_L1_AHB CPZ must be installed into Libero software. This is done automatically through the Catalog update function in Libero, or the CPZ file can be manually added using the **Add Core** catalog feature. Once the CPZ file is installed in Libero, the core can be configured, generated, and instantiated within SmartDesign for inclusion in the Libero project.

Refer to the *Libero SoC Online Help* for further instructions on core installation, licensing, and general use.



3.7 Documentation

This release contains a copy of the *MIV_RV-32IMA_L1_AHB Handbook*. The handbook, describes the core functionality and gives step-by-step instructions on how to simulate, synthesize, and place-androute this core, and also implementation suggestions. Refer to the *Libero SoC Online Help* for instructions on obtaining IP documentation.

For updates and additional information about the software, devices, and hardware, visit the Intellectual Property pages on the Microsemi SoC Products Group website: visit:

http://www.microsemi.com/products/fpga-soc/design-resources/ip-cores.

3.8 Supported Test Environments

No testbench is provided with MIV_RV32IMA_L1_AHB.

The MIV_RV32IMA_L1_AHB RTL can be used to simulate the processor executing a program using a standard Libero generated HDL testbench.

3.9 Resolved Issues in v2.3 Release

- Asynchronous reset issue when using sNVM resolved, SAR 100766.
- CPU uSRAM replaced by registers for ECC configuration.

3.10 Discontinued Features and Devices

There are no discontinued features or devices.

3.11 Known Limitations and Workarounds

There are no known limitations and workarounds for MIV RV-32IMA L1 AHB.