# RN0081 Release Notes CoreAXItoAHBL v3.6





a MICROCHIP company

#### Microsemi Headquarters

One Enterprise, Aliso Viejo, CA 92656 USA Within the USA: +1 (800) 713-4113 Outside the USA: +1 (949) 380-6100 Sales: +1 (949) 380-6136 Fax: +1 (949) 215-4996

Email: sales.support@microsemi.com www.microsemi.com

©2021 Microsemi, a wholly owned subsidiary of Microchip Technology Inc. All rights reserved. Microsemi and the Microsemi logo are registered trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Microsemi makes no warranty, representation, or guarantee regarding the information contained herein or the suitability of its products and services for any particular purpose, nor does Microsemi assume any liability whatsoever arising out of the application or use of any product or circuit. The products sold hereunder and any other products sold by Microsemi have been subject to limited testing and should not be used in conjunction with mission-critical equipment or applications. Any performance specifications are believed to be reliable but are not verified, and Buyer must conduct and complete all performance and other testing of the products, alone and together with, or installed in, any end-products. Buyer shall not rely on any data and performance specifications or parameters provided by Microsemi. It is the Buyer's responsibility to independently determine suitability of any products and to test and verify the same. The information provided by Microsemi hereunder is provided "as is, where is" and with all faults, and the entire risk associated with such information is entirely with the Buyer. Microsemi does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other IP rights, whether with regard to such information itself or anything described by such information. Information provided in this document is proprietary to Microsemi, and Microsemi reserves the right to make any changes to the information in this document or to any products and services at any time without notice.

#### **About Microsemi**

Microsemi, a wholly owned subsidiary of Microchip Technology Inc. (Nasdaq: MCHP), offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions, security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Learn more at www.microsemi.com.



# 1 Revision History

The revision history describes the changes that were implemented in the document. The changes are listed by revision, starting with the most current publication.

# 1.1 Revision 10.0

Updated changes related to CoreAXItoAHBL v3.6.

### 1.2 **Revision 9.0**

Updated changes related to CoreAXItoAHBL v3.5.

### 1.3 **Revision 8.0**

Updated changes related to CoreAXItoAHBL v3.4.

# 1.4 **Revision 7.0**

Updated changes related to CoreAXItoAHBL v3.3.

#### 1.5 **Revision 6.0**

Updated changes related to CoreAXItoAHBL v3.2.

### 1.6 **Revision 5.0**

Updated changes related to CoreAXItoAHBL v3.1.

### 1.7 **Revision 4.0**

Updated changes related to CoreAXItoAHBL v3.0.

### 1.8 **Revision 3.0**

Updated changes related to CoreAXItoAHBL v2.2.

### 1.9 **Revision 2.0**

Updated changes related to CoreAXItoAHBL v2.1.

# 1.10 **Revision 1.0**

The first publication of this document. Created for CoreAXItoAHBL v2.0.



# **Contents**

| 1 | Revisi | on History                          | 3   |
|---|--------|-------------------------------------|-----|
|   | 1.1    | Revision 10.0                       |     |
|   | 1.2    | Revision 9.0                        |     |
|   | 1.3    | Revision 8.0                        | . 3 |
|   | 1.4    | Revision 7.0                        | . 3 |
|   | 1.5    | Revision 6.0                        | . 3 |
|   | 1.6    | Revision 5.0                        | . 3 |
|   | 1.7    | Revision 4.0                        | . 3 |
|   | 1.8    | Revision 3.0                        | . 3 |
|   | 1.9    | Revision 2.0                        | . 3 |
|   | 1.10   | Revision 1.0                        | . 3 |
| 2 | CoreA  | XItoAHBL v3.6                       | 5   |
|   | 2.1    | Overview                            |     |
|   | 2.2    | Features                            |     |
|   | 2.3    | Delivery Types                      |     |
|   | 2.4    | Supported Families                  |     |
|   | 2.5    | Supported Tool Flows                | . 5 |
|   | 2.6    | Installation Instructions           | . 5 |
|   | 2.7    | Documentation                       | . 6 |
|   | 2.8    | Supported Test Environments         | . 6 |
|   | 2.9    | Resolved Issues in the v3.6 Release | . 6 |
|   | 2.10   | Resolved Issues in the v3.5 Release | . 6 |
|   | 2.11   | Resolved Issues in the v3.4 Release | . 6 |
|   | 2.12   | Resolved Issues in the v3.3 Release | . 6 |
|   | 2.13   | Resolved Issues in the v3.2 Release | . 7 |
|   | 2.14   | Resolved Issues in the v3.1 Release | . 7 |
|   | 2.15   | Resolved Issues in the v3.0 Release | . 7 |
|   | 2.16   | Resolved Issues in the v2.2 Release | . 7 |
|   | 2.17   | Resolved Issues in the v2.1 Release | . 7 |
|   | 2.18   | Discontinued Features and Devices   | . 7 |
|   | 2.19   | Known Limitations and Workarounds   | . 7 |



# 2 CoreAXItoAHBL v3.6

#### 2.1 Overview

These release notes accompany the production release of CoreAXItoAHBL. This document provides details about the features, enhancements, system requirements, supported families, implementations, and known issues and workarounds.

### 2.2 Features

- Provides an interface (bridge) between the Advanced eXtensible Interface (AXI) domain and Advanced High-performance Bus Lite (AHB-Lite) domain
- Supports both AXI3 and AXI4 protocol
- Makes alternate AXI write and AXI read transactions possible
- Supports AXI data bus width of 32-bits, with transfer size of 32/16/8 bit
- Supports AXI data bus width of 64-bits, with transfer size of 64/32/16/8 bit
- Maximum number of AXI beats or transfers of 256 when AXI4 interface is selected
- Maximum number of AXI beats or transfers of 16 when AXI3 interface is selected
- Supports unaligned AXI write / read transactions
- Permits the AXI and AHBL clocks to be derived from asynchronous sources
- Supports narrow transfers for the last transfer in AXI write transactions using write strobes
- Provides ERROR/OKAY response for every AXI master transaction
- Supports AHB data bus width of 32-bits
- · Prevents sequential AHBL transfers from crossing 1 KB boundaries

# 2.3 Delivery Types

CoreAXItoAHBL is freely distributed with Microsemi Libero<sup>®</sup> System-on-Chip (SoC). Complete HDL source code is provided for the core and testbenches.

# 2.4 Supported Families

CoreAXItoAHBL is a generic core and supports all the device families.

# 2.5 Supported Tool Flows

CoreAXItoAHBL requires Libero v11.0 or later.

**Note:** CoreAXItoAHBL is compatible with Libero SoC and Libero SoC PolarFire. Unless specified otherwise, this document uses the name Libero to identify Libero SoC and Libero SoC PolarFire.

### 2.6 Installation Instructions

The CoreAXItoAHBL CPZ must be installed into Libero software. This is done automatically through the Catalog update function in Libero, or the CPZ file can be manually added using the **Add Core** catalog feature. Once the CPZ file is installed in Libero, the core can be configured, generated, and instantiated within SmartDesign for inclusion in the Libero project. For more information, see the *Knowledge Based article*.

To know how to create SmartDesign project using the IP cores, refer to the SmartDesign User guide.



### 2.7 Documentation

This release contains a copy of the *CoreAXItoAHBL Handbook*. The handbook, describes the core functionality and gives step-by-step instructions on how to simulate, synthesize, and place-and-route this core, and also implementation suggestions. Refer to the *Libero SoC Online Help* for instructions on obtaining IP documentation.

For updates and additional information about the software, devices, and hardware, visit the Intellectual Property pages on the Microsemi SoC Products Group website: visit:

http://www.microsemi.com/products/fpga-soc/design-resources/ip-cores.

# 2.8 Supported Test Environments

The following test environments are supported:

- VHDL user testbench
- · Verilog user testbench

## 2.9 Resolved Issues in the v3.6 Release

#### Table 1 • Resolved Issues in the v3.6 Release

| SAR Number | Changes   |
|------------|---|
| 115706     | Added AXI4 support.   |
|            | Provided option to select between AHB Mirror Slave BIF or AHB Master BIF when core is instantiated in Libero SmartDesign. |
| 115867     | Added memory map support.   |

# 2.10 Resolved Issues in the v3.5 Release

#### Table 2 • Resolved Issues in the v3.5 Release

| SAR Number | Changes                                     |
|------------|---|
| 108962     | Added support for 32bit AXI data interface. |

### 2.11 Resolved Issues in the v3.4 Release

#### Table 3 • Resolved Issues in the v3.4 Release

| SAR Number | Changes   |
|------------|---|
|            | Fixed the single read transaction failure issue, when AXI and AHB clocks are asynchronous and ACLK:HCLK clock ratio is more than 2:1. |

## 2.12 Resolved Issues in the v3.3 Release

#### Table 4 • Resolved Issues in the v3.3 Release

| SAR Number | Changes  |
|------------|--|
| 96561      | Enhance core to facilitate the use of CoreAXItoAHBL with MiV RV32 AXI cores. |
| 99662      | Repackage core as a generic core.  |



### 2.13 Resolved Issues in the v3.2 Release

#### Table 5 • Resolved Issues in the v3.2 Release

| SAR Number | Changes   |
|------------|---|
| 90363      | CoreAXItoAHBL need support for 16-bit and 8-bit AXI data transfer size. |

# 2.14 Resolved Issues in the v3.1 Release

#### Table 6 • Resolved Issues in the v3.1 Release

| SAR Number | Changes   |
|------------|---|
| 82615      | CoreAXItoAHBL need support for 32-bit AXI data transfer size. |

### 2.15 Resolved Issues in the v3.0 Release

#### Table 7 • Resolved Issues in the v3.0 Release

| SAR Number | Changes   |
|------------|---|
| 69879      | Complete re-design of the core. Unaligned address support added as part of the re-design. |

#### 2.16 Resolved Issues in the v2.2 Release

#### Table 8 • Resolved Issues in the v2.2 Release

| SAR Number | Changes                         |
|------------|---------------------------------|
| 58944      | The core mishandles AXI bursts. |

# 2.17 Resolved Issues in the v2.1 Release

#### Table 9 • Resolved Issues in the v2.1 Release

| SAR Number | Changes                                |
|------------|--|
| 57249      | RValid generation depending on RReady. |

# 2.18 Discontinued Features and Devices

There are no discontinued features for this release.

# 2.19 Known Limitations and Workarounds

This release does not support the following:

- Narrow transfers using write strobes are not permitted for fixed address, AXI write transactions. For example, WSTRB = 8'h7F (for 64-bit transfers), WSTRB = 8'h07 (for 32-bit transfers), and WSTRB = 8'h01 (for 16-bit transfers).
- Sparse assertion of the write strobes (holes in the write strobes) are not supported by the core. For example, WSTRB = 8'h5F (for 64-bit transfers) and WSTRB = 8'h05 (for 32-bit transfers).