Engineering Notes No. 4.1

INFORMATION

NAME: Davian Rosario-Ortiz

DATE: 10/29/2024 - 11/04/2024

Sprint: 4

JIRA BACKLOG

Responsible for:

- Complete Section 4 of SRS document
- Complete Section 5 of SRS document

Contributed to:

- Complete SDD following the same breakdown as the SRS
- Determine Goals with Acclivis
- Determine meeting times and frequency with Acclivis

RESOURCES & DOCUMENTS CONTRIBUTED TO

Table 1 - Contributions

Date	Resource/Docu	Location	Contribution Description
10/29/202	SRS Document	One Drive	Completed Sections 4, 5, and contributed to Section 8

COMPONENTS TESTED

Table 2 - Testing

Date Tested	Component	Result	Comments
10/29/202	PolyVerif on Ubuntu 20.02	Partially Working	Reverted to an older OS after PolyVerif stopped functioning.
10/30/202	Docker & Nvidia Drivers	Errors resolved	Reinstalled drivers with assistance from Jackson Baker
10/31/202	Python Package compatibility	Ongoing issues	Investigating version mismatches in sub release packages.

PROBLEMS SOLVED

Table 3 - Solutions

Date	Problem	Solution & Notes
10/29/202	PolyVerif stopped functioning	Reverted to Ubuntu 20.02 and reinstalled Docker and Nvidia drivers
10/30/202	Errors with Pip installation of modules	Used -no-cache-dir flag to address installation issues

PROBLEMS TO ADDRESS NEXT

Table 4 - Future Problems

Problem	Description
Need to resolve	Investigate continued issues with
software issues.	PolyVerif and LGSVL errors.
Need to resolve	Confirm Pyhton sub release
package-related	compatibility to resolve package-
issues.	related issues.
Need to finish	Finalize environment creation guide and
environment creation	complete a basic simulation with
guides.	logging capabilities.

MEETING NARRATIVE NOTES:

Table 5 - Meeting 1

10/29/2024 Meeting Type: I	n-Class			
Met with Product Owner(s): Y				
Problems Brought Up:				
Problem	Proposed Solution			
Need to work on SRS.	Continued work on SRS, I personally worked on Sections 4 & 5, and contributed to Section 8.			
Other Items Updated on:				
N/A				
Additional Notes:				
Nothing else to note.				

Table 6 - Meeting 2

10/31/2024 Meeting Type: I	n-Class		
Met with Product Owner(s): Y			
Problems Brought Up:			
Problem	Proposed Solution		
Continued PolyVerif issues, and LGSVL issues	Investigating if computer hardware or software configuration is causing errors.		
Other Items Updated on:			
N/A			
Additional Notes:			
Progress made on SRS and environment creation, though technical setbacks with PolyVerif and LGSVL are ongoing.			

NOTES:

Nothing else to note.