For non-CT images, Adjust the parameters!

- •Default parameters are set for CT. IBEX CT number=Hounsfield Unit+1000.
- •For non-CT modality images, users must adjust the parameters to get the meaningful result. See Page2 for example.
- •After adjusting parameters, test to see if parameters are reasonable. See page3 for example.
- •For changing the parameter permanently, modify the file *.INI.

For features, INI file is at

\(RootPath\IBEX_mcr\Work\MyProgram\Matlab\ImageFeatureOutcomeAnalysis\


FeatureAlgorithm\Category\(Feature)\(Feature).INI

For preprocess, INI file is at

\(RootPath\IBEX_mcr\Work\MyProgram\Matlab\ImageFeatureOutcomeAnalysis\

FeatureAlgorithm\Preprocess\(Preprocess).INI

Example how to adjust the parameters



Parameters

Para. for Catogory IntensityHistogram

Step 2: Features Category: **Example how to test the parameters** Name Para. **-** 0 Test IntensityHistogram Features: Name Para. InterQuartileRange Test Kurtosis Test MeanAbsoluteDeviation Test MedianAbsoluteDeviation Test Percentile Test PercentileArea Test Quantile Test Range Test Skewness Test Histogram (Probability VS Value) Histogram (Probability VS Value) 0.35 0.9 0.3 0.8 **Histogram from PET parameters Histogram from CT parameters** 0.25 0.7 0.6 0.2 0.5 0.15 0.4 0.3 0.1 0.2 0.05 0.1 4500 500 1000 1500 2000 2500 3000 3500 4000 20 30 40 50 60 70 80 90 100