

		TITLE:		DOCUMENT NUMBER:								
TASK RISK ASSESSMENT		REGION: GLOBAL		ISSUE: 5		DATE: 29-July-2022						
						PAGE 1 of 1						
WORK ACTIVITY:		REFERENCE NUMBER (Reference Procedure)			WDI Rev. No.		Date:					
Use of Hydraulic Jacks		TRA_Hydraulic Jacks_Fundamental Controls			N/A		29th July 2022					
PERSONNEL IMPACTED (Tick all applicable)												
☒ FieldCore Employees ☒ GE Employees ☒ Customer ☒ Contractors ☒ Affiliates ☐ Public ☐ Others (Specify) _____												
Special Notes: This TRA focusses on the fundamentals of Jack use and operation. Every task needs also to be assessed bringing all the aspects of the workplace, task to be done and tools to be used into consideration. Apply the controls documented within this TRA in addition to the controls that need to be applied specific to the task.												
Severity		Frequency		SEVERITY			Risk Rating					
							Strategy					
S5	Major	F5	Monthly	FREQUENCY	S1	S2	S3	S4	S5	High	Intervention - (Critical Step) PPE cannot be assigned as a Primary Defense	
S4	Severe	F4	Quarterly		F5	5	6	7	8	9	Medium	Control Do not proceed - additional defenses required
S3	Significant	F3	Annually		F4	4	5	6	7	8		
S2	Moderate	F2	Bi-Annually		F3	3	4	5	6	7		
S1	Minor	F1	> two years		F2	2	3	4	5	6	Low	Monitor Maintain Defenses
F1				F1	1	2	3	4	5			
*Risk = (Severity + Frequency) -1												
TASK STEPS		POTENTIAL RISK (PR)				DEFENSES:		CONTROLLED RISK (CR)				
		HAZARDS:		S	F	PR*			S	F	CR*	
								SAFE METHOD OF WORK				
1	Take the Jack and equipment to the point of work.	Manual Handling/Ergonomics, Walking working surfaces		3	3	5	P2W: Team PJB 360, Correct Handling Technique, P2W: Competency / Training of Crew, P2W: Access / Egress Check, P2W: Peer Check / Buddy		2	1	2	
2	Position the Jack	Manual Handling/Ergonomics, Crush/Pinch Injuries, Walking working surfaces		3	4	6	P2W: Access / Egress Check, Correct Handling Technique, Effective Communication, Level / Solid Base		2	1	2	
3	Initial Energizing (begin to apply initial pressure)	Jack line of fire ejection., Dropped Jack., Poor Base Stability, Insufficient saddle contact (Side Loading)		1	4	4	P2W: Competency / Training of Crew, P2W: Peer Check / Buddy, Control Personell Access, P2W: Pre Use Tooling Inspection, Stop Work Authority		1	2	2	
4	Carry out a pre-check before applying pressure.	Jack line of fire ejection., Poor Base Stability, Insufficient saddle contact (Side Loading)		2	4	5	P2W: Competency / Training of Crew, Equipment Eject Restraint / Lanyard		2	2	3	
6	Start to apply pressure in a controlled manner	Jack line of fire ejection., Jack Failure, Suspended Load, Suddenly liberated load		5	4	8	P2W: Peer Check / Buddy, Control Personell Access, Line of Fire Pause / Think, Personal Positioning, Stop Work Authority		2	2	3	
7	Control jacks and the load that is not shifting as planned	Jack Failure, Jack line of fire ejection., Catastrophic Component Failure		5	4	8	Stop Work Authority, Stop / Re Assessment		2	2	3	

8	Control the jacks and the load that is moving	Suspended Load, Suddenly liberated load , Insufficient saddle contact (Side Loading), Poor Base Stability	5	4	8	Personal Positioning, Stop / Re Assessment, Line of Fire Pause / Think, Equipment Eject Restraint / Lanyard	2	2	3	Jack pressure will increase / decrease as load moves. Alignment may become compromised as movement occurs. Apply Stop / ReAssess if alignment is compromised - Return to TRA Steps 3 & 4
9	Pack out, block support and keep secure the load as it moves	Suspended Load, Suddenly liberated load , Dropped Object	2	3	4	Hold Point !!, Stop / Re Assessment, Personal Positioning, Approved Packing, P2W: Peer Check / Buddy	2	2	3	Avoid prolonged suspension of load using the jacks. Insert packing in strategic places. Pinch Points - Avoid by using push tools to position packing.
10	If required remove and pack jack or replace with jack with longer cylinder.	Manual Handling/Ergonomics, Crush/Pinch Injuries., Dropped Jack., Jack line of fire ejection.	3	2	4	Hold Point !!, Stop / Re Assessment, P2W: Competency / Training of Crew, Max 80% Cylinder Stroke., Approved Packing	2	2	3	ATTENTION: Never Use Jack on Jack. Packing / Spacers need to be used to close gaps beyond the jacks 80% distance range.
11	De-energise the jack	Dropped Jack., Crush/Pinch Injuries.	2	3	4	Equipment Eject Restraint / Lanyard, Stop / Re Assessment, Personal Positioning, Line of Fire Pause / Think	2	1	2	Do not think risk has gone because the load has moved Release stored energy (Jacks) in controlled manner. DROPS & Pinch Points become the main hazard. Remove items in chronological manner
12	Remove jack from point of work and return to tool store.	Manual Handling/Ergonomics, Walking working surfaces	3	3	5	Correct Handling Technique, P2W: Competency / Training of Crew	2	1	2	Pass equipment from point of work to crew members in better ergonomic position. Make an assessment of the load (jacks & packing) to be taken to the point of work . Use mechanical aids to transport from point of work. If appropriate employ manual lifting - always adopt correct lift techniques within individual or team physical abilities. Assess access and egress routes - Free from slip, trip hazards, obstacle free and low head contact hazards

EQUIPMENT / MATERIAL / PPE REQUIRED

OEM User instructions.

Inspection Certification (Valid for length of project as a minimum).

CREATED AND ASSESSED BY:	SIGNATURE: 	PRINT NAME: Mark Edwards	DATE: 18th May 2023
REVIEWED & APPROVED BY:	SIGNATURE:	PRINT NAME:	DATE: