

		TITLE: TASK RISK ASSESSMENT				DOCUMENT NUMBER:									
						FC-GL-EHS-MAN-0501-F3 (Tab Q)									
						REGION:		ISSUE:		DATE:		PAGE:			
						GLOBAL		7		21-Sep-2021		1 of 1			
WORK ACTIVITY:				PROCEDURE REFERENCE NUMBER				Iss / Rev		TRA No.		Iss / Rev:		Date:	
Nighttime Wind Turbine Work activity				TRA_Wind_Ons_Nighttime Working_001				1.0		TRA_Wind_Ons_Nighttime Working_001		1.0		4th October 2021	
PERSONNEL IMPACTED (Tick all applicable)															
☒ FieldCore Employees ☒ GE Employees ☒ Customer ☒ Contractors ☒ Affiliates ☒ Public ☐ Others (Specify)															
Severity		Frequency		SEVERITY					Risk Rating		Strategy				
S5	Major	F5	Monthly	FREQUENCY	F5	5	6	7	8	9	High	Intervention - (Critical Step) PPE cannot be assigned as a Primary Defense			
S4	Severe	F4	Quarterly		F4	4	5	6	7	8					
S3	Significant	F3	Annually		F3	3	4	5	6	7	Medium	Control Do not proceed - additional defenses required			
S2	Moderate	F2	Bi-Annually		F2	2	3	4	5	6					
S1	Minor	F1	> two years		F1	1	2	3	4	5	Low	Monitor Maintain Defenses			
*Risk = (Severity + Frequency) -1															
TASK STEPS		POTENTIAL RISK (PR)				DEFENCES:		CONTROLLED RISK (CR)							
		HAZARDS:		S	F			PR*	S	F	CR*	Safe Method of Work			
1	Management of Fatigue	Mental Fatigue resulting in errors/omissions. Physical Fatigue resulting in injury, error, strains. Stress leading to disrupted sleep patterns, frustration & potential poor decision making		3	4	6	Uninterrupted rest periods, Time Zone Acclimatization, Maximum Shift Duration, Maximum Consecutive Shifts. Increased Supervision, Longer Working Day Rest Breaks.	1	3	3	Controls identified in FC-GL-EHS-SAF-0810 must be implemented and maintained: Maximum Shift Duration is 12 hours. Minimum uninterrupted rest between shifts is 11 hours and at least 36 hours uninterrupted rest for each 7 day period. Travel and work must not exceed 14 hours. 1 Hour Meal Break and at least one 15 minute break every 4 hours. No more than 11 days working in a row followed by 72 hours minimum paid rest time. There must be a fatigue focused Supervisor Intervention every 4 hours to check on mental and physical fatigue. Emergency arrangements must be checked and amended to account for lower workforce to respond to events.				
2	Control of Lighting Levels	Work area too dark for safe work. Lighting casting shadows. Lighting creating blinding dazzle. Lighting cables creating trip hazards. Diesels Spills or fumes from Lighting towers.		3	4	6	Sufficient artificial lighting towers. Tower position planning, Head Lamps, Cable laydown and positioning planning, Fuel Handling procedures, Spill Kits/Drip trays.	1	2	2	Lighting Towers need to be positioned and of sufficient number so that they do not create shadows that conceal slip, trip and fall hazards. Lighting Towers need to be positioned so that they do not cause dazzle blindness for any work activity or interfere with crane movement. Head lamps are for supplementary lighting only, or for circumstances when it is not reasonable to provide powered artificial lighting. Diesel fuelled Lighting towers need to be positioned so that exhaust fumes are not blowing into occupied areas or allowed to concentrate in confined/restricted spaces. Cables on nightshift need to be carefully marked or routed so that they do not create trip hazards. A drip tray and fire extinguisher must be used for refuelling lighting towers and a spill kit must be immediately available in the area. Radio communications must be maintained and frequently utilised for any major operation.				

