


EHS Procedure QuickCard

FC-GL-EHS-SAF-0713: Hot Work



Key Changes

- Replaces and Supersedes FC-GL-EHS-SAF-013A - Hot Work
- Integrates legacy Granite/PGS and Alstom procedures
- Checklist incorporated into Hot Work Permit



Key Tools

- Hot Work Permit (FC-GL-EHS-SAF-0713-F1) - **New format**



Further Work / Support

- Operational Teams:
 - Communicate requirements – on-site toolbox talk
 - Implement and provide feedback on new-style Hot Work Permit
- Training as required, including:
 - CRSE GE-EHS-670: Welding, Cutting and Brazing
 - CRSE GE-EHS-545: Portable Fire Extinguishers

Full Implementation by: 20th April 2018