

EHS Procedure QuickCard

FC-GL-EHS-0803: Radiation Safety

Advisor Appointed:
Review & Planning


Control Measures:
ALARA / ALARP

CAUTION - RADIATION AREA


Radiation Safety and ALARA



AS LOW AS REASONABLY ACHIEVABLE



Limit Time



Increase Distance

Personal Monitoring:
Dosimeters

Emergency Arrangements:
Incident Reporting



Key Elements and Changes

- Replaces 013F Radiation Safety; added information on NORM
- Covers Nuclear Power Plants work; exposure for NORM/LSA tasks
- Use customers license as FieldCore does not operate with its own
- Radiological surveys to be completed by customer and reviewed by FieldCore prior to starting work
- Survey Review - ensure actions are taken to limit dose and exposure using ALARA principles- Time, distance, shielding
- Radiation Safety Awareness training required for Rad Workers
- Report all exposures to EHS Regional Manager



Key Tools

- Rad Worker Safety Training
- Customer provided Radiation Work Permits/Risk Assessments



Further Work / Support

- Operations communicate changes to applicable employees
- Develop Rad Worker Awareness Training
- Roll-out the Rad Worker awareness Training and complete