| Pin | Funktion | Waveshare- Display | Robotling | Robotling neu |
|-----|----------|-----------------------|-----------|---------------|
| 1 | GP0 | | I2C0 SD | |
| 2 | GP1 | | I2C0 SCL | |
| 3 | GND | | | |
| 4 | GP2 | Joy U | M2 PWM | |
| 5 | GP3 | Joy S | D0 | X-Shut Links |
| 6 | GP4 | | Tx | |
| 7 | GP5 | | Rx | |
| 8 | GND | | | |
| 9 | GP6 | | | M2 PWM |
| 10 | GP7 | | | M1 PWM |
| 11 | GP8 | Data/Cmd | | |
| 12 | GP9 | SPI CS | D2-J4 | |
| 13 | GND | | | |
| 14 | GP10 | SPI Clk | M1 PWM | |
| 15 | GP11 | SPI Data | LED | |
| 16 | GP12 | Reset | | |
| 17 | GP13 | BL | | |
| 18 | GND | | | |
| 19 | GP14 | | | D2-J4 |
| 20 | GP15 | Α | | |
| 21 | GP16 | Joy L | | |
| 22 | GP17 | В | | |
| 23 | GND | | | |
| 24 | GP18 | Joy D | | |
| 25 | GP19 | | | LED |
| 26 | GP20 | Joy R | | |
| 27 | GP21 | | M3 PWM | |
| 28 | GND | | | |
| 29 | GP22 | | D1 | X-Shut Rechts |
| 30 | Run | | | |
| 31 | GP26 | | Ai0 | |
| 32 | GP27 | | Ai1 | |
| 33 | GND | | | |
| 34 | GP28 | | Ai2 | |
| 35 | ADCref | | | |
| 36 | 3V3Out | | 3V | |
| 37 | 3V3_En | | | |
| 38 | GND | | | |
| 39 | Vsys | | | |
| 40 | Vbus | | | |
| | LED | | • | |
| | Bat | | | |
| | | | | |