

M301 Overheating Response

Purpose:

Define the procedure to follow when M301 exceeds its normal operating temperature.

Trigger:

High-temperature alarm or abnormal temperature reading.

Procedure:

1. Stop or pause the machine safely.
2. Record the temperature and time.
3. Check the active alarm.
4. Check coolant level and flow.
5. Inspect for visible leakage or blockage.
6. Do not restart repeatedly if overheating continues.
7. Contact the maintenance team.
8. Record the incident in the maintenance log.

Escalation condition:

Repeated overheating or unresolved temperature abnormality requires maintenance inspection before production resumes.

Important:

This SOP does not authorize an operator to perform repairs beyond their approved responsibilities.