

Quality Inspection Procedure

Purpose:

Define the standard procedure for identifying and recording production defects.

Applicable:

All production lines.

Inspection information:

- Product
- Production line
- Machine
- Quantity inspected
- Quantity rejected
- Defect type
- Shift
- Date

Procedure:

1. Inspect the produced components according to the applicable quality standard.
2. Separate defective components.
3. Record the rejected quantity.
4. Classify the defect.
5. Identify the production line and machine where applicable.
6. Notify the responsible supervisor when rejection exceeds the accepted threshold.
7. Record the incident for further investigation.

Investigation trigger:

A sudden increase in rejection should be investigated alongside production and machine-performance data.