
Training
Shared model
Per-command model
RMSE (RPM)
0
200
400
600
800
1000
1200
Held-out validation
Shared model
Per-command model
RMSE (RPM)
200
400
600
800
1000
0.2
0.4
0.6
0.8
1.0
Normalized command