P0: Real SegFormer mask to crack skeleton, coordinates, and repair path

(a) Original image




(b) Real SegFormer-B0 mask




(c) Crack skeleton (skeletonize)




(d) Crack map (mask + width)



(e) Physical path (calibration placeholder)



(f) Smoothed skeleton trajectory (offline)



Input: Crack500 valcrop | Model: frozen SegFormer-B0 | No simulated mask. Coordinate scale is a placeholder and must be replaced by measured camera-plane calibration before robot execution.