

Twin Peaks Automotive

San Francisco, CA

REPAIR ESTIMATE

EST-260919-18

2026-09-19

|                  |                                          |          |          |
|------------------|------------------------------------------|----------|----------|
| Vehicle          | 2017 Audi A4                             | Mileage  | 90,540   |
| Customer concern | Rough idle and intermittent EPC warning. | Document | Estimate |

| Status      | Service / Part                | Parts   | Labor                      | Line Total |
|-------------|-------------------------------|---------|----------------------------|------------|
| Authorized  | Engine performance diagnostic | -       | 1.2h x \$195.00 = \$234.00 | \$234.00   |
| Recommended | Ignition coil - cylinder 2    | \$92.00 | 0.4h x \$195.00 = \$78.00  | \$170.00   |
| Recommended | Spark plug set                | \$88.00 | 1.0h x \$195.00 = \$195.00 | \$283.00   |

|                |          |
|----------------|----------|
| Parts subtotal | \$180.00 |
| Labor subtotal | \$507.00 |
| Fees           | \$15.00  |
| Subtotal       | \$702.00 |
| Sales tax      | \$15.52  |
| Total          | \$717.52 |

**Fees:** Shop supplies \$15.00  
**Notes:** Recommended work follows diagnostic test results. Customer may authorize items separately.  
**Customer authorization:** I authorize only the work specifically approved above. Any additional work requires separate authorization.

Customer signature: \_\_\_\_\_ Date: \_\_\_\_\_