

Sunset Tire & Alignment

Daly City, CA

SERVICE RECORD

SR-260919-04

2026-09-19

Vehicle	2020 Subaru Outback	Mileage	63,410
Customer concern	Uneven front tire wear and slight pull to the right.	Record type	Service Record

Technician findings

- Rear tires near wear bars.
- Front toe out of specification.

Status	Work performed	Parts	Labor	Line total
Completed	Installed four 225/60R18 all-season tires	\$760.00	-	\$760.00
Completed	Mounted and balanced four tires	-	1.2h x \$135.00 = \$162.00	\$162.00
Completed	Performed four-wheel alignment	-	1.0h x \$135.00 = \$135.00	\$135.00

Parts subtotal	\$760.00
Labor subtotal	\$297.00
Fees	\$20.00
Subtotal	\$1,077.00
Sales tax	\$66.50
Total	\$1,143.50

Recommendations

- Rotate tires every 5,000-7,500 miles.

Warranty: Tire manufacturer mileage warranty applies.

Notes: Alignment printout provided to customer.