

Pacific Suspension Works

San Mateo, CA

SERVICE RECORD

SR-260919-05

2026-09-19

Vehicle	2017 BMW 330i	Mileage	88,200
Customer concern	Clunk over bumps from front of vehicle.	Record type	Service Record

Technician findings

- Excess movement observed in both front lower control arm bushings.

Status	Work performed	Parts	Labor	Line total
Completed	Replaced left front lower control arm assembly	\$310.00	1.4h x \$185.00 = \$259.00	\$569.00
Completed	Replaced right front lower control arm assembly	\$310.00	1.4h x \$185.00 = \$259.00	\$569.00
Completed	Performed four-wheel alignment	-	1.0h x \$185.00 = \$185.00	\$185.00

Parts subtotal	\$620.00
Labor subtotal	\$703.00
Fees	\$28.00
Subtotal	\$1,351.00
Sales tax	\$57.35
Total	\$1,408.35

Recommendations

- Monitor front tire wear over next 5,000 miles.

Warranty: 12 months / 12,000 miles.

Notes: Clunk not reproduced after repair.