

CoolAir Automotive

San Jose, CA

SERVICE RECORD

SR-260919-06

2026-09-19

Vehicle	2022 Hyundai Tucson	Mileage	39,120
Customer concern	A/C blows warm after approximately 10 minutes.	Record type	Service Record

Technician findings

- Low refrigerant charge detected.
- UV dye trace found at service-port seal.

Status	Work performed	Parts	Labor	Line total
Completed	Performed A/C performance test	-	1.0h x \$165.00 = \$165.00	\$165.00
Completed	Replaced service-port seal	\$18.00	0.4h x \$165.00 = \$66.00	\$84.00
Completed	Evacuated and recharged A/C system	\$120.00	0.8h x \$165.00 = \$132.00	\$252.00

Parts subtotal	\$138.00
Labor subtotal	\$363.00
Fees	\$12.00
Subtotal	\$513.00
Sales tax	\$12.59
Total	\$525.59

Recommendations

- Return for leak recheck if cooling performance drops.

Warranty: 90-day workmanship warranty on A/C service.

Notes: Vent temperature verified after service.