

NorCal Transmission Center

South San Francisco, CA

DIAGNOSTIC REPORT

DR-260919-11

2026-09-19

Vehicle	2013 Chevrolet Malibu	Mileage	132,600
Customer concern	Transmission slips during 2-3 shift when warm.	Record type	Diagnostic Report

Technician findings

- Fluid discolored with metallic debris present in pan.
- Slip reproduced during road test when fluid temperature increased.

Status	Work performed	Parts	Labor	Line total
Completed	Performed transmission diagnostic and road test	-	1.2h x \$175.00 = \$210.00	\$210.00
Completed	Removed transmission pan for inspection	-	1.0h x \$175.00 = \$175.00	\$175.00

Labor subtotal	\$385.00
Fees	\$10.00
Subtotal	\$395.00
Sales tax	\$0.00
Total	\$395.00

Recommendations

- Separate repair estimate recommended before any transmission overhaul work.

Warranty: Not listed

Notes: No rebuild or replacement performed on this visit.