

Union Auto Service

San Francisco, CA

WARRANTY REPAIR RECORD

WR-260919-15

2026-09-19

Vehicle	2019 Volkswagen Tiguan	Mileage	68,100
Customer concern	Coolant level dropping after recent water-pump repair.	Record type	Warranty Repair Record

Technician findings

- Leak found at previously replaced water-pump gasket.

Status	Work performed	Parts	Labor	Line total
Warranty Completed	Removed and resealed water pump under warranty	-	2.5h x \$0.00 = \$0.00	\$0.00
Warranty Completed	Refilled coolant	-	-	\$0.00

Subtotal \$0.00

Sales tax \$0.00

Total \$0.00

Recommendations

- Recheck coolant level after several drive cycles.

Warranty: Warranty repair - no charge to customer.

Notes: Pressure tested after repair; no leak observed.