

SoMa Auto Repair

San Francisco, CA

SERVICE RECORD

SR-260919-16

2026-09-19

Vehicle	2016 Lexus RX350	Mileage	99,850
Customer concern	Follow-up after front brake service; slight odor during first week.	Record type	Service Record

Technician findings

- No abnormal heat pattern or fluid leak observed.
- Brake operation normal during road test.

Status	Work performed	Parts	Labor	Line total
Courtesy Check	Inspected front brake installation	-	0.4h x \$0.00 = \$0.00	\$0.00
Courtesy Check	Road tested vehicle	-	0.2h x \$0.00 = \$0.00	\$0.00

Subtotal	\$0.00
Sales tax	\$0.00
Total	\$0.00

Recommendations

- Return if odor becomes stronger or braking feel changes.

Warranty: Prior brake repair warranty remains active.

Notes: No charge follow-up inspection.