

Richmond District Garage

San Francisco, CA

INSPECTION / SERVICE RECORD

IR-260919-17

2026-09-19

Vehicle	2018 Toyota RAV4	Mileage	80,990
Customer concern	Rattle from front end; inspect before road trip.	Record type	Inspection Report

Technician findings

- Loose front underbody shield fastener found.
- Front suspension components showed no excessive play during inspection.

Status	Work performed	Parts	Labor	Line total
Completed	Performed chassis inspection	-	0.8h x \$150.00 = \$120.00	\$120.00
Completed	Secured underbody shield fasteners	\$6.00	0.2h x \$150.00 = \$30.00	\$36.00

Parts subtotal	\$6.00
Labor subtotal	\$150.00
Subtotal	\$156.00
Sales tax	\$0.52
Total	\$156.52

Recommendations

- No additional front-end repair recommended based on this inspection.

Warranty: Not listed

Notes: Rattle not reproduced after fastener repair.