

South Bay Import Service

Santa Clara, CA

SERVICE RECORD

SR-260919-19

2026-09-19

Vehicle	2020 Volvo XC60	Mileage	59,220
Customer concern	Brake squeal during low-speed stops.	Record type	Service Record

Technician findings

- Rear pads worn unevenly; rotor surfaces scored.

Status	Work performed	Parts	Labor	Line total
Completed	Replaced rear brake pads	\$195.00	1.1h x \$190.00 = \$209.00	\$404.00
Completed	Replaced rear brake rotors - pair	\$390.00	0.7h x \$190.00 = \$133.00	\$523.00

Parts subtotal	\$585.00
Labor subtotal	\$342.00
Fees	\$24.00
Subtotal	\$951.00
Sales tax	\$53.38
Total	\$1,004.38

Recommendations

- Recheck brake wear during next maintenance service.

Warranty: 24 months / 24,000 miles.

Notes: Brake squeal not reproduced after repair.