

Bay EV Diagnostic Center

San Francisco, CA

EV DIAGNOSTIC REPORT

EV-DR-260919-25

2026-09-19

Vehicle	2021 Ford Mustang Mach-E Powertrain: Battery Electric	Mileage	57,240
Customer concern	High-voltage battery warning and reduced usable range.	Record type	Diagnostic Report

Technician findings

- Vehicle stored a high-voltage battery system fault code.
- Isolation test completed within manufacturer diagnostic procedure; no pack replacement performed on this visit.

Status	Work performed	Parts	Labor	Line total
Completed	Performed high-voltage battery diagnostic scan	-	1.2h x \$195.00 = \$234.00	\$234.00
Completed	Performed battery isolation / insulation test	-	1.0h x \$195.00 = \$195.00	\$195.00
Completed	Inspected battery thermal-system components	-	0.6h x \$195.00 = \$117.00	\$117.00

Labor subtotal	\$546.00
Subtotal	\$546.00
Sales tax	\$0.00
Total	\$546.00

Recommendations

- Further manufacturer-level diagnostic follow-up recommended if the warning returns.

Warranty: Not listed

Notes: No high-voltage component replacement completed.

EV safety note: This record summarizes completed professional service. It is not a DIY guide for high-voltage systems.