

Peninsula EV & Hybrid

Redwood City, CA

EV SERVICE RECORD

EV-SR-260919-27

2026-09-19

Vehicle	2020 Chevrolet Bolt EV Powertrain: Battery Electric	Mileage	68,420
Customer concern	Battery thermal-management service message after long drive.	Record type	Service Record

Technician findings

- Coolant level was below the shop's documented service level.
- No external leak observed during pressure inspection.

Status	Work performed	Parts	Labor	Line total
Completed	Performed battery thermal-management diagnostic	-	1.0h x \$180.00 = \$180.00	\$180.00
Completed	Drained, refilled, and bled high-voltage battery coolant circuit	\$95.00	1.4h x \$180.00 = \$252.00	\$347.00
Completed	Performed cooling-system leak inspection	-	0.6h x \$180.00 = \$108.00	\$108.00

Parts subtotal	\$95.00
Labor subtotal	\$540.00
Fees	\$10.00
Subtotal	\$645.00
Sales tax	\$8.67
Total	\$653.67

Recommendations

- Return if thermal-management warning reappears.

Warranty: 90-day workmanship warranty on coolant service.

Notes: Service message cleared after procedure.

EV safety note: This record summarizes completed professional service. It is not a DIY guide for high-voltage systems.