

East Bay EV Works

Berkeley, CA

EV DIAGNOSTIC REPORT

EV-DR-260919-28

2026-09-19

Vehicle	2020 Nissan LEAF Powertrain: Battery Electric	Mileage	73,110
Customer concern	Low humming noise during acceleration between 25 and 40 mph.	Record type	Diagnostic Report

Technician findings

- Noise reproduced during road test.
- Drive-unit mount showed excess movement; no internal drive-unit repair performed.

Status	Work performed	Parts	Labor	Line total
Completed	Performed electric drive-unit road test and noise diagnostic	-	1.2h x \$175.00 = \$210.00	\$210.00
Completed	Inspected drive-unit mounts	-	0.5h x \$175.00 = \$87.50	\$87.50
Completed	Replaced worn drive-unit mount	\$225.00	1.0h x \$175.00 = \$175.00	\$400.00

Parts subtotal	\$225.00
Labor subtotal	\$472.50
Subtotal	\$697.50
Sales tax	\$23.06
Total	\$720.56

Recommendations

- Return if acceleration noise reappears.

Warranty: 12 months / 12,000 miles on replacement mount.

Notes: Noise reduced after mount replacement and verification road test.

EV safety note: This record summarizes completed professional service. It is not a DIY guide for high-voltage systems.