

Golden State EV Care

Daly City, CA

EV INSPECTION REPORT

EV-IR-260919-30

2026-09-19

Vehicle	2021 Volkswagen ID.4 Powertrain: Battery Electric	Mileage	49,760
Customer concern	Brake pedal feels different at low speed; requested regenerative and mechanical brake inspection.	Record type	Inspection Report

Technician findings

- No active regenerative-braking fault recorded during scan.
- Mechanical brake pad thickness and rotor condition documented within shop inspection limits.

Status	Work performed	Parts	Labor	Line total
Completed	Performed brake / regenerative braking diagnostic scan	-	1.0h x \$180.00 = \$180.00	\$180.00
Completed	Inspected mechanical brakes and recorded measurements	-	0.6h x \$180.00 = \$108.00	\$108.00
Completed	Tested brake fluid condition	-	0.3h x \$180.00 = \$54.00	\$54.00

Labor subtotal	\$342.00
Subtotal	\$342.00
Sales tax	\$0.00
Total	\$342.00

Recommendations

- If pedal behavior changes further or a warning appears, schedule follow-up inspection.

Warranty: Not listed

Notes: No parts replaced during this inspection.

EV safety note: This record summarizes completed professional service. It is not a DIY guide for high-voltage systems.