## Scheduler – Running Project

- Scheduler Exercise
  - > From the tasks defined in the tasks table:
    - Turn a pin level ON at the entrance of a Task and turn the pin level OFF at the end of a task execution.
    - Measure the current CPU load
      - Hint: Turn a pin level ON before entering the Background Task and turn the pin level OFF at the end of the Background Task.
    - Modify the CPU Load by adding workload to the tasks.

Space for Sender Information



## **Scheduler – Running Project**

- > Test log shall contain the following screenshots from the scope:
  - All tasks execution
  - Task Periods
  - > CPU Load

