
150



Flight ID: HSO41C HEIGHT LOSS AFTER AN ENGINE FAILURE

from HOVER PIC/SIC:

**ROTOR SPEED: 100% or 102%** 

WIND BENEFIT




Figure 4-37 Height Loss During Flyaway Weights from 6400 kg to 6800 kg

139G1560A002 ISSUE D

ICN-39-A-155050-A-A0126-10013-A-05-1