411/39

Date, Time (UTC) 2022-07-19, 1109

Flight ID:
D-HHMM
HEIGHT LOSS AFTER AN ENGINE FAILURE

from HOVER

PIC/SIC:

Joe Doe

ROTOR SPEED: 100% or 102%




Figure 4-37 Height Loss During Flyaway Weights from 6400 kg to 6800 kg