

NOVA PROGRAM

Nova Manufacturing and Quality Requirements

Domain: Manufacturing quality

Revision A | Synthetic extraction benchmark

2. Functional requirements

REQ-NVA-QLT-001 | Instrument calibration

Every instrument used for acceptance measurements shall show its serial number and a calibration expiry date later than the test date.

REQ-NVA-QLT-002 | Software traceability

Each released controller shall record a software part number and a build hash that match the approved release manifest.

REQ-NVA-QLT-003 | Sampling records

For every production lot, the inspection record shall identify the lot, state the sample size, and name the sampling plan.

3. Verification-oriented requirements

Identifier	Requirement title	Normative requirement
REQ-NVA-QLT-004	Weld acceptance	Every inspected busbar weld shall have an effective diameter of at least 4.5 mm, porosity below 8 percent, and no crack visible at 10x magnification.
REQ-NVA-QLT-005	Label content	The product label shall include the hardware revision, software revision, and a machine-readable serial number matching the human-readable serial number.

Applicability notes

Context	Interpretation
Unless a requirement states otherwise	Limits apply to the complete production-intent assembly.
Use of shall	The complete sentence is normative; table columns do not split obligations.

4. Normative installation figure




Figure 4-1. Colored geometry and embedded annotation are normative.

Engineering note

The figure annotation forms part of the controlled requirement baseline.

Color, direction, sequence, and geometric relationships must be interpreted visually.