Third subtask

```
#include <Servo.h>
Servo servo1;
Servo servo2;
Servo servo3;
Servo servo4;
Servo servo5;
int i=0;
int sensorValue =0; //what the Potentiometer reads from the port A0
int outputValue =0;
void setup()
 servo1.attach(6);
 servo2.attach(10);
 servo3.attach(3);
 servo4.attach(5);
 servo5.attach(9);
 pinMode(A0, INPUT);
}
void loop()
 sensorValue = analogRead(A0);
 outputValue = map(sensorValue, 0, 1023, 0, 90);
     servo1.write(outputValue);
     servo2.write(outputValue);
  servo3.write(outputValue);
  servo4.write(outputValue);
  servo5.write(outputValue);
 delay(10);
}
```