COMPARISON TABLE FOR ALL TIE BEAMS								
NO	VIII A TYPE	TIE BEAM TYPE	DIM. (mm)	TIE BEAM REINOFREMCENT SCHEDULE				Demank
NO.	VILLA TYPE			BOTTOM RFT	TOP RFT	SIDE BARS	STIRRUPS	Remark
1	SKAIA-6THA	TB1	300 x 800	3T16	3T16	2T10	R8-150	
		TB2	300 x 800	5T16	5T16	2T10	R8-150	
		TB3	300 x 800	7T18	7T18	2T10	R8-150	
2	т06	TB1	300 x 800	5T18	5T18	2T10	R8-150	
		TB2	300 x 800	6T18	6T18	2T10	R8-150	
3	VO2A	TB1	300 x 800	5T18	5T18	2T10	R8-150	
4	V02B	TB1	300 x 800	5T18	5T18	2T10	R8-150	
5	V02C	TB1	300 x 800	5T18	5T18	2T10	R8-150	
6	V03A	TB1	300 x 800	5T18	5T18	MISSING	R8-150	WAITING RFI RESPONSE FOR TB2
		TB2	300 x 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
7	V03B	TB1	300 x 800	5T18	5T18	MISSING	R8-150	WAITING RFI RESPONSE FOR TB2
		TB2	300 x 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
8	V03C	TB1	300 x 800	5T18	5T18	MISSING	R8-150	WAITING RFI RESPONSE FOR TB2
		TB2	300 x 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
9	V05'A	TB1	300 x 800	5T18	5T18	2T10	R8-150	
10	V05'B	TB1	300 x 800	5T18	5T18	2T10	R8-150	
11	V06A	TB1	300 X 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB2	300 X 1000	6T18	6T18	MISSING	R8-150	
		TB3	300 X 1000	5T22	5T22	MISSING	R8-150	
12	V06B	TB1	300 X 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB2	300 X 1000	6T18	6T18	MISSING	R8-150	
		TB3	300 X 1000	5T22	5T22	MISSING	R8-150	
13	V06-4THA	TB1	300 X 800	5T18	5T18	MISSING	R8-150	
14	V06-4THB	TB1	300 X 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
15	V06-5THB	TB1	300 X 800	5T18	5T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
16	V06-6THA	TB1	300 X 800	5T18	5T18	MISSING	R8-150	
17	V17A	TB1	300 X 800	4T16	4T16	MISSING	R8-150	
		TB2	300 X 800	4T16	4T16	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB3	300 X 800	4T16	4T16	MISSING	R8-150	
18	V17B	TB1	300 X 800	4T16	4T16	MISSING	R8-150	
		TB2	300 X 800	4T16	4T16	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB3	300 X 800	4T16	4T16	MISSING	R8-150	
19	V40'A	TB1	300 X 800	4T16	4T16	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB2	300 X 800	4T16	4T16	MISSING	R8-150	
		TB3	(300/650) X 800	4T16	4T16	MISSING	R8-150	
20	V40'B	TB1	300 X 900	6T18	6T18	MISSING	R8-150	WAITING FOR SIDE BARS RFI
		TB2	(300/650) X 900	6T18	6T18	MISSING	R8-150	