IBM ASSIGNMENT III

```
//Code for Blinking LED//
import RPi.GPIO as GPIO
import time
LED = 40
GPIO.setwarnings(False)
GPIO.setmode(GPIO.BOARD)
GPIO.setup(LED, GPIO.OUT)
while True:
    GPIO.output(LED,GPIO.HIGH)
    time.sleep(1)
    GPIO.output(LED,GPIO.LOW)
    time.sleep(1)
//Code for Traffic Light System//
from gpiozero import Button, TrafficLights, Buzzer
from time import sleep
buzzer = Buzzer(15)
button = Button(21)
lights = TrafficLights(25, 8, 7)
while True:
     button.wait_for_press()
     buzzer.on()
     light.green.on()
     sleep(1)
     lights.amber.on()
      sleep(1)
      lights.red.on()
      sleep(1)
      lights.off()
      buzzer.off()
```