

SRI HAMSINI & CHANDRA ENTERPRISES

Office Address: 2-1-49/244, Park Street, Street No. 17, Suryanagar Colony, Uppal, Hyderabad, Telangana - 500039

WATER PURIFICATION UNIT: INSTALLATION / COMMISSIONING / SERVICE / VISIT REPORT

Serial No: SR-000015	Report No: 1	Visit Date: 2026-07-28	Complaint No: 1	Unit Type: AMC
CUSTOMER NAME & ADDRESS:	PROBLEM REPORTED:		OBSERVATION & ACTION TAKEN:	
MPUPS THIRUMALAPURAM	Amc visit		Mcf cto gac chek and mcf chang ,booster pump not working properly tds chek , product flow chek	
		SPARES REQUIRED: Booster pump,mcf		
UNIT DETAILS / SITE CONDITION		PLANT READINGS		
Plant Location	MPUPS THIRUMALAPURAM	Raw Water TDS	350	
Plant Capacity	50	Product Water TDS	60	
Design R/W TDS	2000	Product Water Flow in LPH	50.0	
Free Chlorine in R/W	Nil	Sensors Condition	OK	
No. of Hours Running	2h	Pre-Filter Condition	OK	
Membrane Condition	OK	Voltage	230.0	
UV Lamp Condition	OK	Current in Amps	1	
SPARES CONSUMED				
Booster pump,mcf				
CUSTOMER NAME / MOBILE NUMBER	CUSTOMER SIGNATURE & DATE		SCHOOL STAMP	
Venkateshwarlu 9182045472			(no stamp on file)	
SERVICE ENGINEER: MAHESH		STATUS: PROBLEM UNRESOLVED		
SERVICE ENGINEER SIGNATURE:				
Customer Remarks: —				

E-mail Id: ch.srini1979@yahoo.com / ch.srini1979@rediffmail.com Tel No. 7670873623