Xtreme Trail Bike Helmet

1. Important Safety Information	. 3
1.1 Proper Helmet Fit	. 3
1.2 Helmet Care	. 3
1.3 Helmet Usage	. 3
2. Assembling Your Helmet	. 5
2.1 Attaching the Visor	. 5
2.2 Adjusting the Straps	. 5
2.3 Checking the Fit	. 5
2.4 Testing the Adjustments	. 5
3. Adjusting the Straps	. 5
3.1: Adjusting the Chin Strap	. 6
3.2: Adjusting the Rear Straps	. 6
3.3: Verifying the Fit	. 6
4. Using the Helmet Visor	. 7
4.1 Adjusting the Visor Angle	. 7
4.2 Removing the Visor	. 7
4.3 Cleaning the Visor	. 7
5. Cleaning and Maintenance	. 8
5.1 Helmet Cleaning	. 8
5.2 Pad and Strap Maintenance	. 8
5.3 Visor Care	. 8
5.4 Storage	. 8
6. Warranty Information	. 9
6.1 Warranty Claims Process	. 9
6.2 Exclusions	. 9
6.3 Limitation of Liability	. 9
6.4 International Warranty	. 9
6.5 Extending the Warranty	. 9

1. Important Safety Information

1.1 Proper Helmet Fit

Warning: Improperly fitted helmets can result in serious injury or death.

When fitting the Cyclo Tech Xtreme Trail Bike Helmet, ensure the following:

- The helmet sits level on your head and covers the forehead.
- The straps are adjusted to form a V-shape around each ear.
- The chin strap is tight enough to prevent the helmet from moving, but loose enough to allow for comfortable breathing.

To check for a proper fit, follow these steps:

- 1. Place the helmet on your head, ensuring it sits level and covers your forehead.
- 2. Tighten the chinstrap until it is snug beneath your chin.
- 3. Open your mouth wide; you should feel the helmet pull down on your head.

Refer to the user manual for detailed fit instructions.

1.2 Helmet Care

Caution: Failure to properly care for your helmet may reduce its effectiveness.

To clean the Xtreme Trail Bike Helmet:

- 1. Use a soft cloth and mild soap to gently wipe the outer shell.
- 2. Do not use solvents or harsh chemicals as these may damage the helmet.
- 3. Allow the helmet to air-dry before using it.

Inspect your helmet regularly for signs of wear or damage and replace as necessary.

1.3 Helmet Usage

Warning: The Xtreme Trail Bike Helmet is designed for mountain biking only.

Do not use the helmet for any other activity, such as motorcycling, skateboarding, or climbing. Doing so may result in serious injury or death.

Always fasten the chinstrap securely before riding, and ensure the helmet is properly fitted and in good condition.

2. Assembling Your Helmet

2.1 Attaching the Visor

When this helmet is first delivered, you need to attach the visor. The visor is included in the packaging, and it should be attached to the front of the helmet. Use the included screws and screwdriver to secure the visor in place. Make sure it is tightly fastened to prevent any wobbling during use.

2.2 Adjusting the Straps

The helmet comes with adjustable chin straps to ensure a secure fit. To adjust the straps, follow these steps:

- 1. Place the helmet on your head and adjust the straps so that they are snug but not too tight.
- 2. Use the adjustable buckle to secure the straps in place. Pull on the end of the strap to tighten, and release the buckle to loosen.
- 3. Make sure the straps are even on both sides of the helmet to ensure a balanced fit.

2.3 Checking the Fit

Before each use, it is important to check the fit of the helmet to ensure it provides adequate protection. Follow these steps to check the fit:

- 1. Place the helmet on your head and ensure it sits level and covers the top of your forehead.
- 2. Adjust the straps and chin buckle if necessary to achieve a snug and comfortable fit.
- 3. Shake your head gently to ensure the helmet does not move or wobble. If it does, readjust the straps and chin buckle until the fit is secure.

2.4 Testing the Adjustments

After assembling and adjusting the helmet, it is important to test the adjustments to ensure they are secure and comfortable. Take a few moments to walk around and move your head side to side to simulate biking movements. If any part of the helmet feels loose or uncomfortable, readjust the straps and chin buckle as necessary.

3. Adjusting the Straps

To ensure maximum safety and comfort, it is important to properly adjust the straps of your Cyclo Tech Xtreme Trail Bike Helmet. Follow the steps below to adjust the helmet straps.

3.1: Adjusting the Chin Strap

- Step 1: Place the helmet on your head, with the front edge sitting one inch above your eyebrows.
- Step 2: Tighten or loosen the chin strap using the adjustable buckle until it fits snugly under your chin.
- Step 3: Check that the chin strap is securely fastened and does not cause discomfort.

3.2: Adjusting the Rear Straps

- Step 1: Locate the rear stabilizer dial at the back of the helmet.
- Step 2: Turn the dial clockwise to tighten the rear straps or counterclockwise to loosen them.
- Step 3: Ensure a secure and comfortable fit by adjusting the rear straps to your preference.

3.3: Verifying the Fit

- Step 1: After adjusting the chin strap and rear straps, shake your head gently to ensure the helmet stays in place.
- Step 2: Test the fit by moving your head in different directions to confirm that the helmet does not shift or tilt.
- Step 3: If the helmet moves or feels loose, repeat the strap adjustment process until it fits securely.

4. Using the Helmet Visor

4.1 Adjusting the Visor Angle

To adjust the angle of the visor on your Xtreme Trail Bike Helmet, follow these simple steps:

- 1. Gently push and hold the visor in the desired position.
- 2. Use your other hand to tighten the screw located on the right side of the visor, ensuring it stays in place.

4.2 Removing the Visor

If you prefer to ride without the visor, you can easily remove it by:

- 1. Unscrewing the visor screw located on the right side of the helmet.
- 2. Gently lift the visor upwards to detach it from the helmet.

4.3 Cleaning the Visor

To clean the visor of your Xtreme Trail Bike Helmet, simply use mild soap and water. Avoid using harsh chemicals or abrasive materials to prevent damage.

5. Cleaning and Maintenance

5.1 Helmet Cleaning

This helmet is easy washable. Before washing, remove the inside pads and the visor. Use mild soap and warm water to clean the helmet shell, and rinse thoroughly. Do not use harsh chemicals or abrasive materials as they may damage the helmet. Allow the helmet to air dry completely before reassembling.

5.2 Pad and Strap Maintenance

To clean the inside pads and straps, hand wash them with mild soap and water. Rinse thoroughly and allow them to air dry completely before reinstalling them in the helmet. Make sure the straps are not twisted and are properly adjusted for a secure fit.

5.3 Visor Care

The visor can be cleaned with a soft cloth and mild soap. Gently wipe the visor to remove any dirt or debris. Do not use any harsh chemicals or abrasive materials on the visor as they may cause damage.

5.4 Storage

When not in use, store the Xtreme Trail Bike Helmet in a cool, dry place away from direct sunlight and extreme temperatures. Do not store the helmet near any chemicals or solvents, as they may cause damage to the materials.

6. Warranty Information

We are garantee the Cyclo Tech Xtreme Trail Bike Helmet for a period of 12 months from the date of purchase. This warranty covers any defects in materials or workmanship.

6.1 Warranty Claims Process

To make a warranty claim, please contact our customer service department at warranty@cyclo-tech.com. You will need to provide a proof of purchase and a detailed description of the issue with the helmet.

6.2 Exclusions

This warranty does not cover normal wear and tear, misuse, accidents, or damage caused by improper storage. It also does not cover modifications made to the helmet by the user.

6.3 Limitation of Liability

Cyclo Tech is not liable for any incidental or consequential damages resulting from the use of the Xtreme Trail Bike Helmet. Our liability under this warranty is limited to the cost of repairing or replacing the helmet.

6.4 International Warranty

This warranty is only valid within the country of purchase. For international warranty claims, please contact the authorized distributor in your region.

6.5 Extending the Warranty

You can extend the warranty for the Xtreme Trail Bike Helmet by registering your product online at www.cyclo-tech.com/register. By doing so, you will receive an additional 6 months of warranty coverage.