1) ANS

Prediction Accuracy = $(14/18) \times 100$ = 77.77 %

	12	18	23	40	42	44	46	48	50
B1 Buffer	0	0	0	1	0	0	0	0	0
B1 Predicted	Not Taken	Not Taken	Not Taken	Taken	Not Taken	Not Taken	Not Taken	Not Taken	Not Taken
B1 Predictor	Correct	Correct	Incorrect	Incorrect	Correct	Correct	Correct	Correct	Correct
B2 Buffer	1	1	1	0	1	1	1	1	1
B2 Predicted	Taken	Taken	Taken	Not Taken	Taken	Taken	Taken	Taken	Taken
B2 Predictor	Correct	Correct	Incorrect	Incorrect	Correct	Correct	Correct	Correct	Correct

2) ANS

Prediction Accuracy = $(15/18) \times 100$ = 83.33 %

	12	18	23	40	42	44	46	48	50
B1 Buffer	10	00	00	01	00	00	00	00	00
B1 Predicted	Taken	Not Taken							
B1 Predictor	Incorrect	Correct	Incorrect	Correct	Correct	Correct	Correct	Correct	Correct
B2 Buffer	10	11	10	11	11	11	11	11	11
B2 Predicted	Taken	Taken	Taken	Taken	Taken	Taken	Taken	Taken	Taken
B2 Predictor	Correct	Correct	Incorrect	Correct	Correct	Correct	Correct	Correct	Correct

3) ANS

Prediction Accuracy = $(97/99) \times 100$ = 97.97 %

Iteration	2-bit	Comment	Correctness
1 st	0	Not Taken	Incorrect
2 nd to 98	1	Taken	Correct
99	1	Taken	Incorrect

Prediction Accuracy = $(96/99) \times 100$ = 96.96 %

Iteration	2-bit	Comment	Correctness
1 st	00	Not Taken	Incorrect
2 nd	01	Taken	Incorrect
3 rd to 98	11	Taken	Correct
Last	10	Taken	Incorrect

aa=3, bb=2	Branch
01,01,01	L1,L2,L3 Prediction
Incorrect	L1 Not Taken
Correct	L2 Not Taken
Correct	L3 Not Taken

aa=4, bb=5	Branch
11,00,11	L1,L2,L3 Prediction
Correct	L1 Taken
Incorrect	L2 Not Taken
Incorrect	L3 Taken

aa=2, bb=2	Branch
11,01,11	L1,L2,L3 Prediction
Incorrect	L1 taken
Correct	L2 Not Taken
Correct	L3 Taken

Branch Address	Predicted PC	Predicted Taken bits
2012	2020	1
2036	2064	1

Branch Address	Predicted PC	Predicted Taken bits
2012	2020	1
2024	2032	1
2036	2064	1

7) ANS

- a) Commit the register by writing F2 then remove instruction from ROB
- b) Commit the register by writing F2 then remove instruction from ROB
- c) Commit 0(R2) register by writing it and then remove instruction from ROB
- d) Commit R3 register and then remove instruction from ROB
- e) Remove instruction from ROB

Loop:	fld	f2,0(Rx)	=>1+3
IO:	fmul.d	f2,f0,f2	=>1+4
l1:	fdiv.d	f8,f2,f0	=>1+10
I2:	fld	f4,0(Ry)	=>1+3
I3:	fadd.d	f4,f0,f4	=>1+2
I4:	fadd.d	f10,f8,f2	=>1+2
I5:	fsd	f4,0(Ry)	=>1+1
I6:	addi	Rx,Rx,8	=>1+0
I7:	addi	Ry,Ry,8	=>1+0
I8:	sub	x20,x4,Rx	=>1+0
I9:	bnz	x20,Loop	=>1+1

Number of cycles per loop iteration = 37

9) ANS.

Resulting rewritten code:

Loop:	LD	t9,0(Rx)
IO:	MULTD	t10, f0, f2
I1:	DIVD	t11, t9, t10
12:	LD	t12, 0(Ry)
I3:	ADDD	t13, f0, t12
I4:	SUBD	t14, t11, t13
I5:	SD	t14, 0(Ry)