Variable	Size	Description
u	px1	input(control)
		vector
У	qx1	output vector
X	nx1	state vector
A	nxn	state or system
		matrix
В	nxp	input matrix
С	qxn	output matrix
D	qxp	feedthrough
		matrix