Multi-Etch® Effects on Multiple Metals

Multi-Etch® was originally developed for use on titanium but it was also found to be effective on other metals.

Note: below are etching times; for recommended titanium anodizing times, see preparing for anodizing.

All tests were conducted with fresh Multi-Etch heated to 135°F

Metal	Etch Time (minutes)	Etch Depth N/C = No Change	Surface change	Notes
Aluminum	3	.0005"	Bright/semi-polished	
Brass	15 188	.004" .050	Granular	
Copper (see also PMC copper below)	15 94	.008" .050	Granular	
Gold (14KY)	3	N/C	N/C	Note 4
Hafnium	3	N/C	Frosted/matte grey	
Magnesium	3	.001"	Chalky white smut	
Meteorite (Gibeon)	3	.002"	Crystal grain revealed; black smut. Leaving in longer will make the crystal grain more pronounced.	
Nickel	5	0.00025	Matte	
Niobium	3	N/C	N/C	Note 1,4
Palladium	3	N/C	N/C	Note 4
Pewter	15 375	.002" .050		
Platinum	3	N/C	N/C	Note 2, 4

Multi-Etch® Effects on Multiple Metals

Metal	Etch Time (minutes)	Etch Depth N/C = No Change	Surface change	Notes
PMC Bronze	3	0.0025	Brightened; no smut	
PMC Copper	3	.002"	Frosted; dark brown smut	
PMC Fast Bronze	3	.003"	Crystalized surface	
Silver (925)	3	N/C	Slightly frosted	Note 4
Stainless steel	3	.001"	Frosted with dark grey smut	
Tantalum	3	N/C	N/C	Note 1,4
Titanium6/4grade 5 (aircraft grade)	6	.0005"	Brightened/matte	Note 5
TitaniumCPgrade 2	5-20 seconds 15 150	not measurable .005" .050	See Note 3	Note 3
Tool steel (01)	15 94	.008" .050	Frosted finish	
Zinc	3	.0005"	Black smut	
Zirconium	15 250	.003" .050		

Note 1

Niobium and Tantalum: Multi-Etch can be used to erase anodizing "mistakes" on these two metals. If high voltage colors, i.e., turquoise-green, need to be removed, etch times can be between 15 minutes to one hour.

These metals normally anodize without the need to use ME. However, occasionally these metals arrive from the mill with oxides that can alter the brilliance of anodizing. When that is the case, you can pre-etch these metals in order to achieve the normally brilliant colors. Etch times in these cases will vary depending on the thickness of these "mill oxides."

Multi-Etch® Effects on Multiple Metals

Note 2

Platinum: Although ME will not etch platinum, it can be used to remove all steel ions prior to welding or soldering. Rather than using the standard protocols involving a 15 minute dip in nitric acid, a 15 <u>second</u> dip in Multi-Etch at 135°F is just as effective.

Note 3

Titanium, CP grade 2: Preparing titanium for brilliant anodization requires just a 5-20 second dip. The surface finish whether polished, matte, etc. will be maintained as long as the etch time is less than 20 seconds. Longer etch times will tend to change polished finishes to matte. After five minutes, the finish starts to trend to polished.

Erasing anodizing "mistakes" takes 30 seconds to two minutes depending on the color (thickness of the oxide.) Low voltage colors take less time to remove than high voltage colors.

Note 4

Using Multi-Etch to remove broken drill bits: For gold, niobium, palladium, platinum, silver, and tantalum, dip the piece in Multi-Etch for approximately 3 minutes to remove enough of the drill bit so that it can be picked out. Leave in longer to dissolve the whole drill bit.

Note 5

Titanium, 6/4--grade 5 (aircraft grade): Generally 6/4 does not need any chemical preparation other than degreasing in order to achieve good anodized color but this can vary depending on whether or not there are stubborn oxides left from mill processing.