






50 Ohm termination




60 Ohm termination




100 Ohm termination






150 Ohm termination




60 Ohm AC termination



Unterminated





Unterminated