Project: PA6940 Current Revision: R1M0E1 PA6940 Revision History: Revision Reason for Change **Changes Implemented** Date 11th of April 2023 Connector that connects to device was not mirrored (CONNECTOR J2).

JA CONNECTOR OUT.

STRB deleted

- GPIO3 moved to pin 3

- FSYNC moved to pin 1

- Changed R1 from 0 ohm to 10 ohms -STROBE connection removed from male connector connecting slave devices -GPIO3 moved to pin 3 -FSYNC moved to pin 1 - Changed R1 from 0 ohm to 10 ohms Luxonis Holding 1925 Harmony Park Drive Westminster, CO 80234 Title PA6940 Cannot open file
C:\Users\BrianLuxonis\ Size: Tabloid Number:D0000999 Revision:R1M0E1 Date: 4.03.2024 Time: 07:56:13 Sheet1 of 3
Drawn by: Primoz Ambrozic

