Project: SL6996 Current Revision: R1M1E1 Assembly variant: Production SL6996 Revision History: **Reason for Change** Date Revision **Changes Implemented** 29 May 2023 Change connectors to top contact
 Change 15pin connector to a more robust part
 Pull connectors to center of PCB for better mechanical properties Changed connectors to top contact F32Q
 Changed 15pin connector to F52Q
 Pulled connectors to center of PCB Luxonis Holding 1925 Harmony Park Drive Westminster, CO 80234 Title SL6996 Cannot open file
C:\Users\BrianLuxonis\

