

## **Cracking white paste Cracking clear paste**

## **Technical data sheet**

- Appearance white /light yellow paste
- Application cotton and lycra etc.

## **Operation suggestions:**

- 1. 100 mesh,
- 2. Printing O100 paste 2-3 times for base---printing the cracking paste 2-3 times, after printing the first time and second time use the cold wind to dry, the last time use the hot wind to dry then cracking.



