



Cracking white paste Cracking clear paste

Technical data sheet

- Appearance white /light yellow paste
- Application cotton and lycra etc.

Operation suggestions:

- 1. 100 mesh,
- 2. Printing O100 paste 2-3 times for base---printing the cracking paste 2-3 times, after printing the first time and second time use the cold wind to dry, the last time use the hot wind to dry then cracking.



