

Faculty of Engineering, Built Environment and Information Technology

Fakulteit Ingenieurswese, Bou-omgewing en Inligtingtegnologie / Lefapha la Boetšenere, Tikologo ya Kago le Theknolotši ya Tshedimošo

Complex production scheduling due to multiple product combinations per machine.

Final report

EXECUTIVE SUMMARY

Jumbo Brands, established in 1985, was known as a popular ice popsicle company Jolly Jumbo. Not only the name has changed over the years as their production lines has grown and the type of products that they manufacture. The company only focuses on products for the food industry with items such as vinegar, lemon juice, hot chocolate. The company needs to build up to two weeks' worth of safety stock to be able to fulfil all there clients orders, currently with there Make to Order production scheduling they are struggling to keep up .

Operational research (OP) is determined as an appropriate theoretical area in industrial engineering to determine the company's most optimal solution for their production scheduling from their Make to Order system to a Make to Stock system.

A literature review is done on the above-mentioned theoretical area as well as on the project approach. In phase one of the problem analysis, industrial engineering techniques such as a fishbone diagram and the Five Whys are used to understand the problem. In the second phase of the problem analysis, research was conducted to understand what other people did when faced with a similar problem area. It was important to understand the different types of models used to obtain a production schedule and to understand what the problem identified requires.

The requirement elicitation is done in the literature review to ensure that the most fitting model is used for the project. The chosen model, Mixed integer linear program (MILP), is further explained as well as aspects connected with this specific model.

After understanding the models and gathering required data as determined by the problem analysis section it was possible to construct a preliminary solution with an objective function that minimises the amount of changeovers.

A sensitivity analysis was done to determine what will happen with the preliminary solution if identified parameters were changed, in order to make sure that the best solution is chosen. Three scenarios were considered, namely increase in demand, breakdown on one line and changing production time.

TABLE OF CONTENTS

1.	Introduction and background	1
1.1	Project context	1
1.2	Problem statement	1
1.3	Project motivation	1
1.4	Appropriate theoretical context	2
2.	Literature review	4
2.1	Literature on the project approach	4
2.1.1	Problem analysis	5
2.1.2	Solution Construction Technique	8
2.1.3	Alternative or priority construction	12
2.1.4	Literature review summary	14
3.	Project approach	. 16
3.1	Main deliverables	16
3.2	Project management deliverables	16
3.3	Phases, techniques and software tools	16
3.4	Project plan	17
3.4.1	Resources, constraints, budget	17
3.4.2	Timeline	17
4.	Problem analysis	. 18
5.	Preliminary Solution	. 22
6.	Alternative or priority construction	. 26
7.	Solution Constructs	. 28
8.	Evaluation results Error! Bookmark not defin	ned.
9.	Conclusion	. 28
Refei	rences	
Appe	endix A: Gannt chart	30
	endix B: Model Data	
Appe	endix C: The solution in Lingo	1

LIST OF FIGURES

Figure 1: Scenario 1	12
Figure 2: Scenario 1 data	13
Figure 3: Scenario 1 results	13
Figure 4: Scenario 2 results	14
Figure 5: Scenario 3 results	14
Figure 6: Fishbone diagram	18
Figure 7: Gantt chart	30
LIST OF TABLES	
Table 1: Cost description	2
Table 2: Theoretical sources	3
Table 3: Methodology connections	5
Table 4: Model description (Sung and Maravelias, 2009)	11
Table 5: Project deliverables	16
Table 7: Manufacturing line description	19
Table 8: Bot Changeover Matrix	1
Table 9: Bot Weekly demand	1
Table 10: Bot Production rates	1
Table 11:Bot Safety Stock	1
Table 12: Bot1 Changeover Matrix	2
Table 13: Bot1 Weekly Demand	2
Table 14: Bot1 Production Rates	2
Table 15: Bot1 Safety stock	2
Table 16: Bot2 Changeover Matrix	3
Table 17: Bot2 Weekly Demand	3
Table 18: Bot2 Production Rates	3
Table 19: Bot2 Safety Stock	3
Table 20: Bot3 Changeover Matrix	4
Table 21: Bot3 Weekly Demand	4
Table 22: Bot3 Production Rates	4
Table 23: Bot3 Safety Stock	4

LIST OF ABBREVIATIONS

Abbreviation	Description
MILP	Mixed Integer Linear Program
OR	Operations Research
SKU	Stock Keeping Unit
FMCG	Fast Moving Consumer Goods
TSP	Travelling salesperson problem

1. Introduction and background

In this section, the background of the project environment will be discussed to give the reader a better understanding of the project.

1.1 Project context

Small companies often adopt a multiple product approach regarding manufacturing to diversify revenue across the different market segments and seasonal periods. This approach is beneficial for financial stability within companies but can become complex due to demand increase.

Jumbo Brands is a proudly South African company that initially started by manufacturing ice popsicles under the name Jolly Jumbo. Since then, Jumbo Brands has grown immensely into a multi-product company producing different liquid and powder-based products within the food industry. These products are blended and packaged in-house for brands owned by Jumbo Brands and external contracts. Jumbo Brands manufactures 206 different products with their thirteen manufacturing lines, with each line suitable for certain products. Jumbo Brands run a wide variety of products daily, resulting in a significant decrease in efficiency as regular changeovers between products are a very timely process.

Jumbo Brands used to follow a Make to Order manufacturing process, but they were not able to complete all the required orders in time for delivery. Since then, Jumbo Brands has decided to move to a Make to Stock manufacturing process with the long term goal of at least two weeks worth of stock on hand.

1.2 Problem statement

Jumbo Brands decided to move to a Make to Stock system to obtain two weeks' safety stock, but are struggling to build and maintain this stock level with their current production planning system.

Jumbo Brands decided to build and maintain two weeks' worth of stock by minimising the complexities caused by sequence dependant changeovers. Finding a way to aid Jumbo Brands with the identified problem, it will be possible for the company to transition from a Make to Stock system to a Make to Order system.

1.3 Project motivation

Since Jumbo Brands decided to move to Make to Stock, they have struggled to build up the necessary safety stock for all their Stock Keeping Units (SKU). Production scheduling has a significant influence on creating product availability. Currently, Jumbo Brands tried to alleviate the problem by using a manual excel spreadsheet to do production planning which entails lot sizing and production scheduling. However, this tool does not help solve the complexity caused by changeovers and is based on the fulfilment of orders, not necessarily to build stock. The different compatibilities between products cause a substantial time loss due to changeovers. This loss differs between the sequence of different products. The complexity is caused by specific tasks that need to be conducted between each different product. Changeovers consist of multiple tasks: setting up the machines for a new size of packaging material and preventing cross-contamination by adequately cleaning all the needed equipment. Specific sequencing of certain product combinations is crucial to minimise the time lost due to changeovers.

The company is experiencing stock outages at times, which leads to three possibilities, namely back ordering, cancelled orders or losing a customer, all three have large cost effects on a company that could have been prevented if effective planning was done.

This example based of one of Jumbo Brands clients, Tiger Brands, this entails the cost of not fulfilling the client's order. Jumbo brands manufacture five different products for Tiger Brands on an average per month Tiger Brands orders 1258 boxes of Tiger brands SIXO Cola.

Table 1: Cost description

Cost	Description
Back ordering	Jumbo Brands offer free shipping or discount on shipping to clients depending the status of the client.
Cancelled order	As it is a big order of 1258 boxes and the client pays per box, if an order is cancelled, R 310 740 will be lost and this is only when considering one order of one item.
Losing a client	Jumbo Brands will lose approximately R 4 377 840 if only one product order for a year from one client is lost. As Jumbo Brands manufactures five different products for Tiger Brands it is possible that the client will not make use of Jumbo Brands to produce the rest of its product resulting in an even larger loss.

If the manual excel spreadsheet method of production planning is not replaced by a more suitable method, the company will still struggle to fulfil clients' orders which, leads to one of the costs occurrences mentioned in Table 1: Cost description. It is crucial to ensure the company has two weeks' worth of stock, to have a Make to Stock system, to minimise the possibility of losing capital.

1.4 Appropriate theoretical context

Operations research (OP) has shown to be the most promising area for a solution to the problem. According to Georgiadis et al. (2020), OP focuses on using different models to find an optimal solution to help with decision making within companies. The research conducted by Georgiadis et al. (2020) regarding specific OP techniques within the food process industry to improve the efficiency of production scheduling. Georgiadis considered previous models used for production scheduling. Georgiadis found that in the 1990s, researchers were trying to find algorithms that would suit all situations. These models were mainly classified as a State-Task-Network or a Resource-Task-Network.

Table 2: Theoretical sources

Year	Reference
(Descending)	
2020	G. P. Georgiadis, B. Mariño Pampín, D. Adrián Cabo and M. C. Georgiadis
	Computers and Chemical Engineering 2020 Vol. 134 DOI: 10.1016/j.compchemeng.2019.106682
2019	Optimization-Based Scheduling for the Process Industries: From Theory to Real-Life Industrial Applications
	G. P. Georgiadis, A. P. Elekidis and M. C. Georgiadis
	Processes 2019 Vol. 7 Issue 7 Pages 438 DOI: 10.3390/pr7070438
2010	MILP-based approaches for medium-term planning of single-stage continuous multiproduct plants with parallel units
	S. Liu, J. M. Pinto and L. G. Papageorgiou
	Computational Management Science 2010 Vol. 7 Issue 4 Pages 407-435
	DOI: 10.1007/s10287-009-0096-5
2009	A projection-based method for production planning of multiproduct facilities
	C. Sung and C. T. Maravelias
	AIChE Journal 2009 Vol. 55 Issue 10 Pages 2614-2630
	DOI: 10.1002/aic.11845

2. Literature review

In this chapter, a literature review is presented on how to approach the project, how to analyse the problem and how to conduct a requirement analysis. The literature review aims to conduct research in order to understand the whole project.

2.1 Literature on the project approach

Since the solution to this project lies within the field of operations research, the Design Research methodology proposed by Manson (2006) will be used. The methodology ids discussed below with the specific view of this project.

Awareness of the Problem

In this stage of the Design Research process, the problem is identified, made aware of. The problem is analysed by looking at similar problems and reviewing and understanding their solution, creation and evaluation methods to move on to the next stage of the Design Research process. The deliverable for this phase is a project proposal that will help orientate the direction of a new research effort.

Suggested solution

The focus of this phase is to formulate a model that satisfies the needs of this project. This will mainly be done by looking at similar research papers and learning from them to formulate a model that best suits the situation. The product of this phase will be a mixed-integer linear program that meets all the required outputs.

Development of solution

The model formulated in the previous phase will be developed using mathematical modelling techniques relevant to this area of study. It is still unknown which software will be used to achieve this, but further study will be done into this area.

Evaluation

The model will be compared to the current method of production scheduling to see if it is effective. This will be done by looking at certain key performance indexes relevant to the area of study. Further methods will be researched to look at the model's validity, and it will be tested to see if the answer is logical and constant.

Conclusion

Once the model has reached a point where it provides a satisfactory suggestion, it will be put forth as the final solution. This solution will then be further analysed to look at future recommendations for improving the model.

Table 3 considers how the chapters in this report connect with the methodology mentioned above. Chapter 2 is connected with all parts of the methodology as each part requires a literature review.

Table 3: Methodology connections

Chapter	Methodology		
Introduction and background	Awareness of the problem		
2. Literature review	Awareness of the Problem, Suggested solution, Development of a solution, Evaluation, Conclusion		
3. Project approach	Awareness of the Problem		
4. Problem analysis	Awareness of the Problem		
5. Solution analysis	Suggested solution		
6. Alternative or priority construction	Development of solution		
7. Solution construction	Development of solution		
8. Conclusion	Evaluation, Conclusion		

2.1.1 Problem analysis

The first phase of the problem analysis is to use industrial engineering techniques to understand the identified problem clearly and the second phase is to do research on models that considered similar problem statements as previously mentioned. As a whole this section makes it possible to formulate the problem identified and to understand what information is required to solve the problem.

Cause and effect analysis

Andersen and Fagerhaug (2006) states that a cause and effect diagram is "a diagram that analyses relationships between a problem and its causes. It combines aspects of brainstorming with systematic analysis to create a powerful technique, this tool's main purpose is to understand what causes a problem." According to Bjørn Andersen and Tom Fagerhaug (2006, p. 119) different cause and effect analyses exists, such as fishbone and process diagrams. Fishbone diagrams are a traditional method of making charts, with the main product being a chart with a shape that resembles a fishbone. A process diagram focuses more directly on analysis of problems with in business processes. A fishbone chart is created for each step of the process that is considered to create problems thus addressing all possible causes of less than expected performance. After all individual fishbone diagrams are created a collective analysis is conducted to determine the causes of the highest importance thus completing the process diagram.

The fishbone diagram will be used to analyse all potential causes of the main problem, why Jumbo brands need to change to a Make to Stock system.

Five Whys

According to Bjørn Andersen and Tom Fagerhaug (2006, p.129) the Five Whys process is used to dig deeper into the level of identified causes. To be able to ultimately determine the root cause of a problem, 'why?' should be asked every time a cause has been identified. More than Five Whys can be asked if the possible root cause was not identified in the first five steps (Andersen and Fagerhaug, 2006). It is possible that the root cause was not identified after asking the five whys meaning more whys can be asked. Ultimately when no further causes can be found, when a why is asked, the last answer to the last why asked is identified as the root cause to the problem (Andersen and Fagerhaug, 2006).

Bjørn Andersen and Tom Fagerhaug (2006, p. 130) indicates steps in order to conduct the Five Whys process:

- 1. Determine the starting point of the analysis, either a problem or an already identified cause that should be further analysed.
- 2. Use brainstorming, brainwriting, and other approaches to find causes at the level below the starting point.
- 3. Ask "Why is this a cause of the original problem?" for each identified cause.
- 4. Depict the chain of causes as a sequence of text on a whiteboard.
- 5. For each new answer to the question, ask the question again, continuing until no new answer results. This will most likely reveal the core of the root causes of the problem.
- 6. As a rule of thumb, this method often requires five rounds of the question "Why?"

By combining the Five Whys process with the cause and effect analysis it will make it possible to have a deeper understanding of the identified problem. The cause and effect diagram will be completed first then the Five Whys process will follow to clearly understand all the causes identified by the cause and effect diagram.

Researched information

As stated in Chapter 1, Georgiadis et al. (2020) considers OP techniques in the food process industry to improve the efficiency of production scheduling.

Georgiadis et al. (2019) specifically looked at a Spanish fish canning company. After the possible areas of inefficiency regarding production scheduling, it became clear that the complexity is due to the facility being host to multi-product, multi-stage production. Georgiadis et al. (2019) solution took form through multiple MILP, firstly, the model converts orders into batches using a precedence framework. After that, a MILP was running that refers explicitly at the sequencing of production; the model was formulated by using a unit-specific general precedence framework to achieve an optimal production schedule regarding the multiple sequential stages needed to complete products.

The work done by Angizeh et al. (2020) refers to taking a more smart orientated approach by implementing energy consumption into the production scheduling problem. The author uses a MILP that minimizes the total manufacturing cost, which is comprised of production, energy and labour costs. The result of this model produces optimal labour and product assignment within the production schedule.

The research conducted by Farizal et al. (2021) looks at optimising the production schedule of a fast-moving consumer good (FMCG) plant that produces soap. The proposed model uses two objective functions, which minimizes the number of machines used and the make span of products. The author tested the model by using each objective function separately and then together. This showed that minimising the number of machines leads to a low machine utilisation rate and an extended make span. This concern is appropriately altered by adding the second objective function. Farizal et al. (2021) collected data connected to production planning. The data collected is as follow:

- Production line. Description of the production line used to produce items.
- Products. Describes the product and the production line responsible for.
- Process time. Considers the time it takes to manufacture a batch.
- Product demand. Considers the demand for all items produced on the production lines in question.
- Capacity. Refers to the capability of the production line.

Liu et al. (2010) addresses a medium-term planning situation with a single-stage continuous multiproduct plant with multiple manufacturing lines requiring sequence-dependant changeovers. The model is a MILP which is based on the travelling salesperson problem (TSP). The model looks at applying a rolling horizon approach by taking the required length of the planning horizon and splitting it up into different subproblems, which are solved up and until the end of the planning horizon. Masruroh et al. (2020) looked at integrating production planning decisions with the rest of the supply chain to increase the total supply chains profit. (Masruroh et al., 2020) chose this concept due to the flexibility needed within a multi-product production facility. In a multi-product production facility, changeover and setup times should be prioritised when creating a production schedule due to their tremendous impact. Two different MILP were used to combine the two areas of interest. Various types of objective functions to best suit Masruroh et al. (2020) situations were considered. Success was shown within this study's parameters by using an objective function that maximises profit when prioritising the supply chain side of the study. After that, Masruroh et al. (2020) looked at minimising setup time and cost due to the beneficial characteristics of increasing production rate and reduced lead time. The combination of these two models creates results that reflect an optimal production schedule while considering distribution.

Very few production schedules consider the limiting factors of production resources, this side of the production scheduling problem is thoroughly explained by Jodlbauer and Strasser (2019). This is done by splitting the used items into on-demand items and consumption items. Meaning that consumption items produced in-house is used in the on-demand items. The production plan is divided into three different levels that consider the limiting constraint.

From the above research that was conducted, it is clear that a well-formulated production schedule must interact with other planning attributes within the company, such as demand and order due dates.

2.1.2 Solution Construction Technique

Georgiadis et al. (2019) shows the basis of how to formulate a Mixed Integer Linear Program (MILP) for production scheduling. It states that three elements that need to be mapped before creating the model, namely: time, tasks and resources. The *time* at which specific production tasks takes place and the appropriate sequence which they will follow. The *tasks* are the processes that need to be completed to transform the raw materials into a final product. The *resources* include all the different resources needed to manufacture a product.. To appropriately describe a production scheduling problem, you need to look at the facility data, production targets and resource accessibility and limitations. A typical production scheduling model should attend to batching/lot-sizing, task resource assignment and sequencing and timing of tasks.

Georgiadis et al. (2019) states that the MILP models that fall under these classifications can further be classified based on the time representations, namely discrete and continuous. Furthermore, the models can be categorised into time-grid based or precedence based. The concept of finding one model to suit all situations quickly became irrelevant due to the various features required by different scheduling problems.

MILP

According to Sung and Maravelias (2009) "a MILP model, variables may be continuous or discrete, all constraints are linear inequalities, and the objective function is linear, and all discrete variables are assumed to be binary-valued". Variables are constrained by integrality constraints $y \in$ and by redundant bounds $0 \le y \le 1$ (Sung and Maravelias, 2009). Sung and Maravelias (2009) states that a MILP model is "linearly relaxed" by removing integrality constraints while maintaining redundant bounds. Graphically, the feasible region of a MILP model is usually presented as the feasible region of its linear relaxation with integrality constraints superimposed, and mathematically, each enumeration of the MILP model's binary variables results in LP (Sung and Maravelias, 2009). A MILP model's linear relaxation is an over-approximation thus the solution provides a bound on the MILP optimal objective. By introducing linear inequality $y \le 0$ (in combination with $0 \le y \le 1$, this forces y to be equal to 0) or linear inequality $y \ge 1$ (this forces y to be equal to 1) a LP is restricted thus, re-introducing integrality.

When considering a series of progressively restricted LP's, organized as part of a hierarchical tree, it can be solved to collectively yield a tighter bound than the linear relaxation solution. Sung and Maravelias (2009) states that the "solution of MILP models generally relies on a branch-and-cut algorithm to organize a series of LP solutions". Since each LP roughly corresponds to a specific combination of individual binary variables being relaxed ($0 \le y \le 1$), fixed to 0, or fixed to 1, branch-and-cut is a form of implicit enumeration (Sung and Maravelias, 2009). Sung and Maravelias (2009) states that when a MILP model grows in size, it grows linearly in binary variables but exponentially in combinations.

Model Terminology

According to Sung and Maravelias (2009) models contain variables, constraints and an objective function. A combination of variables is seen as existing in a higher-dimensional space with constraints being used to define an allowed subset of this space, called the feasible region. The objective function is used to determine which point in the feasible region is most suited (Sung and Maravelias, 2009). As Sung and Maravelias (2009) states, all variables are solved simultaneously, thus no distinction is made between variables.

Scheduling formulations can be categorised into a network-based formulation of general processes or a batch-based formulation for sequential processes (Sung and Maravelias, 2009).

From Table 4, the following is obtained, to further define a facility, certain aspect needs to be identified within the facility. The process type can be described as a continuous or batch process. With a continuous process, there is a constant flow of materials throughout the entire process, and it is usually implemented with mass production facilities. Wherewith, a batch process approach is all the relevant materials are transformed at one unit before moving to the next. The production environment indicates the material handling within the facility, and it can be sequential or network-based. A sequential environment implies that each batch has an exact path that it follows to achieve a final product. It can further be split up into single stage where there is only one unit needed to manufacture the product or multi-stage where more

than one unit is used. Then a network environment has no specific operation that needs to be performed by a specific unit during manufacturing.

Table 4: Model description (Sung and Maravelias, 2009)

Type of formulation	Description
Network-based	This formulation is used to address problems in complex process networks with batch mixing/splitting and recycle streams. Network-based formulations consider batching and scheduling decisions simultaneously and can be readily extended to account for utility and storage constraints. Network-based approaches can further be classified into:
	 Discrete-time formulations: Where the time horizon is divided a priori, possibly into equal sub-periods. Continuous-time formulations: Where the time horizon is partitioned as part of the optimization. Mixed-time formulations: Where the time grid is fixed but the durations of the tasks are variable.
Batch-based	This formulation is used for single-stage, multi-stage and multi-purpose processes where batches are processed sequentially and where batch splitting/mixing is not allowed and there are no recycle streams. In batch-based formulations, batches are treated as discrete entities moving through the different stages of the process, thus preserving batch identity. Most batch-based formulations employ sequencing variables and constraints rather than a time grid. Batch-based formulations can further be classified into: 1. Slot-based 2. Precedence-based 3. Formulations that use resource-task network (RTN) ideas

Looking at the above-mentioned information it is clear that in the case of Jumbo Brands the following is applicable. Jumbo Brands follows a batch process with a sequential environment wherein it has a multi-stage setup.

Optimality

Any solution within the feasible region is seen as feasible, even if the optimal solution is not known yet. In addition, a "bound" can be found that is no worse than the optimal value. According to Sung and Maravelias (2009) a bound is used to find a value that is no worse than the optimal value. A bound is found by searching an overapproximating of the original feasible region, if the overapproximating overlaps the feasible region the optimal solution of the overapproximating must be at least as good as the optimal solution of the feasible region.

2.1.3 Alternative or priority construction

Higle and Wallace (2003) indicated that sensitivity analysis is used to explore how changes in the problem data might change the solution to a linear program. According to Higle and Wallace (2003) the use of sensitivity analysis is to allay concerns about uncertainty to draw attention to an issue that rarely arises in the development of LP models. As LP models usually includes time periods, they typically are in the time at which decisions take effect, for example production levels in a certain month

According to Farizal et al. (2021) by using sensitivity analysis scenarios it provides a check to see if the proposed LP model is applicable to provide the optimal results. An example of how to use a sensitivity analysis as done by Farizal et al. (2021) with accordance with his "Production scheduling optimisation to minimise makespan and the number of machines" LP model. In his example he considers three different scenarios namely surging demand, changing production time and if a production line is not used.

Scenario 1: Surging demand

This scenario is a situation where additional demand occurs threefold or more than the forecasting value. This situation is not an impossible situation. In real life, demand can increase triple or more when special events occur. For example, during religious holiday or at the end of year. To cope such a situation, companies usually carry safety inventory for a given period. However, if the sudden demand is beyond the safety inventory, company can implement overtime strategy or sub-contracting strategy. In this scenario, say the demand goes up like shown in Figure 1. The demand goes up four times than the forecast. For this kind of demand, will the existing production capacity be able to handle? If the answer is yes, what is the production arrangement and the schedule?

D 1 4	Demand (Box)		
Product -	Forecasting	Scenario 1	
1	29,192	89,564	
2	23,209	73,826	
3	16,182	71,975	
4	9,470	51,554	
5	14,794	58,290	
6	11,530	68,740	

Figure 1: Scenario 1

Product -	Demand (Box)		
	Forecasting	Scenario 1	
Total	104,377	413,949	

Figure 2: Scenario 1 data

Figure 3 shows the optimization result for the scenario displayed on Figure 1. The result show that the current production lines are able to handle a demand spike of four folds if the machine is scheduled properly. Table 14 clearly shows that to handle the high jump of the demand, all the four lanes are utilized with the makespan 540.1 hours. This makespan makes the production lines almost in 100% utilization. The makespan is approaching the total machine available time, i.e. 550 hours. For this scenario, Lines A, B, and C are dedicated to produce products 2, 5, and 1, respectively. While the rest of products, i.e. products 3, 4, and 6 are scheduled at Line D with the production sequence as product 6, product 3, and product 4.

Line	Product	M (hour)	T (hour)	S (hour)
A	2	0	345	345.5
В	5	0	511.3	511.8
C	1	0	523,8	524.3
	6	0	192.5	193
D	3	193	201.6	395.2
	4	395.2	144.4	540.1

Figure 3: Scenario 1 results

Scenario 2: Changing production time

This scenario happened when the total available time for the lines to be operated is only 295.4 hours instead of 505 hours. This scenario happens for instance if national holidays are observed at one particular month. The holiday will reduce the regular production time. The scenario may frequently happen in Indonesia so it should be anticipated. Figure 4 shows the optimization scheduling results for this scenario. The results indicate to use the two largest capacity machines, i.e. lines D and A. Line D is used for producing products 3 and 2, while line A is for products 1, 5, 6, and 4. The makespan for this scheduling scheme is 185.1 hours. The two lines almost utilized at the same utilization rate.

Line	Product	M (hour)	T (hour)	S (hour)
-	3	0	75.6	76.1
D	2	76.1	108.5	185.1
	1	0	81.8	82.3
A	5	82.3	41.4	124.2
	6	124.2	32.3	157
	4	157	26.5	184

Figure 4: Scenario 2 results

Scenario 3: Production line is not being used

Scenario 3 is a situation where the number of products needed is normal but a line with the largest capacity is broken or turned off for maintenance. If this scenario happens, what is the optimum scheduling to be used? In this research, the scenario is only checked for the largest capacity machine since this scenario will make sure the production will be fulfilled if a lesser capacity machine was broken. Figure 5 shows the optimization result for scenario 3. The production can be scheduled with the second largest capacity machine, Line A. The makespan for this scenario is 490.7 hours and the production sequence are product 1, 3, 2, 5, 4, and 6.

Line	Product	M (hour)	T (hour)	S (hour)
	1	0	136.4	136.9
	3	136.9	75.6	213
	2	213	108.5	322
A	5	322	69.1	391.6
	4	391.6	44.3	436.4
	6	436.4	53.9	490.7

Figure 5: Scenario 3 results

In this example he makes use of scenarios that can happen in real life and based of the chosen scenarios and the changes it brings he determined the best solution. A sensitivity analysis will be done, in accordance with the example mentioned above, in order to understand the effect that changes have on the model and to ultimately chose the best solution to the problem.

2.1.4 Literature review summary

The literature reviews consider industrial engineering techniques such as the fishbone diagram and Five Whys to understand the complete problem. Past research is used to understand how other similar problems were analysed and what method was used to ultimately understand the problem to solve it.

According to the information obtained from the research conducted it was established that to solve the problem it is required to make use of a MILP model. The requirement elicitation section further looks in to a MILP to understand how it works and what is required to obtain a MILP

Another industrial engineering technique was researched, namely a sensitivity analysis, this is used to understand the proposed solution and to see what changes have an effect on the model to ensure the correct solution was chosen. The sensitivity analysis also provides guidance to highlight where changes must be made or re-evaluated where the model is concerned.

3. Project approach

In this section the project approach will be discussed in detail.

3.1 Main deliverables

The main deliverable of this project is a MILP model. The MILP must aid the company in their Make to Stock system by ensuring that two weeks' worth of stock is available at all times.

3.2 Project management deliverables

All deliverables mentioned in Table 5 will be completed during BPJ 410 and BPJ 420. The mentioned deliverables will be used to complete the project and for the for the project sponsor to understand better understand the structure of the project.

Table 5: Project deliverables

Number	Deliverable
1.	Project topic
2.	Project proposal and ethical clearance
3.	Preliminary project report and reflection on learning
4.	Oral presentation
5.	Interim project report
6.	Final project report
7.	Poster
8.	Final oral presentation

3.3 Phases, techniques and software tools

As stated in Section 2.1 of the Design Research methodology proposed by Manson (2006) is be used for this project. By making used of this methodology, the problem can be understood, and a solution can be modelled.

3.4 Project plan

The project plan is considered in this section. The resources, constraints, budget and timeline is considered.

3.4.1 Resources, constraints, budget

In order to obtain the correct information to understand the problem and to ultimately be able to construct a model human resources are required to gather this information.

Software tools will be required to analyse the information obtained and to model a solution. A software tool such as Lingo, Python or Excel will be used to model and test the constructed model to see if it is indeed the best solution. A computer will also be used to enable to usage of the stated software tools.

3.4.2 Timeline

A detailed timeline is presented in Appendix A: Gannt chart by making use of a Gantt chart, this timeline is done in more detail then the BPJ module presents.

4. Problem analysis

As stated in Section 2.1.1 before the production problem is modelled it is important to first understand the problem as a whole and to then understand the current production planning structure of the company which will present the information that is required to solve the problem.

Observations

To find the possible bottle neck which is withholding the company from keeping a two week stock level per product the ERP was consulted. After analysing which products are on back order the most and which machine lines they correspond with. It became evident that only the Bottling lines where currently struggling to keep up with orders. Even though further analysis showed that the 4 bottling lines are capable of producing the required amounts if managed properly. Thus the model only needs to cover these four lines. The relevant Data for the model for each line can be seen in Appendix B: Model Data.

The fishbone diagram combined with the Five Whys

As mentioned in the literature review the fishbone diagram and the Five Whys method is combined in order to have a better understanding of the problem. As seen in Figure 6: Fishbone diagram the main problem is that there is no sufficient finished goods safety stock available. Three causes were looked at, namely current production planning structure, the long changeover time and the machine capacity. The current production planning structure looks at the current Excel spreadsheet method used to fulfil a client's order and how this Make to Order structure is preventing safety stock to build up. Long changeover time, as production is scheduled according to client orders the most optimal changeover time is not considered meaning this is production time lost which can be used to produce finished goods.

The machine capacity considers the fact that production is scheduled according to the Make to Order structure meaning the machines full capacity is not always used and again not optimising production time.




Figure 6: Fishbone diagram

By considering the Five Whys conducted for each cause it is evident that the Make to Order structure is restricting the safety stock levels that want to be obtained, thus a Make to Stock structure is indeed a possible solution to the problem. It is also clear that the causes mentioned are affected by the fact that a proper production scheduling model/program that considers changeover times, machine capacity and stock levels is not in place. By making use of the suggested MILP model as seen in the literature review it is possible to take the identified causes into consideration to solve the problem.

The facility

Jumbo Brands currently have thirteen manufacturing lines. The thirteen lines are described, as seen in Table 6. The facility has two warehouses where raw materials and finished products are received, sent and stored from. As production planning instructs, raw materials are obtained from the warehouse and then taken to the appropriate manufacturing line to start the production process. Currently items are made according to an order meaning directly after production they are delivered to the client.

Table 6: Manufacturing line description

Line number	Line name	Line description
1.	ВОТ	This manufacturing line produces liquid products for a size range of 300 ml to 2000ml and is responsible for manufacturing products for Boston, Pic n Pay, Ubrands, Unity, Majoya and Squash.
2.	BOT1	This manufacturing line produces only fruit liquid products for a size range of 300 ml to 2000ml and is responsible for manufacturing products for Boston and Pic n Pay.
3.	BOT2	This manufacturing line produces liquid products only for size 200 ml and is responsible for manufacturing all Tiger Brand products.
4.	вот3	This manufacturing line produces liquid products for a size of only 500 ml and is responsible for manufacturing products for Boston, Revite, Checkers, Liberty, OK, Rite, Unity, Ubrands and Pic n Pay.
5.	PALLETS	This manufacturing line produces fried products for a size range of 60 g to 100 g and is responsible for manufacturing products for Craves and Pic n Pay.
6.	STICKS	This manufacturing line produces powdered mixed beverages in a longer sachet shape for a size range of 12.5 g to 20 g and is responsible for manufacturing products for Boston and Caddie.
7.	CREAMER	This manufacturing line produces fried products for a size range of 375 g to 750 g and is responsible for manufacturing products for Boston, Unity and Ubrands.
8.	ENRISTA	This manufacturing line produces powdered mixed beverage sachets for a size range of 12 g to 100 g and is responsible for manufacturing products for Enrista.

Line number	Line name	Line description
9.	ENRISTA1	This manufacturing line produces powdered mixed beverage sachets for a size range of 18 g to 30 g and is responsible for manufacturing products for Enrista.
10.	FIESTAS	This manufacturing line produces only chip products with a size of 150 g and is responsible for manufacturing products for Fiestas.
11.	FT	This manufacturing line produces only ice pops with a size of 150 ml and is responsible for manufacturing products for Fruit treats.
12.	JAR	This manufacturing line produces powdered mixed beverages packaged in jars for a size range of 250 g to 500 g and is responsible for manufacturing products for Boston and Pic n Pay.
13.	JJ	This manufacturing line produces popsicles for a size range of 25 ml to 80 ml and is responsible for manufacturing products for Jolly Jumbo.

Products

In Appendix B: Model Data, It shows all products manufactured on the 4 bottling lines and there respective data needed for the model.. The company manufactures products such as coffee and different types of beverages, lemon juice, vinegar and snacks.

Production capacity

Each product produced on the corresponding lines as seen in **Error! Reference source not found.** has its own rate at which a specific product can be produced. It is important to obtain this information as it is required for the scheduling of production to be performed accurately in accordance with the demand forecasting of a product. The production capacity is described by the number of units produced after an hour.

Demand forecasting

The Sales department has established a sales forecast for the year from March 2021 to February 2022. According to the Sales department this forecasting is done based on historical data and seasonal demand patterns. There after the average range of stock was calculated to test if the model will be able to robust enough to handle all products irrespective of seasonality. The forecast is required to determine how many hours are required for each line per time period.

To create a solution to Jumbo Brands production scheduling problem, there will be two main areas that the model will have to consider. This was evident after conducting the problem analysis:

• It must accurately determine the lot sizes per stock-keeping unit (SKU) to enable the company to achieve the goal of two-weeks safety stock.

•	To correctly place these lots into a most optimal sequence with regards to time wasted due to changeovers.

5. Preliminary Solution

In the following chapter a preliminary solution for the problem will be presented. The preliminary solution contains sets identified, parameters determined according to the identified information in Chapter 4, the variables required, the constraints identified to limit the model and lastly the objective function.

We then let:

Sets

Let \overline{L} be the set of machines.

Let \overline{T} be the set of weeks.

Let \overline{I} be the set of products.

Let $\overline{I_l}$ be the set of products that can be produced on line l.

Parameters

 $c_{ijl} \triangleq \text{The given changeover time(hours)}$ from product i to j on line l, where $i \in \overline{I}$ and $j \in \overline{I}$ and $l \in \overline{L}$.

 $d_{it} \triangleq \text{The given demand per product } i \text{ in week } t \text{, where } i \in \overline{I} \text{ and } t \in \overline{T}.$

 $r_{il} \triangleq \text{The given production rates of product } i \text{ on line } l, \text{ where } i \in \overline{l} \text{ and } l \in \overline{L}.$

 $s_i \triangleq \text{The given safety stock on hand per product } i, \text{ where } i \in \overline{I}.$

 $a \triangleq$ The available time for production in a week for production excluding weekends.

 $z \triangleq$ The available time for production in a week for production including weekends..

Variables

 $p_{it} \triangleq \text{The amount of product } i \text{ produced during time period } t, \text{ where } i \in \overline{I} \text{ and } t \in \overline{T}.$

 $o_{ilt} \triangleq \text{The order in which product } i \text{ is manufactured on production } l \text{ during time}$ period t, where $i \in \overline{I}$ and $l \in \overline{L}$ and $t \in \overline{T}$.

 $v_{it} \triangleq \text{The inventory level of product } i \text{ for time period } t \text{, where } i \in \overline{I} \text{ and } t \in \overline{T}.$

 $pt_{ilt} \triangleq \text{The production time of product } i \text{ on prodution line } l \text{ during time period } t \text{, where } \in \overline{I} \text{ and } l \in \overline{L} \text{ and } t \in \overline{T}.$

 $x_{ilt} \triangleq \begin{cases} 1 \text{ if product } i \text{ is produced on production line } l \text{ during time period } t, \text{ where } i \in \overline{I} \\ & \text{and } l \in \overline{L} \text{ and } t \in \overline{T}. \\ & 0 \text{ Otherwise} \end{cases}$

```
lp_{ilt} \triangleq \begin{cases} 1 \text{ if product } i \text{ is the last product produced on production line } l \text{ during time} \\ \text{period } t, \text{ where } i \in \overline{I} \text{ and } l \in \overline{L} \text{ and } t \in \overline{T}. \\ 0 \text{ Otherwise} \end{cases}
fp_{ilt} \triangleq \begin{cases} 1 \text{ if product } i \text{ is the first product produced on production line } l \text{ during time} \\ \text{period } t, \text{ where } i \in \overline{I} \text{ and } l \in \overline{L} \text{ and } t \in \overline{T}. \\ 0 \text{ Otherwise} \end{cases}
ct_{ijlt} \triangleq \begin{cases} 1 \text{ if product } i \text{ is manufactured before product } j \text{ on production line } l \text{ during} \\ \text{time period } t, \text{ where } i \in \overline{I} \text{ and } j \in \overline{I} \text{ and } l \in \overline{L} \text{ and } t \in \overline{T}. \end{cases}
0 \text{ Otherwise}
bt_{ijlt} \triangleq \begin{cases} 1 \text{ if there is a changeover from product } i \text{ in week } t\text{-1 to product } j \text{ in week } t \text{ on production line } l \\ \text{time period } t, \text{ where } i \in \overline{I} \text{ and } j \in \overline{I} \text{ and } l \in \overline{L} \text{ and } t \in \overline{T}. \end{cases}
0 \text{ Otherwise}
```

Objective Function

$$\min \mathbf{z} = \sum_{i \in I_l} \sum_{j \in I_l} \sum_{l \in L} \sum_{t \in T} ct_{ijlt} + bt_{ijlt}$$
(1)

Subject to:

$$\begin{split} \sum_{i \in I_l} f p_{ilt} &= 1 & \forall l \in \overline{L}; t \in \overline{T} & (2) \\ \sum_{i \in I_l} l p_{ilt} &= 1 & \forall l \in \overline{L}; t \in \overline{T} & (3) \\ f p_{ilt} \leq x_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (4) \\ l p_{ilt} \leq x_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (5) \\ o_{jlt} - (o_{ilt} + 1) \geq -M(1 - ct_{ijit}) & \forall i \in \overline{I}_l; j \in \overline{I}_l; j \neq i; l \in \overline{L}; t \in \overline{T} & (5) \\ \sum_{\substack{i \in I_l \\ i \neq j}} ct_{ijit} = x_{jlt} - f p_{jlt} & \forall j \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (7) \\ \sum_{\substack{j \in I_l \\ i \neq j}} ct_{ijit} = x_{ilt} - l p_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (8) \\ \sum_{\substack{j \in I_l \\ i \neq j}} bt_{ijlt} = f p_{jlt} & \forall j \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} - \{1\} & (9) \\ \sum_{j \in I_l } bt_{ijlt} = l p_{il(t-1)} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} - \{1\} & (10) \\ o_{ilt} \leq M x_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (11) \\ f p_{ilt} \leq o_{ilt} \leq \sum_{j \in I_l} x_{jlt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (12) \\ ax_{ilt} \leq pt_{ilt} \leq zx_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (13) \\ \sum_{i \in I_l } pt_{ilt} + \sum_{i \in I_l } \sum_{j \in I_l} (ct_{ijlt} + bt_{ijlt}) c_{ijl} \leq z & \forall l \in \overline{L}; t \in \overline{T} - \{1\} & (14) \\ \sum_{i \in I_l } pt_{ilt} + \sum_{i \in I_l } \sum_{j \in I_l} (ct_{ijlt}) c_{ijl} \leq z & \forall l \in \overline{L}; t \in \overline{T} & (15) \\ p_{it} = r_{ii} pt_{ilt} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (16) \\ v_{it} = v_{i(t-1)} + p_{it} - d_{it} & \forall i \in \overline{I}_l; t \in \overline{T} & (17) \\ v_{it} \geq s_i & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (19) \\ o_{ilt}, pt_{ilt} \geq 0 & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (20) \\ x_{ilt}, l p_{ilt}, ct_{ijt}, ct_{ijt}, bt_{ijit} \in \{0,1\} & \forall i \in \overline{I}_l; l \in \overline{L}; t \in \overline{T} & (21) \\ \end{cases}$$

(1) is the objective function that minimises the number of changeovers. Constraints (2)-(3) ensures that at least one product runs on the production line per shift. Where constraints (4)-(5) allocates the first and last products during each shift. Constraint (6) looks at the production order within the time period. In constraint (7)-(8) all the changeovers within the time period are assigned. The (9)-(10) is to allocate changeovers between time periods with constraint (11) being used to eliminate subtours by forcing it to 0 if it is not produced. (12) ensures that the order index follows a numerical order. Constraint (13) is used to restrict the production time for a week. (14)-(15) is used to restrict the summation of the production time and changeover times that it does not exceed the available time. (16) calculates the amount of products produced with (17) calculating the inventory level for the time period (18) is used to ensure that there is always two weeks worth of safety stock. Constraint (19)-(20) is the non negativity constraints and (20) is the binary constraint.

6. Alternative or priority construction

After constructing the program in LINGO as can be seen in Appendix C: The solution in Lingo the solution was defined as infeasible. This is due to the constraints being to restrictive according to analysis. But there is no constraints that aren't necessary that can be removed to make the constraints more slack. Thus, the following chapter could not be done accordingly but problem areas are discussed in Solution

Constructs. As soon as this corrected the following will be conducted during the sensitivity analysis.

Alternative solution

For the alternative solution the objective function will be changed to maximise the makespan of production. This will not only help achieve the goal of obtaining two weeks worth of stock but build a

further buffer of stock

Alternative Objective Function

$$max z = \sum_{i \in I} \sum_{t \in T} p_{it}$$

Sensitivity Analysis

Three different scenarios are considered and analysed to understand what effects these changes will

have on the model.

Scenario 1: Increase in demand

The first scenario considers what will happen to the model if demand is increased by double the forecasting value. This is analysed as it will have an effect on the production period, changeover time and the safety stock amount required. The effect of the change in demand must be analysed as this is a sure thing that will happen as some of the products being considered are in fact seasonal products, such as all cold beverages and ice cream products produced. As mentioned the seasonal products will have

an effect on the safety stock amounts which is the main concerns of the project.

After considering the increase in demand it is important to understand if the model will restrict any further increase in demand and if yes wat what level of increase will this happen? If the model is indeed

capable of handling the demand increase how will the production schedule change?

Scenario 2: Breakdown on one line

In this scenario the required safety stock amount stays the same but one of the eleven production lines are experiencing a breakdown or maintenance is required. This scenario considers what the model will do to obtain the optimal schedule in this scenario. As multiple lines can be used to produce similar

products only the lines capable of producing these similar products will be considered.

Scenario 3: Changing production time

26

This scenario considers what the model will do when the production period is changed. This consideration is important as it is inevitable that the production period will not stay constant always as events such as strikes, holiday or production issues will occur.

7. Solution Constructs

The following chapter will discuss the model.

Current Model

The solution was constructed by referring to multiple other production scheduling models. It became evident that most of them follow the same way of thinking as a traveling sales person problem. Thus this model follows the same direction.

Further research into objective function types that Minimise changeovers or Maximise Makespan revealed the following. Objective functions that minimise Changeovers give you the most cost-effective way to achieve your production goal. Because as soon as the production goal is achieved for the time period it will not assign further production.

Whereas an objective function that maximises makespan Will achieve the production goals with additional manufacturing taking place. Thus, this utilizes the facility the best but gives you a bunch of extra stock.

8. Conclusion

The Model was not able to run due to unknown reasons so the conclusion of this project is for further research to be done.

Future Work on model

After allot of analysis done on the current model there where no formulation errors but the solution still remained infeaseable. During Debugging mode it came up that the model suggests that the problem sits with constraint 14 which is used to restrict the summation of the production time and changeover times that it does not exceed the time available for production.

$$\sum_{i \in I_l} pt_{ilt} + \sum_{i \in I_l} \sum_{j \in I_l} (ct_{ijlt} + bt_{ijlt}) c_{ijl} \le z \qquad \forall l \in \overline{L}; t \in \overline{T} - \{1\}$$

$$(14)$$

After this I tried to play around with the time allowed for production which lead to no results. Thus I would suggest further research into how to relax this constraint.

References

- ANDERSEN, B. & FAGERHAUG, T. 2006. Root cause analysis: simplified tools and techniques. Second edition. ed. Milwaukee, Wisconsin: ASQ Quality Press.
- ANGIZEH, F., MONTERO, H., VEDPATHAK, A. & PARVANIA, M. 2020. Optimal production scheduling for smart manufacturers with application to food production planning. *Computers & Electrical Engineering*, 84.
- FARIZAL, F., GABRIEL, D. S., RACHMAN, A. & RINALDI, I. 2021. Production Scheduling Optimization to Minimize Makespan and the Number of Machines with Mixed Integer Linear Programming. 1041.
- GEORGIADIS, G. P., ELEKIDIS, A. P. & GEORGIADIS, M. C. 2019. Optimization-Based Scheduling for the Process Industries: From Theory to Real-Life Industrial Applications. *Processes*, 7, 438.
- GEORGIADIS, G. P., MARIÑO PAMPÍN, B., ADRIÁN CABO, D. & GEORGIADIS, M. C. 2020. Optimal production scheduling of food process industries. *Computers and Chemical Engineering*, 134.
- HIGLE, J. L. & WALLACE, S. W. 2003. Sensitivity Analysis and Uncertainty in Linear Programming. *Interfaces* [Online], 33.
- JODLBAUER, H. & STRASSER, S. 2019. Capacity-driven production planning. Computers in Industry, 113.
- LIU, S., PINTO, J. M. & PAPAGEORGIOU, L. G. 2010. MILP-based approaches for medium-term planning of single-stage continuous multiproduct plants with parallel units. *Computational Management Science*, 7, 407-435.
- MANSON, N. J. 2006. Is operations research really research? *Orion*, 22, 155-180.
- MASRUROH, N. A., FAUZIAH, H. A. & SULISTYO, S. R. 2020. Integrated production scheduling and distribution allocation for multi-products considering sequence-dependent setups: a practical application. *Production Engineering: Research and Development*, 14, 191-206.
- SUNG, C. & MARAVELIAS, C. T. 2009. A projection-based method for production planning of multiproduct facilities. *AIChE Journal*, 55, 2614-2630.

Appendix A: Gannt chart




Figure 7: Gantt chart

Appendix B: Model Data

Table 7: Bot Changeover Matrix

Changeover	всокт вс	COLI	BCOPF	BOACV	/ воз	SQ5 BV	/1 B'	V2 B	V5 B	V6	CHSQ5	CSV3	CSV4	t CS	/7 CS	V8 F	FGRANNEC FC	RNEC02 FT	SFC F	rsg F	T5MO F	T50 F	TSPA I	J250 L	IE250 P	PCOKT P	PCOLI P	PCOPF P	PLJ25 P	PNNCOCE PE	NNCOC! PE	NNCOIB PP	NNCOPF PI	PNNCORI PI	PNNCOTF PP	SQ5 SV	1 SV	2 U	TV3 U	ITV4
всокт	0,00	0,53	0,:	.9 (0,47	0,84	0,51	0,65	0,72	0,93	3 0,92	0	,91	0,50	0,65	0,66	0,54	0,02	0,62	0,38	0,03	0,75	0,98	0,62	0,94	0,23	0,70	0,31	0,67	0,90	0,38	0,30	1,00	0,63	0,38	0,17	0,32	0,70	0,72	0,20
BCOLI	0,17	0,00	0,4	18	0,14	0,82	0,39	0,87	0,76	0,91	1 0,60	0	,18	0,97	0,88	0,14	0,13	0,78	0,08	0,66	0,00	0,30	0,86	0,75	0,27	0,25	0,90	0,70	0,52	0,36	0,70	0,69	0,62	0,16	0,66	0,54	0,64	0,23	0,92	0,06
BCOPF	0,58	0,89	0,0	10 0	0,26	0,91	0,39	0,76	0,66	0,68	8 0,08	3 0	,19	0,39	0,24	0,60	0,08	0,44	0,25	0,44	0,53	0,60	0,48	0,48	0,12	0,19	0,61	0,40	0,89	0,07	0,91	0,37	0,88	0,82	0,87	0,80	0,92	0,07	0,80	0,48
BOACV	0,41	0,80	0,5	9 (0,00	0,51	0,49	0,53	0,11	0,15	5 0,08	3 0	,66	0,22	0,66	0,89	0,55	0,73	0,82	0,17	0,08	0,17	0,30	0,68	0,02	0,72	0,52	0,58	0,29	0,56	0,87	0,20	0,05	0,02	0,86	0,12	0,10	0,24	0,36	0,94
BOSQ5	0,32	0,83	0,9	14 (0,36	0,00	0,25	0,92	0,19	0,69	0,17	7 0	,10	0,94	0,40	0,38	0,15	0,29	0,23	0,76	0,58	0,64	0,41	0,48	0,39	0,33	0,42	0,45	0,31	0,22	0,41	1,00	0,05	0,33	0,94	0,27	0,36	0,11	0,62	0,08
BV1	0,29	0,95	0,3	12	0,17	0,03	0,00	0,73	0,03	0,53	0,29	0	,25	0,54	0,45	0,47	0,21	0,24	0,23	0,54	0,44	0,38	0,95	0,53	0,25	0,41	0,30	0,68	0,35	0,44	0,27	0,72	0,45	0,29	0,56	0,05	0,76	0,13	0,66	0,26
BV2	0,29	0,56	0,:	2 (0,25	0,27	0,13	0,00	0,51	0,70	0,89	0	,58	0,25	0,60	0,96	0,84	0,91	0,08	0,55	0,99	0,22	0,36	0,74	0,81	0,71	0,06	0,90	0,46	0,94	0,44	0,92	0,93	0,04	0,53	0,25	0,26	0,01	0,20	0,36
BV5	0,49	0,93	0,4	17 (0,46	0,02	0,54	0,22	0,00	0,76	5 0,40	0	,23	0,01	0,38	0,35	0,12	0,52	0,98	0,71	0,74	0,76	0,59	0,97	0,51	0,49	0,24	0,18	0,11	0,81	0,39	0,47	0,43	0,86	0,67	0,31	0,93	0,17	0,88	0,30
BV6	0,06	0,24	0,7	8 8	0,85	0,33	1,00	0,92	0,98	0,00	0,28	3 0	,43	0,24	0,75	0,43	0,01	0,61	0,55	0,10	0,62	0,42	0,17	0,73	0,34	0,49	0,17	0,63	0,43	0,23	0,37	0,88	0,87	0,17	0,38	0,56	0,36	0,40	0,64	0,16
CHSQ5	0,50	0,92	0,0)1 (0,89	0,34	0,26	0,21	0,74	0,93	3 0,00	0	,20	0,63	0,73	0,99	0,03	0,23	0,05	0,00	0,74	0,18	0,96	0,95	0,62	0,85	0,79	0,75	0,94	0,31	0,14	0,64	0,44	0,96	0,46	0,81	0,80	0,83	0,92	0,25
CSV3	0,09	0,37	0,6	6 (0,75	0,16	0,44	0,96	0,45	0,38	0,12	0	,00	0,08	0,39	0,14	0,63	0,44	0,62	0,31	0,13	0,81	0,36	0,36	0,00	0,26	0,69	0,56	0,75	0,53	0,59	0,32	0,63	0,96	0,44	0,90	0,45	0,22	0,68	0,90
CSV4	0,60	0,26	0,6	6 (0,68	0,22	0,37	0,41	0,13	0,94	4 0,55	0	,21	0,00	0,99	0,29	0,19	0,77	0,09	0,02	0,06	0,25	0,59	0,64	0,97	0,15	0,54	0,46	0,55	0,78	0,91	0,42	0,17	0,08	0,07	0,26	0,14	0,93	0,40	0,07
CSV7	0,96	0,58	0,3	14	0,48	0,64	0,85	0,66	0,24	0,39	0,52	2 0	,82	0,24	0,00	0,74	0,05	0,06	0,92	0,86	0,08	0,82	0,90	0,07	0,46	0,97	0,71	0,68	0,06	0,21	0,13	0,78	0,95	0,76	0,11	0,64	0,01	0,12	0,34	0,16
CSV8	0,69	0,35	0,3	15 (0,82	0,38	0,39	0,34	0,43	0,03	0,38	3 0	,95	0,00	0,29	0,00	0,43	0,73	0,27	0,50	0,46	0,02	0,83	0,75	0,56	0,49	0,41	0,27	0,19	0,99	0,55	0,09	0,12	0,19	0,74	0,39	0,84	0,74	0,71	0,97
FGRANNEC03	0,15	0,40	0,3	18	0,55	0,07	0,42	0,35	0,38	0,47	7 0,67	0	,15	0,06	0,26	0,82	0,00	0,36	0,02	0,61	0,04	0,29	0,05	0,24	0,24	0,04	0,50	0,07	0,24	0,86	0,56	0,74	0,22	0,77	1,00	0,27	0,12	0,16	0,47	0,50
FORNEC02	0,61	0,70	0,7	75 (0,96	0,13	0,52	0,05	0,55	0,94	4 0,56	0	,08	0,94	0,30	0,58	0,92	0,00	0,68	0,69	0,15	0,70	0,01	0,62	0,98	0,47	0,81	0,85	0,53	0,17	0,90	0,36	0,49	0,09	0,43	0,97	0,97	0,72	0,10	0,10
FT5FC	0,67	0,77	0,4	10 1	0,99	0,17	0,26	0,31	0,88	0,67	7 0,91	. 0	,92	0,07	0,10	0,76	0,42	0,42	0,00	0,76	0,45	0,71	0,49	0,93	0,00	0,10	0,19	0,54	0,08	0,87	0,03	0,27	0,11	0,40	0,30	0,76	0,79	0,37	0,58	0,87
FT5G	0,51	0,80	0,:	.8 (0,71	0,33	0,27	0,10	0,40	0,52	2 0,84	0	,20	0,82	0,73	0,51	0,32	0,21	0,23	0,00	0,64	0,60	0,50	0,84	0,10	0,42	0,45	0,17	0,16	0,70	0,08	0,83	0,03	0,53	0,54	0,02	0,23	0,27	0,19	0,20
FT5MO	0,47	0,35	0,9	18	0,29	0,72	0,55	0,70	0,45	0,86	0,15	0	,15	0,66	0,83	0,63	0,53	0,43	0,95	0,21	0,00	0,91	0,75	0,08	0,33	0,82	0,53	0,13	0,86	0,99	0,49	0,89	0,72	0,05	0,18	0,15	0,81	0,28	0,60	0,73
FT5O	0,94	0,54	0,7	2 (0,32	0,83	0,72	0,39	0,72	0,39	0,58	3 0	,61	0,36	0,32	0,07	0,43	0,27	0,82	0,96	0,71	0,00	0,44	0,04	0,85	0,87	0,49	0,25	0,48	0,20	0,33	0,29	0,57	0,59	0,54	0,97	0,28	0,08	0,00	0,44
FT5PA	0,14	0,04	0,2	4 (0,46	0,00	0,65	0,01	0,27	0,57	7 0,12	2 0	,92	0,70	0,47	0,75	0,52	0,71	0,39	0,71	0,51	0,52	0,00	1,00	0,52	0,04	0,31	0,18	0,48	0,35	0,98	0,92	0,52	0,98	0,71	0,81	0,79	0,82	0,19	0,72
LJ250	0,93	0,27	0,8	14 (0,64	0,97	0,19	0,21	0,18	0,77	7 0,69	0	,26	0,46	0,78	0,25	0,64	0,02	0,76	0,13	0,58	0,15	0,62	0,00	0,64	0,96	0,46	0,58	0,76	0,58	0,18	0,72	0,50	0,18	0,07	0,17	0,62	0,98	0,48	0,50
LJE250	0,45	0,92	0,6	57 (0,28	0,42	0,02	0,84	0,62	0,43	3 0,94	. 0	,62	0,02	0,61	0,37	0,83	0,27	0,62	0,78	0,25	0,10	0,27	0,35	0,00	0,87	0,81	0,16	0,41	0,39	0,63	0,49	0,42	0,15	0,74	0,42	0,77	0,37	0,81	0,33
PPCOKT	0,89	0,19	0,4	10 0	0,64	0,17	0,80	0,71	0,52	0,93	3 0,84	0	,08	0,26	0,41	0,66	0,61	0,01	0,26	0,43	0,92	0,07	0,27	0,78	0,58	0,00	0,37	0,38	0,99	0,64	0,15	0,50	0,72	0,11	0,51	0,52	0,96	0,45	0,13	0,36
PPCOLI	0,60	0,70	0,5	0 0	0,44	0,60	0,61	0,12	0,57	0,57	7 0,32	2 0	,11	0,98	0,97	0,51	0,52	0,33	0,23	0,29	0,62	0,11	0,19	0,16	0,24	0,87	0,00	0,05	0,38	0,94	0,79	0,81	0,27	0,11	0,96	0,32	0,03	0,37	0,92	0,99
PPCOPF	0,05	0,14	0,5	i3 (0,88	0,08	0,22	0,58	0,54	0,02	2 0,14	0	,52	0,63	0,87	0,44	0,55	0,84	0,55	0,57	0,99	0,14	0,57	0,09	0,65	0,76	0,01	0,00	0,32	0,41	0,65	0,73	0,09	0,38	0,40	0,92	0,24	0,69	0,47	0,75
PPLJ25	0,99	0,66	0,2	19 1	0,72	0,40	0,47	0,14	0,03	0,64	4 0,30	0	,71	0,85	0,26	0,73	0,76	0,59	0,25	0,46	0,84	0,84	0,17	0,29	0,37	0,61	0,77	0,55	0,00	0,58	0,91	0,26	0,61	0,37	0,77	0,72	0,60	0,67	0,18	0,55
PPNNCOCR	0,00	0,59	0,9	14 (0,99	0,30	0,08	0,66	0,10	0,00	0,56	0	,49	0,06	0,67	0,45	0,59	0,30	0,32	0,62	0,05	0,97	0,47	0,29	0,74	0,61	0,18	0,34	0,12	0,00	0,51	0,49	0,82	0,52	0,90	0,21	0,51	0,50	0,17	0,09
PPNNCOCS	0,90	0,76	0,2	18	0,45	0,78	0,87	0,45	0,57	0,88	0,31	. 0	,21	0,56	0,68	0,08	0,83	0,05	0,91	0,03	0,64	0,67	0,40	0,13	0,70	0,23	0,26	0,09	0,60	0,10	0,00	0,62	0,24	0,23	0,78	0,57	0,15	0,06	0,85	0,43
PPNNCOIB	0,89	0,85	0,3	10 0	0,24	0,89	0,70	0,32	0,50	0,86	5 0,24	0	,54	0,67	0,70	0,07	0,24	0,88	0,23	0,08	0,15	0,82	0,49	0,37	0,75	0,38	0,88	0,90	0,29	0,45	0,49	0,00	0,17	0,98	0,43	0,44	0,26	0,15	0,80	0,78
PPNNCOPF	0,38	0,79	0,8	14 (0,34	0,84	0,16	0,18	0,08	0,73	3 0,12	2 0	,44	0,92	0,93	0,14	0,68	0,80	0,26	0,55	0,43	0,35	0,64	0,49	0,56	0,22	0,19	0,75	0,57	0,99	0,40	0,19	0,00	0,61	0,43	0,48	0,43	0,20	0,89	0,96
PPNNCORB	0,11	0,59	0,3	1 (0,39	0,52	0,56	0,30	0,27	0,26	0,55	0	,20	0,66	0,44	0,73	0,97	0,94	0,50	0,31	0,88	0,03	0,69	0,37	0,18	0,12	0,74	0,86	0,07	0,46	0,32	0,93	0,50	0,00	0,82	0,49	0,88	0,92	0,48	0,18
PPNNCOTR	0,06	0,60	0,8	15 (0,81	0,78	0,74	0,56	0,33	0,25	5 0,01	. 0	,80	0,14	0,08	0,52	0,01	0,07	0,94	0,96	0,49	0,51	0,33	0,95	0,45	0,32	0,05	0,46	0,76	0,95	0,76	0,16	0,72	0,89	0,00	0,40	0,66	0,33	0,07	0,87
PPSQ5	0,77	0,20	0,0	13 (0,21	0,61	0,02	0,13	0,12	0,19	0,06	0	,74	0,11	0,95	0,42	0,84	0,37	0,46	0,18	0,28	0,52	0,16	0,29	0,17	0,72	0,17	0,16	0,29	0,54	0,62	0,26	0,43	0,32	0,80	0,00	0,60	0,58	0,73	0,86
SV1	0,48	0,91	. 0,3	15 (0,44	0,97	0,94	0,68	0,40	0,18	3 0,78	3 0	,70	0,08	0,64	0,71	0,22	0,99	0,61	0,03	0,79	0,48	0,01	0,39	0,89	0,34	0,55	0,67	0,14	0,54	0,02	0,56	0,86	0,02	0,98	0,88	0,00	0,94	0,09	0,07
SV2	0,92	0,09	0,8	6 (0,96	0,76	0,65	0,47	0,07	0,72	2 0,26	0	,18	0,34	0,31	0,16	0,32	0,57	0,15	0,42	0,67	0,12	0,39	0,96	0,76	0,34	0,01	0,15	0,99	0,45	0,67	0,35	0,60	0,27	0,79	0,06	0,93	0,00	0,63	0,26
UTV3	0,44	0,58	0,0	14 (0,63	0,66	0,15	0,09	0,08	0,45	0,99	0	,73	0,80	0,26	0,12	0,17	0,66	0,04	0,16	0,46	0,67	0,20	0,94	0,13	0,21	0,66	0,36	0,73	0,44	0,37	0,09	0,44	0,38	0,29	0,21	0,85	0,00	0,00	0,72
UTV4	0,49	0,53	0,3	17	0,33	0,50	0,56	0,31	0,62	0,45	0,76	0	,57	0,77	0,24	0,43	0,46	0,60	0,87	0,55	0,01	0,28	0,66	0,74	0,22	0,95	0,97	0,75	0,31	0,29	0,10	0,18	1,00	0,04	0,39	0,32	0,60	0,83	0,29	0,00

Table 8: Bot Weekly demand

Demad	BCOI	KT BCC	DLI B	COPF B	DACV	BOSQ5	BV1	BV2	BV:	5 BV	5 CI	HSQ5 CS	V3 CSV4	CS.	V7 C	SV8	FGRANNEC FO	RNEC02 FT5F	C FT50	S FT5N	IO FT50) FT:	SPA L	250	LJE250	PPCOKT	PPCOLI	PPCOPF	PPLJ25	PPNNCOCF	PPNNCOCS F	PPNNCOIB PP	NNCOPF PE	PNNCORE PPN	INCOTF PPSQ	5 SV1	SV2	UTV3	UTV4
1-4		137	406	442	29	99	9 5	622	2074	449	137	1198	725	263	360	299	72	58	67	92	60	60	81	4954	128	279	50	5 42	7 2733	3 379	985	378	787	937	410	608	627	350	189
	1	34	102	111	7	2!	5 1	406	519	112	34	300	181	66	90	75	18	15	17	23	15	15	20	1239	32	70	12	6 10	7 683	3 95	246	95	197	234	103	152	157	88	47
	2	34	102	111	7	25	5 1	406	519	112	34	300	181	66	90	75	18	15	17	23	15	15	20	1239	32	70	12	6 10	7 683	3 95	246	95	197	234	103	152	157	88	47
	3	34	102	111	7	25	5 1	406	519	112	34	300	181	66	90	75	18	15	17	23	15	15	20	1239	32	70	12	5 10	7 683	95	246	95	197	234	103	152	157	88	47
	4	34	102	111	7	2!	5 1	406	519	112	34	300	181	66	90	75	18	15	17	23	15	15	20	1239	32	70	12	6 10	7 683	3 95	246	95	197	234	103	152	157	88	47

Table 9: Bot Production rates




Table 10:Bot Safety Stock

Safety Stock	всокт	BCO	LI BCOF	F BOA	CV BC	OSQ5	BV1	BV2	BV5	BV6	CHSQ5	CSV3	CSV4	CSV7	CSV8	FGRANN	NEC FORNECO2 FT5FC	FT5G	FT5M0	FT50	FT5PA	LJ250	LJE25	PPC	OKT PPCO	LI PPCC	OPF P	PLJ25	PPNNCOCI I	PNNCOCS	PPNNCOIB PI	PNNCOPI PPN	INCORE PP	NNCOTF PPSQ	5 SV1	SV2	UTV3	UTV4
units		69	203	221	15	50	2811	10	37	225	59 5	99 36	3 13	32 1	80 1	50	36 29	34	46	30	30	41	2477	64	140	253	214	1367	190	493	189	394	469	205	304	314	175	95 43

Table 11: Bot1 Changeover Matrix

Changeovers	30502 B	OSOR2 B	NOSOCH2 B	OSOPF2 BV3	BV-	CCI	12 (1	HSO2 CS	vs cs	V6 II	FU2 LI	. сн	L1750 L17	SO R	B11750 M	APA2 M	IAPN2 M	AST2 C	BCDPA2 OBC	DPN2 OB	TDST2 PPC	NACE PPI	NRE PP	NEP P	PPCNOGE PP	CNOME PPO	CNPA PPI	TCCR PPI	TCLE PP	TCPF PP	ITCAP PP	COLIZ PPI	12 PP	SO1 PP	01B PP	SO2 PPS	OR PPS	SOFC PP	SOM PPSO	OPE LIBSO:	UTSOO2	UTVS	UTV6
BOS O2	0.00	0.06	0.13	0.79	0.48	0.85	0.02	0.07	0.62	0.85	0.88	0.23	0.48	0.01	0.49	0.70	0.42	0.13	0.30	0.10	0.43	0.91	0.69	0.37	0.63	0.90	0.69	0.98	0.56	0.19	0.37	0.24	0.95	0.09	0.85	0.51	0.65	0.60			0.93 0.4		
BOSQB2	0.87		0.13	0.91	0.38	0.81	0.14	0.89	0.10	0.12	0.30	0.03	0.45	0.81	0.48	0.31	0.06	0.07	0.92	0.40	0.15	0.99	0.50	0.43		0.93	0.20	0.26	0.74	0.31	0.96	0.49	0.13	0.47	0.09	0.51	0.53	0.11			0.61 0.6		
BOSQCH2	0,53	0,27	0,00	0,48	0,77	0,70	0,27	0,03	0,01	0,57	0,16	0,13	0,14	0,82	0,14	0,55	0,33	0,25	0,06	0,79	0,48	0,21	0,66	0,90	0,39	0,37	0,08	0,54	0,93	0,92	0,98	0,41	0,30	0,10	0,21	0,89	0,76	0,13	0,29	0,93	0,80 0,7	5 0,17	0,20
BOSQPF2	0,41	0,01	0,56	0,00	0,36	0,72	0,27	1,00	0,10	0,61	0,99	0,47	0,04	0,20	0,54	0,88	0,62	0,10	0,98	0,06	0,90	0,26	0,46	0,15	0,26	0,40	0,74	0,84	0,81	0,97	0,73	0,57	0,21	0,80	0,81	0,42	0,21	0,41	0,99	0,15	0,08 0,50	6 0,83	0,88
BV3	0,97	0,68	0,01	1,00	0,00	0,79	0,41	0,09	0,93	0,61	0,01	0,88	0,07	0,72	0,02	0,11	0,88	0,12	0,52	0,21	0,02	0,38	0,66	0,21	0,55	0,34	0,76	0,12	0,58	0,32	0,31	0,93	0,94	0,27	0,04	0,38	0,83	0,65	0,86	0,58	0,74 0,45	9 0,51	0,35
BV4	0,61	0,71	0,69	0,22	0,83	0,00	0,66	0,14	0,65	0,63	0,66	0,17	0,35	0,38	0,85	0,31	0,00	0,20	0,91	0,85	0,98	0,03	0,67	0,93	0,02	0,11	0,31	0,64	0,52	0,56	0,79	0,45	0,32	0,62	0,08	0,61	0,15	0,21	0,32	0,84 0	0,08 0,2	2 0,69	0,96
CCLJ2	0,65	0,84	0,93	0,78	0,11	0,24	0,00	0,99	0,63	0,01	0,40	0,80	0,83	0,18	0,63	0,82	0,49	0,29	0,67	0,90	0,22	0,88	0,57	0,38	0,31	0,27	0,86	0,31	0,96	0,04	0,20	0,80	0,11	0,11	0,69	0,09	0,30	0,36	0,66	0,27 0	0,71 0,8	4 0,05	0,10
CHSQ2	0,10	0,45	0,95	0,56	0,63	0,06	0,99	0,00	0,01	0,83	0,72	0,16	0,78	0,35	0,19	0,30	0,86	0,83	0,57	0,01	0,64	0,52	0,63	0,30	0,89	0,14	0,41	0,50	0,32	0,66	0,86	0,20	0,43	0,54	0,31	0,52	0,92	0,76	0,09	0,68	0,8	7 0,40	0,53
CSVS	0,55	0,50	0,95	0,39	0,40	0,73	0,57	0,61	0,00	0,66	0,90	0,34	0,20	0,53	0,28	0,52	0,64	0,15	0,13	0,09	0,59	0,60	0,21	0,41	0,10	0,50	0,75	0,10	0,95	0,81	0,40	0,78	0,92	0,84	0,72	0,19	0,38	0,34	0,93	0,67	0,65 0,1	8 0,67	0,46
CSV6	0,71	0,04	0,17	0,38	0,78	0,21	0,24	0,00	0,96	0,00	0,35	0,46	0,13	0,78	0,30	0,10	0,39	0,65	0,21	0,34	0,02	0,48	0,75	0,77	0,13	0,57	0,08	0,37	0,64	0,16	0,94	0,52	0,92	0,55	0,02	0,90	0,70	0,89	0,03	0,81 (0,34 0,2		
LFLJ2	0,62	0,01	0,11	0,06	0,02	0,49	0,66	0,06	0,96	0,59	0,00	0,49	0,53	0,54	0,81	0,73	0,67	0,12	0,49	0,04	0,48	0,49	0,57	0,88	0,90	0,35	0,66	0,89	0,92	0,49	0,93	0,95	0,79	0,75	0,27	0,13	0,89	0,97	0,31	0,05	0,59 0,5		
LJ3	0,31	0,82	0,30	0,12	0,51	0,37	0,11	0,74	0,79	0,58	0,77	0,00	0,18	0,12	0,50	0,54	0,17	0,64	0,65	0,69	0,80	0,63	0,50	0,76	0,36	0,57	0,33	0,02	0,66	0,12	0,54	0,46	0,16	0,24	0,61	0,64	0,80	0,67	0,68	0,63	0,0		
CHLJ750	0,85	0,87	0,71	0,37	0,77	0,16	0,92	0,80	0,01	0,64	0,31	0,53	0,00	0,04	0,42	0,02	0,77	0,82	0,39	0,29	0,88	0,65	0,48	80,0	0,49	0,32	0,22	0,90	0,18	0,10	0,63	0,77	0,14	0,02	0,80	0,60	0,65	0,97	0,56	0,44 0	0,58 0,3		
LJ750	0,32	0,07	0,30	0,42	0,94	0,75	0,48	0,53	0,99	0,03	0,46	0,53	0,07	0,00	0,01	0,29	0,04	0,27	0,42	0,24	0,58	0,03	0,68	0,73	0,65	0,17	0,35	0,43	0,11	0,67	0,73	0,09	0,74	0,28	0,86	0,66	0,10	0,68	0,38	0,86	0,64 0,5	3 0,44	
RBLJ750	0,60		0,30	0,94	0,90	0,55	0,87	0,10	0,21	0,91	0,97	0,12	0,64	0,13	0,00	0,75	0,79	0,57	0,12	0,30	0,87	0,51	0,85	0,91	0,46	0,72	0,08	0,28	0,93	0,09	0,83	0,36	0,23	0,83	0,19	0,09	0,81	0,12	0,66	0,03 (0,91 0,2		
MAPA2 MAPN2	0,52	0,09	0,03	0,65	0,22	0,48	0,38	0,83	0,81	0,61	0,37	0,06	0,01	0,09	0,16	0,00	0,96	0,42	0,55	0,96	0,37	0,43	0,75	0,28	0,06	0,91	0,82	0,94	0,04	0,88 80.0	0,08	0,74	0,65	0,06	0,39	0,71	0,07	0,55			0,04 0,3		
MAPN2 MAST2	0,28		0,19	0,52	0,19	0,90	0.09	0,93	0,86	0,16	0,19	0,99	0.04	0,29	0,87	0,28	0,00	0,76	0,93	0,44	0,51	0,73	0,11	0,63	0,46	0,29	0,40	0,50	0,54	0,08	0.60	0,73	0,72	0,44	0,71	0,11	0,92	0,17			0.16 0.1		
ORCDPA2	0,23		0,72	0,77	0,73	0,85	0,09	0,24	0,80	0,75	0,31	0,03	0,31	0,88	0,54	0,39	0,01	0,71	0.00	0,93	0,73	0,84	0,43	0,43	0,70	0,59	0,55	0,92	0,54	0,40	0.83	0,70	0,70	0,42	0,78	0,64	0.70	0,06	0.20	0,25	0,18 0,1		
OBCDPN2	0.42		0,73	0.00	0.75	0.09	0,88	0,46	0,76	0,61	0,15	0.15	0.01	0,31	0,42	0,76	0,07	0,71	0,00	0,70	0,68	0,31	0,87	0,90	0,53	0.93	0.90	0,92	0,56	0,45	0.90	0.36	0,34	0,31	0,22	0,71	0,70	0,74	0,20	0,76	0.11 0.3		
OBCDST2	0.96		0,11	0,00	0,78	0,03	0.09	0.06	0.05	0.56	0,40	0.25	0,37	0,40	0,52	0.50	0,35	0.55	0.01	0.07	0.00	0,32	0.04	0.89	0.38	0.00	0,46	0.35	0,50	0,76	0.77	0.48	0.29	0.91	0.95	0.73	0.43	0,75		0,53	0.65 0.9		
PPCNACE	0,92		0,75	0,70	0,76	0.76	0,00	0,69	0,57	0,99	0,51	0.12	0,23	0,56	0.05	0.11	0,33	0.17	0.85	0.54	0.13	0,00	0,82	0.24	0.62	0.75	0.18	0.91	0,54	0,69	0.14	0.12	0.79	0.05	0.10	0,73	0.55	0.76		0.80	0.02 0.8		
PPCNBF	0.30		0,65	0.68	0,26	0,70	0.64	0.20	0.96	0,60	0.25	0.31	0.43	0.33	0.99	0.22	0,15	0.74	0.77	0.60	0.05	0,34	0.00	0.63	0.79	0.42	0.26	0.28	0.06	0,83	0.16	0.62	0.99	0,97	0,20	0.79	0.70	0.88	0.91		0.86 0.7		
PPCNFP	0.36	0.59	0.86	0.51	0.24	0.69	0.06	0.04	0.98	0.46	0.60	0.98	0.80	0.00	0.42	0.54	0.79	0.56	0.26	0.73	0.85	0.98	0.85	0.00	80.0	0.30	0.05	0.15	0.40	0.24	0.81	0.94	0.31	0.18	0.18	0.80	0.63	0.15	0.39	0.03	0.21 0.5	8 0.33	0.52
PPCNOGF	0.92	0.75	0.36	0.42	0.55	0.77	0.80	0.19	0.80	0.86	0.06	0.17	0.00	0.49	0.01	0.23	0.68	0.11	0.64	0.77	0.77	0.79	0.14	0.70	0.00	0.99	0.66	0.60	0.69	0.45	0.27	0.83	0.92	0.19	0.77	0.72	0.91	0.79	0.49	0.63	0.93 0.93	3 0.37	0.96
PPCNOMF	0,36	0,54	0,02	0,65	0,28	0,09	0,31	0,34	0,42	0,94	0,37	0,38	0,40	0,80	0,29	0,15	0,31	0,55	0,58	0,58	0,67	0,27	0,13	0,58	0,55	0,00	0,64	0,88	0,94	0,99	0,61	0,51	0,89	0,63	0,77	0,70	0,52	0,87	0,79	0,52	0,10 0,1	9 0,81	0,09
PPCNPA	0,32	0,60	0,47	0,91	0,95	0,93	0,21	0,28	0,13	0,27	0,98	0,48	0,97	0,10	0,08	0,30	0,79	0,12	0,71	0,56	0,09	0,78	0,39	0,78	0,05	0,65	0,00	0,47	0,77	0,01	0,66	0,81	0,16	0,35	0,96	0,56	0,56	0,56	0,61	0,95	0,77 0,6	8 0,16	0,27
PPITCCR	0,04	0,51	0,23	0,82	0,90	0,31	0,62	0,99	0,28	0,61	0,40	0,24	0,91	0,95	0,19	0,70	0,02	0,97	0,24	0,68	0,61	0,62	0,13	0,94	0,92	0,73	0,54	0,00	0,29	0,10	0,64	0,23	0,18	0,18	0,67	0,43	0,05	0,54	0,26	0,81 (0,61 0,2	6 0,51	0,92
PPITCLE	0,80	0,42	0,30	0,33	0,43	0,38	0,13	0,79	0,38	0,23	0,09	0,17	0,20	0,45	0,25	0,96	0,63	0,01	0,26	0,35	0,64	0,34	0,36	0,83	0,46	0,52	0,04	0,19	0,00	0,12	0,61	0,88	0,53	0,38	0,44	0,07	0,53	0,83	0,55	0,66	0,48 0,9	3 0,01	0,00
PPITCPE	0,94	0,98	0,96	0,75	0,97	0,54	0,95	0,07	0,94	0,57	0,45	0,55	0,02	0,48	1,00	0,06	0,52	0,85	0,15	0,71	0,77	0,77	0,41	0,46	0,52	0,43	0,64	0,68	0,87	0,00	0,64	0,03	0,42	0,25	0,50	0,76	0,39	0,36	0,08	0,34	0,44 0,3	5 0,24	0,28
PPITCAP	0,34	0,71	0,28	0,81	0,10	0,62	0,80	0,13	0,21	0,08	0,62	0,25	0,80	0,18	0,74	0,45	0,05	0,78	0,96	0,66	0,64	0,37	0,89	0,74	0,36	0,19	0,81	0,52	0,53	0,36	0,00	0,38	0,89	0,93	0,54	0,39	0,93	0,54	0,46	0,74	0,75 0,8		
PPCOLI2	0,88		0,63	0,54	0,57	0,16	0,83	0,34	0,57	0,93	0,70	0,86	0,46	0,89	0,27	0,79	0,89	0,98	0,02	0,93	0,56	0,47	0,92	0,46	0,79	0,30	0,09	0,98	0,95	0,72	0,21	0,00	0,26	0,52	0,18	0,78	0,52	0,38	0,26		0,65 0,1		
PPLJ2	0,62	0,36	0,82	0,62	0,63	0,01	0,41	0,57	0,41	0,34	0,14	0,44	0,15	0,40	0,21	0,26	0,80	0,65	0,34	0,44	0,94	0,92	0,23	0,98	0,92	0,32	0,31	0,50	0,41	0,91	0,32	0,00	0,00	0,68	0,41	0,99	0,92	0,88			0,13 0,4		
PPSQ1	0,99		0,68	0,76	0,84	0,12	0,29	0,04	0,87	0,78	0,10	0,72	0,11	0,57	0,06	0,34	0,32	80,0	0,04	0,95	0,14	0,75	0,96	0,92		0,38	0,31	0,57	0,33	0,25	0,27	0,45	0,91	0,00	0,17	0,31	0,09	0,89			0,57 0,43		
PPSQ1B	0,78		0,70	0,81	0,13	0,38	0,24	0,89	0,34	0,33	0,05	0,27	0,63	0,18	0,36	0,31	0,29	0,22	0,50	0,51	0,93	0,88	0,07	0,12	0,13	0,37	0,48	0,25	0,42	0,28	0,24	0,21	0,25	0,08	0,00	0,70	0,77	0,24			0,43 0,43		
PPSQ2	0,60		0,38	0,29	0,25	0,13	0,81	0,61	0,39	0,65	0,54	0,83	0,73	0,64	0,17	0,13	0,53	0,54	0,93	0,22	0,99	0,95	0,48	0,99	0,10	0,25	0,81	0,65	0,09	0,20	0,03	0,10	0,08	0,40	0,89	0,00	0,61	1,00			0,36		
PPSQB	0,12		0,32	0,98	0,63	0,77	0,27	0,27	0,54	0,71	0,28	0,75	0,99	0,68	0,81	0,15	0,64	0,04	0,62	0,85	0,87	0,90	0,34	0,13	0,90	0,95	0,50	0,51	0,02	0,32	0,46	0,08	0,87	0,59	0,44	0,14	0,00	0,85	0,90		0,47 0,6		
PPSQFC PPSQM	0,31		0,12	0,41	0,44	0,83	0,05	0,12	0,14	0,07	0,52	0,85	0,01	0,57	0,48	0,36	0,51	0,41	0,59	0,95	0,28	0,89	0,62	0,31	0,64	0,98	0,68	0,83	0,53	0,61	0,66	0,52	0,52	0,09	0,89	0,56	1,00	0,00			0,17 0,4		
PPSQM	0,82		0,63	0,27	0,78	0,68	0,29	0,64	0,79	0,95	0,79	0,27	0,41	0,27	0,13	0,16	0,20	0,99	0,34	0,16	0,48	0,12	0,85	0.08	0,22	0,57	0,73	0,24	0,27	0,83	0,93	0,13	0,13	0,43	0,66	0,01	0.05	0,30		0,40 0	0,00		
URSO2	0,29		0,12	0,49	0,44	0,02	0,79	0,43	0,67	0,92	0,61	0.24	0,46	0,25	0,00	0,35	0,72	0,44	0,87	0,45	0,98	0,26	0,79	0.19	0,36	0.03	0,78	0,14	0,54	0,87	0,03	0,40	0,78	0,83	0,99	0,20	0,05	0,98	0,66	0.06	0,00 0.8		0,34
UBSQ2 UTSQQ2	0,50		0,07	0,21	0,77	0,39	0,08	0,95	0,47	0,14	0,75	0.06	0,94	0.06	0,07	0,35	0,84	0,98	0.65	0.70	0,54	0,46	0,71	0,19	0,41	0,03	0,07	0,48	0,91	0,18	0,46	0,52	0,38	0,37	0,29	0,16	0,34	0,32			0.18 0.00		
UTVS	0.25	0.16		0,48	0,54	0.35	0.18	0,72	0.98	0,54	0,03	0.44	0.70	0.34	0.23	0.97	0,64	0.23	0.56	0.32	0.22	0,83	0.34	0.22	0.20	0.74	0.76	0,51	0.85	0.05	0.61	0.30	0,97	0.25	0,50	0.91	0.35	0,45			0.54 0.6		
UTV6	0,25			0.87	0,37	0.85	0,20	0.75	0,50	0,82	0.15	0.52	1.00	0.59	0,20	0,38	0,54	0,13	0.40	0,66	0,22	0,35	0,50	0.29		0,74	0,70	0,51	0,03	0,84	0.14	0,30	0,97	0.18	0,50	0,72	0.66	0.19			190 0.7		
18	0,30	0,03	0,30	2,07	4,47		2,30	4,73	2,07	3,02	3,23	-,04	2,00	4,00	3,70	2,30	2004	3,22	-,40	2,30	4,-0	4,44	2,00	-,	3,01	-,20	-,44	0,00	0,64	2,04	-,47	4,44	4,07	0,10	2,00		-,,,,,	4,40	0/40		. 0,7	. 0,04	2,00

Table 12: Bot1 Weekly Demand



Table 13: Bot1 Production Rates




Table 14: Bot1 Safety stock




Table 15: Bot2 Changeover Matrix

Changeovers	TBS200CS	TBS200NS	TBS200OS	TBS200PS	TBS200RS
TBS200CS	0,00	0,92	0,64	0,43	0,87
TBS200NS	0,62	0,00	0,26	0,80	0,97
TBS200OS	0,28	0,23	0,00	0,53	0,43
TBS200PS	0,21	0,98	0,43	0,00	0,67
TBS200RS	0,27	0,97	0,96	0,45	0,00

Table 16: Bot2 Weekly Demand

Demad	TBS200CS	TBS200NS	TBS200OS	TBS200PS	TBS200RS
1-4	1788	962	1141	658	1038
1	447	241	285	165	260
2	447	241	285	165	260
3	447	241	285	165	260
4	447	241	285	165	260

Table 17: Bot2 Production Rates

Productio Rates	TBS200CS	TBS200NS	TBS200OS	TBS200PS	TBS200RS
cases/hour	30	30	30	30	30

Table 18: Bot2 Safety Stock

Safety Stock	TBS200CS	TBS200NS	TBS200OS	TBS200PS	TBS200RS
units	894	481	571	329	519

Table 19: Bot3 Changeover Matrix

Changeovers	CHLJ500	CHR5OR	LJ500	LJE500	LFLJ500	OKLJ500	PPLJ500	RBLJ500	SDG	SDLL	SDMI	SDN	SDO	UBLJ500	UTLJ500
CHLJ500	0,00	0,73	0,74	0,68	0,97	0,78	0,42	0,80	0,47	0,57	0,97	0,80	0,29	0,31	1,00
CHR5OR	0,93	0,00	0,23	0,11	0,68	0,03	0,34	0,73	0,88	0,90	0,19	0,50	0,72	0,78	0,59
LJ500	0,85	0,55	0,00	0,51	0,99	0,62	0,47	0,88	0,29	0,29	0,79	0,82	0,71	0,57	0,38
LJE500	0,14	0,12	0,58	0,00	0,81	0,47	0,22	0,27	0,56	0,48	0,88	0,43	0,51	0,93	0,54
LFLJ500	0,72	0,28	0,73	0,05	0,00	0,12	0,02	0,92	0,36	0,73	0,96	0,24	0,93	0,40	0,05
OKLJ500	0,61	0,85	0,03	0,34	0,66	0,00	0,18	0,23	0,91	0,11	0,52	0,28	0,59	0,62	0,38
PPLJ500	0,39	0,06	0,73	0,19	0,32	0,23	0,00	0,03	0,01	0,79	0,68	0,61	0,60	0,90	0,34
RBLJ500	0,89	0,87	0,28	0,37	0,07	0,87	0,91	0,00	0,20	0,48	0,79	0,23	0,84	0,59	0,15
SDG	0,63	0,69	0,87	0,30	0,40	0,42	0,70	0,68	0,00	0,85	0,55	0,90	0,14	0,21	0,23
SDLL	0,28	0,14	0,26	0,67	0,36	0,44	0,70	0,37	0,38	0,00	0,30	0,92	0,89	0,40	0,25
SDMI	0,76	0,04	0,95	0,58	0,74	0,44	0,28	0,51	0,67	0,26	0,00	0,79	0,98	0,49	0,68
SDN	0,81	0,89	0,65	0,07	0,84	0,26	0,93	0,45	0,79	0,94	0,69	0,00	0,03	0,98	0,04
SDO	0,79	0,91	0,32	0,57	0,75	1,00	0,92	0,51	0,92	0,38	0,33	0,10	0,00	0,26	0,88
UBLJ500	0,34	0,74	0,63	0,36	0,49	0,70	0,51	0,96	0,97	0,95	0,03	0,11	0,92	0,00	0,96
UTLJ500	0,02	0,01	0,00	0,79	0,27	0,89	0,94	0,48	0,36	0,98	0,39	0,12	0,59	0,80	0,00

Table 20: Bot3 Weekly Demand

Demad	CHLJ500	CHR5OR	LJ500	LJE500	LFLJ500	OKLJ500	PPLJ500	RBLJ500	SDG	SDLL	SDMI	SDN	SDO	UBLJ500	UTLJ500
1-4	5576	16	9890	240	300	664	5393	5825	152	123	127	158	126	937	78
1	1394	4	2473	60	75	166	1348	1456	38	31	32	40	32	234	20
2	1394	4	2473	60	75	166	1348	1456	38	31	32	40	32	234	20
3	1394	4	2473	60	75	166	1348	1456	38	31	32	40	32	234	20
4	1394	4	2473	60	75	166	1348	1456	38	31	32	40	32	234	20

Table 21: Bot3 Production Rates

Productio Rates	CHLJ500	CHR5OR	LJ500	LJE500	LFLJ500	OKLJ500	PPLJ500	RBLJ500	SDG	SDLL	SDMI	SDN	SDO	UBLJ500	UTLJ500
cases/hour	92	161	92	92	92	92	92	92	184	184	184	184	184	92	184

Table 22: Bot3 Safety Stock

Safety Stock	CHLJ500	CHR5OR	LJ500	LJE500	LFLJ500	OKLJ500	PPLJ500	RBLJ500	SDG	SDLL	SDMI	SDN	SDO	UBLJ500	UTLJ500
units	2788	8	4945	120	150	332	2697	2913	76	62	64	79	63	469	39

Appendix C: The solution in Lingo

```
Model:
Sets:
!Machines/1..4/:;
!Products/1..102/:;
Bot/1..38/: r, s;
!Bot1/1..44/:;
!Bot2/1..5/:;
!Bot3/1..15/:;
Weeks/1..4/;
IJ(Bot, Bot): c;
IT(Bot, Weeks): d, p, o, v, pt, x, lp, fp;
IJT(Bot, Bot, Weeks): ct, bt;
Endsets
!Objective Function;
Min = @sum(IJT(i,j,t): ct(i,j,t) + bt(i,j,t));
!Constraints;
!2;
@for(Weeks(t):
      @sum(Bot(i): fp(i,t)) = 1);
@for(Weeks(t):
      @sum(Bot(i): lp(i,t)) = 1);
@for(IT(i,t):
      fp(i,t) \le x(i,t));
!5;
@for(IT(i,t):
      lp(i,t) \le x(i,t));
@for(IJT(i,j,t)| i #NE# j:
      o(j,t) - (o(i,t) + 1) >= -1*M*(1-ct(i,j,t)));
!7;
@for(IT(j,t):
      @sum(Bot(i) | i #NE# j: ct(i,j,t)) = x(j,t) - fp(j,t));
!8;
@for(IT(i,t):
      @sum(Bot(j) | i #NE# j: ct(i,j,t)) = x(i,t) - lp(i,t));
!9;
@for(IT(j,t)| t #NE# 4:
      \operatorname{@sum}(\operatorname{Bot}(i):\operatorname{bt}(i,j,t)) = \operatorname{fp}(j,t));
!10;
@for(Bot(i):
      @sum(Bot(j): bt(i,j,1)) = 0);
@for(Bot(i):
      @sum(Bot(j): bt(i,j,2)) = lp(i,1));
@for(Bot(i):
      @sum(Bot(j): bt(i,j,3)) = lp(i,2));
!11;
@for(IT(i,t):
      O(i,t) \le M*x(i,t));
@for(IT(i,t):
```

```
fp(i,t) >= o(i,t));
@for(IT(i,t):
      o(i,t) \le @sum(Bot(k): x(k,t)));
!13;
@for(IT(i,t):
      a*x(i,t) >= pt(i,t));
@for(IT(i,t):
      pt(i,t) \le z*x(i,t));
!14;
@for(Weeks(t) | t #NE# 4:
      @sum(Bot(i): pt(i,t)) + @sum(IJ(i,k) : ct(i,k,t) + bt(i,k,t)*c(i,k)) <=
z);
!15;
@sum(Bot(i): pt(i,1)) + @sum(IJ(i,k) :ct(i,k,1)*c(i,k)) \le z;
!16;
@for(IT(i,t):
     p(i,t) = r(i) * pt(i,t));
!17;
@for(Bot(i):
      v(i,1) = p(i,1) - d(i,1);
@for(Bot(i):
      v(i,2) = v(i,1) + p(i,2) - d(i,2);
@for(Bot(i):
      v(i,3) = v(i,2) + p(i,3) - d(i,3);
@for(Bot(i):
      v(i,4) = v(i,3) + p(i,4) - d(i,4));
!18;
@for(IT(i,t):
     v(i,t) >= s(i));
!Binary;
@for(IT(i,t):
      @bin(x(i,t)));
@for(IT(i,t):
      @bin(lp(i,t)));
@for(IT(i,t):
      @bin(fp(i,t)));
@for(IJT(i,k,t):
      @bin(ct(i,k,t)));
@for(IJT(i,k,t):
      @bin(bt(i,k,t)));
Data:
C =
                                                           0.55 0.06
      0.75
           0.14 0.21 0.08 0.07 0.55 0.84 0.32 0.37
\cap
                 0.21 0.22
                                         0.54 0.11
                                                     0.65 0.59 0.13
      0.67
           0.67
                             0.23 0.9
      0.84
           0.49
                 0.31 0.29
                             0.99
                                   0.83
                                         0.3
                                                0.13
                                                     0.1
                                                           0.52
                                                                 0.36
      0.61 0.06 0.81 0.35
0.95
     0
            0.9
                  0.02 0.67
                             0.97
                                   0.72
                                         0.03 0.36
                                                     0.81
                                                           0.93 0.89
      0.72
           0.16
                 0.74 0.98
                             0.06
                                   0.03
                                         0.2
                                                0.21
                                                     0.06 0.35 0.64
      0.01
           0.15
                 0.86 0.66
                             0.11
                                   0.78
                                         0.17
                                               0.86
                                                     0.9
                                                           0.06 0.77
      0.86 0.7
                  0.49 0.02
0.73 0.81
                  0.11 0.26
                             0.43
                                   0.85
                                         0.83
                                               0.02
                                                     0.68
                                                           0.82
                                                                 0.25
           Ω
      0.97
           0.98
                 0.19
                       0.26
                             0.98
                                   0.24
                                         0.49 0.84
                                                     0.31
                                                           0.46
      0.77
           0.75
                 0.43
                       0.17
                             0.27
                                   0.05
                                         0.18 0.18
                                                     0.59
                                                           0.13
      0.86 0.51
                 0.96 0.65
                       0.19
0.21
     0.12
           0.83
                 0
                             0.57
                                   0.88
                                         0.69
                                               0.2
                                                     0.45
                                                           0.62
                                                                 0.26
      0.94
           0.12
                 0.41 0.14
                             0.67
                                   0.82
                                         0.52
                                               0.75
                                                     0.21
                                                           0.04
                                                                 0.05
      0.04 0.22
                  0.37 0.24
                             0.09 0.42
                                         0.48 0.07
                                                     0.26
                                                           0.07
                                                                 0.67
      0.28 0.62 0.98 0.79
```

0.39	0.57 0.86 0.02 0.71	0.6 0.85 0.03 0.86	0.48 0.48 0.74 0.25	0 0.39 0.64 0.75	0.73 0.14 0.89	0.58 0.95 0.84	0.68 0.06 0.97	0.04 0.75 0.57	0.8 0.15 0.54	0.68 0.45 0.77	0.92 0.93 0.8	
0.69	0.69 0.61 0.46 0.86	0.1 0.37 0.49 0.58	0.91 0.06 0.18 0.99	0.86 0.46 0.3 0.01	0 0.75 0.41	0.71 0.36 0.47	0.09 0.92 0.44	0.94 0.8 0.26	0.52 0.72 0.33	0.84 0.09 0.21	0.41 0.51 0.3	
0.97	0.68 0.63 0.75 0.46	0.73 0.3 0.96 0.9	0.23 0.06 0.46 0.26	0.73 0.89 0.54 0.06	0 0.83 0.76	0 0.28 0.95	0.08 0.67 0.83	0.69 0.66 0.84	0.51 0.58 0.68	0.89 0.15 0.74	0.07 0.63 0.18	
0.13	0.78 0.17 0.99 0.68	0.4 0.44 0.35 0.87	0.71 0.2 0.05 0.82	0.45 0.97 0.23 0.85	0.36 0.4 0.81	0.65 0.61 0.12	0 0.73 0.65	0.4 0.06 0.28	0.2 0.2 0.52	0.39 0.27 0.64	0.04 0.81 0.73	
0.5	0.24 0.86 0.62 0.57	0.34 0.12 0.83 0.32	0.61 0.9 0.58 0.51	0.99 0.89 0.58	0.04 0.2 0.27	0.26 0.7 0.37	0.06 0.33 0.86	0 0.44 0.1	0.86 0.08 0.25	0.26 0.3 0.19	0.3 0.35 0.43	0.6
0.29	0.98 0.23 0.58 0.84	0.41 0.59 0.55 0.37	0.94 0.83 0.06 0.88	0.01 0.17 0.21	0.55 0.3 0.01	0.32 0.76 0.58	0.8 0.19 0.87	0.02 0.82 0.89	0 0.74 0.38	0.69 0.72 0.45	0.99 0.24 0.03	0.6
0.33	0.65 0.58 0.72 0.84	0.41 0.82 0.06 0.85	0.82 0.49 0.85 0.51	0.35 0.68 0.38	0.55 0.23 0.35	0.62 0.32 0.21	0.21 0.01 0.84	0.06 0.07 0.55	0.05 0.59 0.7	0 0.56 0.5	0.63 0.26 0.15	0.9
0.24	0.92 0.81 0.95 0.62	0.82 0.62 0.24 0.89	0.45 0.32 0.93 0.7	0.07 0.03 0.21 0.57	0.72 0.34 0.48	0.45 0.69 0.13	0.35 0.74 0.15	0.3 0.75 0.04	0.38 0.72 0.31	0.98 0.3 0.69	0 0.07 0.78	
0.18	0.17 0.08 0.56 0.39	0.34 0.85 0.47 0.99	0.31 0.81 0.77	0.84 0.07 0.4	0.05 0.32 0.03	0.12 0.08 0.1	0.46 0.91 0.73	0.43 0.37 0.63	0.01 0.22 0.97	0.68 0.09 0.7	0.78 0.47 0.5	0
0.77	0.15 0.42 0.28 0.46	0.83 0 0.2 0.33	0.47 0.31 0.19 0.75	0.1 0.01 0.67 0.1	0.97 0.02 0.28	0.88 0.51 0.3	0.27 0.82 0.39	0.14 0.6 0.85	0.06 0.56 0.46	0.5 0.72 0.46	0.4 0.2 0.55	
0.91	0.02 0.48 0.93 0.26	0.62 0 0.26 0.4	0.58 0.58 0.96 0.66	0.05 0.45 0.1	0.83 0.33 0.98	0.87 0.72 0.21	0.2 0.29 0.92	0.65 0.87 0.86	0.28 0.89 0.8	0.55 0.01 0.49	0.26 0.83 0.52	0.4
0.03	0.59 0.85 0.97 0.32	0.7 0.28 0.1 0.8	0.63 0 0.67 0.22	0.35 0.84 0.63	0.31 0.53 0.57	0.08 0.23 0.23	0.42 0.37 0.82	0.97 0.55 0.5	0.38 0.45 0.59	0.28 0.78 0.22	0.8 0.96 0.17	0.3
0.98	0.62 0.16 0.52 0.22	0.49 0.37 0.38 0.57	0.15 0.07 0.83 0.48	0.76 0.99 0.06 0.64	0.92 0 0.43	0.83 0.81 0.05	0.88 0.76 0.05	0.83 0.92 0.84	0.07 0.94 0.18	0.62 0.82 0.76	0.9 0.09 0.33	
0.73	0.05 0.43 0.76 0.58	0.26 0.38 0.89 0.12	0.77 0.83 0.4 0.58	0.44 0.53 0.98 0.13	0.72 0.55 0.54	0.77 0 0.3	0.51 0.61 0.23	0.52 0.19 0.01	0.51 0.73 0.41	0.39 0.43 0.26	0.64 0.9 0.52	
0.49	0.57 0.14 0.08 0.98	0.07 0.36 0.41 0.76	0.97 0.06 0.82 0.75	0.28 0.99 0.39	0.69 0.05 0.31	0.47 0.64 0.79	0.96 0 0.58	0.14 0.98 0.63	0.11 0.52 0.78	0.38 0.1 0.25	0.8 0.77 0.12	0.3

0.6	0.17 0.77 0.26 0.91	0.6 0.84 0.12 0.84	0.69 0.98 0.11 0.24	0.86 0.81 0.09 0.29	0.68 0.06 0.7	0.79 0.5 0.21	0.76 0.42 0.03	0.55 0 0.39	0.47 0.53 0.62	0.84 0.25 0.2	0.05 0.79 0.76	
0.77	0.48 0.47 0.86 0.06	0.12 0.44 0.23 0.23	0.24 0.91 0.77 0.62 0.04	0.34 0.49 0.35 0.78	0.28 0.61 0.87	0.47 0.42 0.8	0.33 0.49 0.4	0.55 0.58 0.35	0.28 0 0.08	0.21 0.79 0.12	0.26 0.13 0.57	
0.27	0.68 0.02 0.79 0.11	0.61 0.87 0.35 0.05	0.37 0.07 0.97 0.05	0.87 0.61 0.53	0.89 0.55 0.23	0.17 0.36 0.46	0.23 0.64 0.86	0.12 0.43 0.91	0.81 0.32 0.07	0.01 0 0.35	0.37 0.93 0.04	0.5
0.35	0.3 0.49 0.89 0.19	0.57 0.64 0.53 0.63	0.12 0.97 0.79 0.58	0.74 0.62 0.42 0.16	0.59 0.56 0.75	0.67 0.95 0.93	0.04 0.87 0.02	0.73 0.16 0.62	0.43 0.89 0.5	0.66 0.08 0.98	0.1 0 0.55	
0.36	0.84 0.88 0.25 0.68	0.6 0.96 0.62 0.65	0.06 0.01 0.88 0.66	0.25 0.14 0.37	0.89 0.53 0.5	0.6 0.78 0.24	0.29 0.17 0.74	0.87 0.54 0.72	0.7 0.62 0.29	0.78 0.54 0.62	0.83 0 0.51	0.3
0.27	0.08 0.95 0.33 0.96	0.63 0.27 0 0.29	0.3 0.16 0.71 0.18	0.87 0.93 0.01 0.31	0.95 0.79 0.38	0.81 0.31 0.22	0.27 0.31 0.13	0.93 0.48 0.91	0.44 0.3 0.93	0.73 0.01 0.47	0.69 0.43 0.16	
0.37	0.66 0.06 0.66 0.63	0.44 0.44 0.31 0.59	0.03 0.06 0 0.24	0.56 0.43 0.94 0.26	0.03 0.55 0.82	0.39 0.17 0.45	0.41 0.95 0.47	0.43 0.92 0.41	0.21 0.45 0.74	0.01 0.51 0.74	0.43 0.84 0.81	
0.34	0.58 0.67 0.34 0.73	0.82 0.48 0.37 0.18	0.72 0.44 0	0.84 0.44 0.8	0.36 0.23 0.52	0.09 0.64 0.23	0.8 0.17 0.68	0.5 0.37 0.18	0.2 0.33 0.46	0.76 0.72 0.98	0.75 0.08 0.26	0.8
0.21	0.24 0.98 0.56 0.51	0.61 0.94 0.97 0.46	0.11 0.94 0.43 0.02	0.87 0.79 0.3 0.81	0.64 0.5 0	0.18 0.82 0.38	0.84 0.12 0.73	0.49 0.25 0.55	0.41 0.02 0.51	0.03 0.5 0.79	0.39 0.11 0.02	
0.03	0.75 0.22 0.05 0.88	0.06 0.91 0.75	0.88 0.07 0.74 0.32	0.85 0.07 0.94 0.71	0.38 0.17 0.96	0.79 0.39 0	0.46 0.86 0.62	0.95 0.81 0.36	0.21 0.55 0.75	0.94 0.65 0.28	0.39 0.91 0.39	
0.85	0.85 0.11 0.03 0.34	0.3 0.95 0.69 0.83	0.76 0.45 0.68 0.24	0.66 0.35 0.17 0.24	0.01 0.92 0.12	0.5 0.29 0.62	0.09 0.39 0	0.96 0.87 0.67	0.89 0.36 0.67	0.4 0.5 0.91	0.77 0.75 0.64	
0.31	0.43 0.54 0.17 0.08	0.48 0.84 0.43 0.53	0.86 0.5 0.08 0.7	0.03 0.08 0.92 0.83	0.42 0.49 0.8	0.95 0.66 0.84	0.2 0.91 0.3	0.1 0.84 0	0.27 0.4 0.56	0.63 0.27 0.18	0.76 0.41 0.62	
0.86	0.46 0.81 0.15 0.85	0.18 0.32 0.62 0.58	0.15 0.45 0.78 0.09	0.57 0.63 0.02 0.73	0.83 0.69 0.33	0.76 0.23 0.31	0.2 0.22 0.58	0.93 0.56 0.62	0.45 0.79 0	0.22 0.47 0.2	0.15 0.45 0.17	
0.53	0.94 0.28 0.58 0.05	0.78 0.66 0.73 0.08	0.46 0.79 0.61 0.19	0.6 0.36 0.18 0.24	0.63 0.25 0.25	0.52 0.45 0.03	0.17 0.04 0.07	0.5 0.79 0.34	0.15 0.54 0.06	0.71 0.75 0	0.38 0.23 0	
0.08	0.2 0.36 0.29 0.96	0.08 0.4 0.8 0.11	0.6 0.02 0.35 0.51	0.02 0.81 0.85	0.38 0.63 0.14	0.99 0.9 0.19	0.87 0.76 0.06	0 0.55 0.56	0.5 0.05 0.65	0.41 0.39 0.12	0.35 0.84 0	0.5

```
0.72 0.32 0.19 0.29 0.29 0.75 0.99 0.05 0.58 0.85 0.68 0.77
     0.35 0.26 0.98 0.14 0.62 0.98 0.91 0.76 0.02 0.18 0.62 0.3
     0.71 0.86 0.08 0.11 0.91 0.56 0.41 0.17 0.92 0.89 0
     0.11 0.96 0.7
0.64 0.64 0.11 0.4 0.02 0.77 0.22 0.6 0.82 0.5
                                                       0.53 0.61
     0.55 0.09 0.16 0.8 0.67 0.8 0.19 0.29 0.26 0.52 0.87
     0.48 0.23 0.22 0.24 0.72 0.61 0.6 0.09 0.36 0.37 0.11
     0.68 0 0.05 0.14
0.35 0.77 0.21 0.67 0.9 0.62 0.43 0.05 0.06 0.85 0.81 0.83 0.7
     0.3
           0.11 0.49 0.01 0.4 0.63 0.83 0.95 0.96 0.73 0.06
     0.43 0.69 0.16 0.68 0.77 0.61 0.34 0.09 0.55 0.64 0.56
     0.71 0 0.24
0.43 0.55 0.72 0.62 0.53 0.72 0.79 0.24 0.57 0.54 0.49 0.52
     0.98 0.1 0.58 0.92 0.27 0.08 0.35 0.98 0.82 0.02 0.87
     0.79 0.77 0.72 0.4 0.39 0.48 0.26 0.25 0.6 1
                                                             0.53 0
     0.43 0.62 0.00;
d =
           111 7
                      25
                            1406 519
                                            34
                                                  300
                                                        181
                                                              66
34
     102
                                       112
                                                                   90
               15
                                                  1239 32
                           23
                                       15
                                                                   126
           18
                      17
                                 15
                                             20
                                                              70
     75
                      246 95
                                            103
               95
     107
                                 197
                                       234
                                                  152
                                                        157
           683
                                                              88
                                                                   47
     22
                7
                      25
                            1406 519
34
     102
           111
                                       112
                                             34
                                                  300
                                                        181
                                                              66
                                                                   90
                            23
                                                  1239 32
     75
           18
                15
                      17
                                 15
                                       15
                                             20
                                                              70
                                                                   126
     107
           683
                95
                      246
                            95
                                 197
                                       234
                                             103
                                                  152
                                                        157
                                                              88
                                                                   47
     22
                7
34
     102
           111
                      25
                            1406 519
                                       112
                                             34
                                                  300
                                                        181
                                                              66
                            23
     75
           18
                15
                      17
                                 15
                                       15
                                            20
                                                  1239 32
                                                              70
                                                                   126
     107
           683
                95
                      246
                            95
                                 197
                                       234
                                             103
                                                  152
                                                        157
                                                              88
                                                                   47
     22
34
     102
           111
                7
                      25
                           1406 519
                                       112
                                            34
                                                  300
                                                        181
                                                              66
               15
                            23
           18
     75
                      17
                                 15
                                       15
                                            20
                                                  1239 32
                                                             70
                                                                   126
     107
           683
               95
                      246
                          95
                                 197
                                       234
                                           103
                                                  152
                                                        157
                                                             88
                                                                   47
     22;
r =
0.0119 0.0119 0.0109 0.0125 0.0119
     0.0119 0.0125 0.0125 0.0125 0.0119 0.0119

      0.0125
      0.0125
      0.0222
      0.0222
      0.0278
      0.0278

      0.0278
      0.0278
      0.0278
      0.0109
      0.0109
      0.0119

      0.0119
      0.0119
      0.0109
      0.006
      0.006
      0.006
      0.006

     0.006 0.0125 0.0109 0.0109 0.0119
                                                       0.0119;
s =
                     50 2811 1037 225 69 599
           221 15
                                                        363
69
     203
                                                            132 180
           36
                          46
                                30 30 41
                                                 2477 64
     150
                29
                     34
                                                             140 253
           1367 190 493 189 394 469 205 304 314 175 95
     214
     43;
a = 91;
z = 125;
M = 100000;
Enddata
```

End