Location Name: Khalifa University, Building No D100	Description of Task/Activity/Area/Premises etc.: Assembly Work

SN	Step 1	Step 2	Step 3					Step 4					
	Hazard	Who might be at risk	Risk Rating			What have you already been doing (List all the Control measure already in place)	Control Measure (Refer to Hierarchy of Control) What further action, if any, is necessary, if so what Action is to be taken by whom and by when?	Actions and Implementation			Residual Risk		
			Probability (P)	Severity (S)	Rating (P X S)			Action Whom	Action By When	Done %	Probability (P)	Severity (S)	Rating (P X S)
1	**Bad Housekeeping:** Slips trips and Falls	Workers/ Visitors	2	3	6	• Proper PPE. • Proper Housekeeping.	• Walkways to be provided and kept it Clean. • 5S to be maintained and will be evidenced.	Supervi sor	-	-	1	3	3
2	**Gas Cutting:** Fire Hazard	Workers	2	4	8	• Proper PPE. • Experienced Personnel. • Proper Fire Extinguisher.	• Educate Gas Cutting Safety Procedure. • Fire Blanket.	Safety Officer	-	-	1	4	4
	Explosion	Workers/ Visitors	2	4	8	• Proper Isolation. • All cylinders are in secured.	• Educate Gas Cutting Safety Procedure.	Safety Officer	-	-	1	4	4
	Damaged or Leaking Cylinder or Hoses.	Workers/ Visitors	2	3	6	• Inspect the Cylinders & Hoses before start Working. • Monitor a Gas Condition.	• Inspect cylinders & Hoses before working and it will be Recorded. • Educate Gas Cutting Safety Procedure.	Supervi sor/ Safety Officer	-	-	1	3	3

3	**Hand Drilling:** Electrical Shock	Operators	3	4	12	• Check Surroundings & Plugs Before Use. • Check Hidden/Buried cables before Drilling.	• Qualified Persons to test all Portable Electrical tools 6 Months Once.	Supervi sor	-	-	1	4	4
	Flying Debris, Swarf etc	Operators/ Visitors	2	4	8	• Wear Protective eye wear or Face Shield. • Advice Nearby persons of Hazards. • Wear Protective Gloves If Necessary	• Educate OCP of Hand Drilling to Workers. • Isolate areas with barriers or Tapes if necessary	Supervi sor/ Safety Officer	-	-	1	4	4
	Noise or Hearing Damage	Operators/ Visitors	2	4	8	• Wear Hearing Protection. • Advice Nearby persons of Hazards.	• Educate OCP of Hand Drilling to Workers.	Safety Officer	-	-	1	4	4
	Hand or Arm Vibration	Operators	2	4	8	• Select Power tools with lowest Vibration Levels. • Restrict a Use of Vibration Inducing tool for recommended times. • Ensure tools are properly stored, Maintained and Tested.	• Arrange Health Surveillance for those affected for Vibration. • Educate OCP of Hand Drilling to Workers.	Supervi sor/ Safety Officer	-	-	1	4	4
	Dust	Operators/ Visitors	3	3	9	• Use Dust Mask. • Wear Close Fitting Safety Goggles. •Stop working if Visibility noticeably reduced. • Clean work area Regularly. (E.g Sweep, Vacuum.	• Arrange Health Surveillance for those affected for Eye and Skin Irritation. • Increase Ventilation area if Possible.	Supervi sor/ Safety Officer	-	-	2	3	6

4	**Manual Handling:** Fall of Object	Operators/ Helpers	3	4	12	• Best working practices to be adopted • Work Instructions/signs. • Proper PPE.	• Training and Awareness • Supervision & Monitoring of the Activity	Supervisor	-	-	1	4	4
	Stress/Strain While Lifting	Operators/ Helpers	3	3	9	• Work Instructions/signs • Training & Awareness on Kinetic techniques to personnel • First Aid Kit Mandatory.	• Arrange Health Surveillance for those affected for Persons.	Supervisor	-	-	2	3	6
	Slip / Trips / Fall	Operators/ Helpers	3	4	12	• Proper PPE. • Proper Housekeeping.	• Pre-inspection to remove the objects causing slip, trip & fall. • Proper Housekeeping & Cleanliness practices	Supervisor/ Safety Officer	-	-	1	4	4
5	**Use Of Hand Tools for Assy** Contact with Sharp Edges	Operators/ Helpers	3	4	12	• Guarding the Sharp edges. • Monitoring the Activity. • Cover with aprons, Face Shields and Gloves.	• Educate with OCP Handling of Sharp edges. • Supervisor Monitoring the Activity.	Supervisor	-	-	1	4	4
	Improper Selection of Tools	Operators/ Helpers	2	4	8	• No activity to be performed until proper tools are provided • Replace the tool with proper quality tool	• Operational control procedures for hand tools shall be adhered	Store keeper	-	-	1	4	4
	Leak/ spillage	Operators/ Visitors	3	4	12	• Monitoring of the Activity •Clean-up of spill/leak	• Bund wall • Emergency Preparedness and Response plan in place	Maintenance/ Safety Officer	-	-	1	4	4

6	**Electrical Commissioning:**	Operators/ Visitors	4	4	16	• Insulation of electrical equipment/guards • Only Authorized Personnel to perform electrical task • PPE to be worn and care taken to prevent slips and trip. • Wiring, cable and cord sets must be of the recommended capacity • Do not operate with wet hands, in wet or damp areas and avoid inclement weather. If operating a power tool in damp conditions is unavoidable, use a ground fault circuit interrupter protected supply. • Use of proper PPE	• Ensure hand & power tools are properly insulated • Emergency Preparedness and Response Plan in place • Follow appropriate guidelines and control measures	Maintenance/ Safety Officer/ Supervisor	-	-	1	4	4
7	**Unwanted Activities:**	Operators/ Visitors	3	4	12	• Warning Signs • Awareness to Personnel • Fire Protection system in place	• Emergency Preparedness and Response Plan in place • Fine system in case of violation	Supervisor/ Safety Officer	-	-	1	4	4
	Step 5 : 05/ 10/ 2022 **Review Date: 10/ 10/ 2022**					• Review your assessment to make sure you are still improving, or at least not sliding back. • If there is a significant change in your workplace, remember to check your risk assessment and when necessary amend it.							

Conducted by: **Aswin Angel. A.**
(Signature over printed Name)

Endorsed by: **Ramesh Paneer Selvam**
(Signature over printed Name)

Approved by: **Mr. Kamaljit Singh Saini**
(Signature over printed Name)

SAI TECH INDUSTRIES FZCO
P. O. BOX 19283
Jebel Ali Free Zone
Dubai UAE

PROBABILITY	SEVERITY				
	Insignificant (1)	Minor (2)	Moderate (3)	Major (4)	Catastrophic (5)
Rare (1)	1	2	3	4	5
Possible (2)	2	4	6	8	10
Likely (3)	3	6	9	12	15
Often (3)	4	8	12	16	20
Frequent/Almost Certain (5)	5	10	15	20	25

15 - 25	Extreme Risk	Absolutely Unacceptably High Activity or industry should not proceed in current form
8 - 12	High Risk	Unacceptably High Activity or industry should be modified to include remedial planning and action and be subject to detailed HSE assessment
4 – 6	Moderate Risk	Acceptable but must be managed at "As Low As Reasonably Practicable" (ALARP) Activity or industry can operate subject to management and / or modification
1 - 3	Low Risk	Acceptable without required further action No action required unless escalation of risk is possible

Hierarchy of Control (Controls identified may be a mixture of the hierarchy in order to provide minimum operator exposure)

Elimination	Eliminate the hazard.
Substitution	Provide an alternative that is capable of performing the same task and is safer to use.
Engineering Controls	Provide or construct a physical barrier or guard or technical measures
Administrative Controls	Develop policies, procedures practices and guidelines, in consultation with employees, to mitigate the risk. Provide training, instruction and supervision about the hazard.
Personal Protective Equipment	Personal equipment designed to protect the individual from the hazard.

Risk Score Timeframe	High =24 hours	Low =28 days
Extreme =Immediately	Moderate =14 days	Negligible =Not applicable