جامعة خليفة
Khalifa University

SECTION 1. PERMIT REQUEST		Permit No. 042/ 2022 SAN
Date: 20/07/2022		Work Order No.
Exact Location: ROOF Of ARZAHNA BUILDING SAN CAMPUS		Procedures/ Checklist:
Equipment to be worked on: Welding machine		Method Statement/ Risk Assessment: Attached
Description of Work: waterproofing for two points on the top roof Building		
Contractors Contact Details: WHITE CRESCENT		Starting Expectations: 20-07-2022- 8:30 AM
Name: ZIAD JALLOUL	Phone No.: 0556088969	Ending Expectations: 23-07-2022- 17:00 PM
Job Originator Name: Mr. Vengadessane	Sec/Dept: FMS	Signature:

SECTION 2. HAZARDS ASSESMENT, PRECATIONS AND APPROVALS

A. Hazards Identified		B. Work Site Precautions		C. Personal Protective and safety Equipment	
Working after daylight	☐	Combustible gas test	☐	Face Shield	☐
Liquid/Gas Under Pressure	☐	H_2S test/monitoring	☐	Gloves (specify)	☑
Toxic Materials/H_2S	☐	O_2 test	☐	Goggles	☑
Corrosive Materials	☐	Cover Catchment Basin /Drain/Vents	☐	Standard PPE (Helmet, boots, coveralls, Safety Glasses)	☑
Flammable Materials	☑				
Electricity	☐	Adequate Lighting	☐	Safety Harness	☐
Moving Machinery	☐	Environmental	☐	Communication Means	☑
Lifting Operation	☐	Lifting Tackle	☐	Dust Mask	☑
Weather Condition	☑	Equipment inspection	☐	Welder's Suit	☐
Ventilation	☐	Scaffolding/staging	☐	**D. Additional Certificates/Permits**	
Falling	☐	Fire Watcher	☑	Electrical PTW	☐
Confined Space	☐	Suitable access/egress	☐	Hot PTW	☑
Water Flushed	☐	Barriers & signs	☑	Confined Space PTW	☐
Water Steamed	☐	Pressurized fire hose	☐	Mechanical PTW	☐
Steam	☐	Fire Extinguisher (type)	☑	**E. Approval**	
Noise	☐			Security Personnel: Signature: _____	
		Adjacent/Associated Work (Define)……	☐		

SECTION 3. GAS TESTING REQUIREMENTS Not applicable

I have examined the above equipment at _____ AM/PM & observed the reading to be:
Combustible: ____% Hydrogen Sulphide: _____ ppm Oxygen: _____% Other: (Name):____ ppm
Gas Tester's Signature: _____

Agreement: I have checked both the permit and the job. I understand the nature and the extent of the work and I the precautions to be followed in completing the work Sign: ....

Permit Issued by: Mr.Ahammed Basheer/Mr. Sultan Job Title: Lab's safety senior specialist Time: 9:00 AM

Received By: Mr. Umar Farooq Job Title HSE Engineer. Time: 9:05 AM

Permit Sign Off			
	Work Complete:	Job Title:	Time:
	For Permit Issuer:	Job Title:	Time:
	Work Not Complete:	Job Title:	Time:

Note: This permit is automatically suspended in case of emergency, at the end of the working day, or if the conditions mentioned in this permit change. On suspension, the permit must be returned to the Permit Office.

All Safe Work Permits must be signed by Both the Permit Receiver and Permit Issuer before work is conducted and after it is completed

جامعة خليفة
Khalifa University

PERMIT VALIDITY/EXTENTION							
Day:	SUN	MON	TUE	WED	THUR	FRI	SAT
Date:							
Contractor:							
Security Section:							
Facility Section:							
Time of Issue:							

GUIDELINES ON HOW TO COMPLETE THE COLD WORK PERMIT

1) The Facility Section Engineer/ Contractor requesting the permit should complete Section (1) of the permit.
2) Section (2 A, B, C & D) of the permit shall be completed and signed by the Facility Section personnel responsible of the work to be performed. The Security Section will also identify in Section (3) the authorized Gas Testers who are to undertake the gas testing (KU Employee).
3) Section (3) combustible gas, hydrogen sulphide and oxygen tests shall be conducted by a certified and authorized Gas Tester (GT) **other than the Contractor**, as required by the Security Section and the results entered into Section(3). For Confined Space Entry, the results shall be entered on the certificate itself.
4) The Facility Section Engineer, declaring that he has personally checked the work requirement and precautions identified by Facility Section, approves work to proceed, specifying the date and start time of work.
5) The Contractor shall also sign stating that he will abide the conditions and precautions stated in the permit and that he will conduct a TBT immediately before commencing the work. A TBT must to be conducted by the Contractor prior to starting work each day and on shift changes.
6) A CWP has a total duration of 7 days provided that the permit conditions remain unchanged, and that the precautions are acceptable for the job to continue safely. If the conditions changed a new CWP should be issued.
7) The Contractor must return the original copy of the permit daily to the Security & Facility Division Officer to obtain the initials of Security Section and Facility Section for extension. Repeat gas testing (if required by the Security Section) must be conducted prior to extending the permit with the results being registered on the reverse page of PTW.
8) Permit Cancellation/ Close-out shall be signed by Contractor/Facility Section Engineer declaring that the work has been properly performed and the worksite has been left in tidy and safe condition. If work is incomplete they shall specify its condition. In all cases the Contractor's copy (Original) is to be returned to the Security & Facility Division.
9) The Facility Section will check the site confirming that the worksite is left in a safe and tidy condition, ensures that Permit has been registered and logged in PTW Record Register, and signs permit cancellation/ close-out.
10) Finally, the Security Section will ensure that related certificate(s)/ permit(s) (Confined Space Entry certificate) are closed or remain in place. He ensures that all inhibits are re-instated, and signs the permit cancellation/ close-out.

Copies of this document available in KU EHS Intranet are only the latest, valid and controlled documents. All other copies are uncontrolled and valid only on the date printed. Last printed: 20/7/2022 9:37:00 AM