DYNAMIXEL FOR UNITY



Hello Dynamixel - 1

DynamixelForUnity
Tutorial and Learning Materials

Agenda

- 1. Introduction to Dynamixel Servomotors
 - a. What is a Dynamixel servomotor
 - b. Control Methods for Dynamixel Servomotors
 - c. Basic overview of available motors
- 2. PC Connection and Power Supply
 - a. Main Components for using Dynamixel Servomoters
 - b. Connecting to PC and Power Supply
- 3. Integration with Unity3D
- 4. Value of DynamixelForUnity
- 5. About this series of tutorials

1. Introduction to Dynamixel Servomotors


What is a Dynamixel Servomotor

Dynamixel: A Smart Actuator Brand by ROBOTIS

- All-in-One Module
- Multiple control modes

including position, velocity, and current.

Easy Operation




Control Methods for Dynamixel Servomotors

Set/Get methods

- GroupSync methods

GroupBulk methods



Basic overview of available motors

Protocol 1.0



Protocol 2.0



DYNAMIXEL FOR UNITY



Basic overview of available motors

X Series

- Wide range of prices and performances.
- Versatile choice suitable for various applications.



P Series

- High-performance, high-end series.
- Ideal for demanding applications, despite the higher cost.



2. How to connect your Dynamixel Motor?


- 1. Dynamixel servomotor
- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)

1. Dynamixel servomotor

- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)



- 1. Dynamixel servomotor
- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)



- 1. Dynamixel servomotor
- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)



- 1. Dynamixel servomotor
- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)



- 1. Dynamixel servomotor
- 2. 3-pin TTL or 4-pin RS-485 cables
- 3. U2D2 (USB serial interface)
- 4. SMPS (Power supply)
- 5. SMPS2Dynamixel (Power supply)



Connecting to PC and Power Supply

All cable connections and disconnections must be made after the power is **turned off.**




Connecting to PC and Power Supply(using U2D2 Power Hub Board)


All cable connections and disconnections must be made after the power is **turned off.**



3. Dynamixel Control from Unity3D

Download Unity Editor





- 1. Easy Integration in Under 5 Minutes
- 2. Unified Control for Multiple Motors
- 3. Abstraction of Low-Level Functionalities
- 4. Efficient and Optimized Performance

1. Easy Integration in Under 5 Minutes

- 2. Unified Control for Multiple Motors
- 3. Abstraction of Low-Level Functionalities
- 4. Efficient and Optimized Performance

1. Easy Integration in Under 5 Minutes

2. Unified Control for Multiple Motors

- 3. Abstraction of Low-Level Functionalities
- 4. Efficient and Optimized Performance

- 1. Easy Integration in Under 5 Minutes
- 2. Unified Control for Multiple Motors

3. Abstraction of Low-Level Functionalities

4. Efficient and Optimized Performance

- 1. Easy Integration in Under 5 Minutes
- 2. Unified Control for Multiple Motors
- 3. Abstraction of Low-Level Functionalities

4. Efficient and Optimized Performance

5. About this series of tutorials

About this series of tutorials

1. Hello Dynamixel -1: What is a Dynamixel servomotor?



- 2. Hello Dynamixel -2: Basic principles of motor control of D4U.
- 3. Hello Dynamixel -3: Setting and Using various control modes position control mode Torque based position control wheel mode -

and more...