System Readiness (HCO) Exceptions Checklists Readiness | Signoff | Links Reports Help Readiness Choose... All Components {9,657} (64 Masked) Expand All Collapse All ⊟--- 💢 🥜 JLAB Status Key-⊕ X ⊘ CEBAF 👛 Ready ь́-- 💥 🥜 LERF Checked . ★ Cryo X Not Ready া 💢 🧳 Hall A 🖦 💢 🥜 Hall B NA Not Applicable - ¥ < Hall B Beamline Node Key-Category/System . di → . Subsystem ⊕ X ⊘ CLAS12 FT Component ⊕ 👍 🥏 CLAS12 MVT Group □ X < CLAS12 TOF ⊕ X | CLAS12 CTOF ⊕ X ≡ CLAS12 FTOF 1a ⊕ X ≡ CLAS12 FTOF 1b ± K CLAS12 FTOF 2 ⊕ 👍 📜 CLAS12 CND ⊕ 👍 📑 CLAS12 Calorimeter ⊕ 👍 🔚 CLAS12 Gas ⊕ X ≡ CLAS12 LTCC

□ ♣ ☐ CLAS12 RICH
□ ★ ☐ CLAS12 SVT
□ ♣ ♦ Hall B HPS Detector
□ ♣ ♦ Hall B PRad Detector

🖶 👍 📑 Hall B DAQ

⊞ X III B Sweep

🖶 👍 📑 Hall B Beam Transport Monitors